

Technical Service Information Bulletin October 1, 1999

# TILE: TILT/TELESCOPIC STEERING NOISE/ SMOOTHNESS IMPROVEMENT

Models: **'99 LS 400** 

# **Introduction** Production countermeasures have been implemented to reduce noise and improve smoothness of operation of the Tilt/Telescopic Steering Column Assembly.

Problem Description

Information

- 1. Power Tilt/Telescopic Smoothness of Operation.
- escription
- A. Power Tilt/Telescopic Auto Return at engine start.
- B. Auto Return and Auto Away with key placed in ignition cylinder without starting engine.
- C. Power adjust manual operation.
- 2. Squeak noise and/or Vibration (Groan) when operating the Power Telescopic Function.
- 3. Squeak noise and/or Vibration (Groan) when operating the Power Tilt Function.

# Production • 1999 LS 400 vehicles starting with the following VINs:

STARTING VIN	PRODUCTION CHANGE			
JT8BH28F * W0145000	Tilt Motor Set Bolts changed to improve Tilt Motor alignment.			
JT8BH28F * X0166329	Tilt Motor, Telescopic Motor & Tilt Stopper Spring have been changed.			

Parts	PREVIOUS P/N	CURRENT P/N	PARTNAME	QTY
Information	45855–60010	Same	Bolt, Tilt Motor	2
	89231–50041	89231–50042	Motor, Power Tilt	1
	89232–50040	89232–50041	Motor, Power Telescopic	1
	90501–14159	90504–14007	Spring, Stopper, with Damper	1
	90523–06019	Same (Non-reusable Part)	E-Ring, Tilt Motor Shaft Upper	1
	90523-08001	Same (Non-reusable Part)	E-Ring, Tilt Motor Shaft Lower	1
	90389–08124	Same (Non-reusable Part)	Bush, Tilt Steering Support Bolt	2

#### Warranty Information

ty	OP CODE	DESCRIPTION	TIME	OPN	T1	T2
on	ST9006	R & R Tilt Motor, Telescopic Motor & Tilt Stopper Spring	1.1	89231–50040	91	99


## Applicable Warranty\*:

This repair is covered under the Lexus Basic Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



- Required Tools & Materials
- Molybdenum disulfide lithium based grease (P/N 08887–02007, Sta–Lube® – P/N SL3174 or equivalent)
  - Torque wrench with N•m or ft•lbf scale.
  - Torque wrench with N•m or in•lbf scale.
  - Repair 1. Tilt Motor Replacement
- Procedure
- With the ignition key in the "ON" position, record the customer's Radio Presets and press Seat Memory Switch "1".
- b. Disconnect the battery negative terminal.
- c. Disconnect the Tilt Motor Electrical Connector.
- d. Remove the 2 Tilt Motor Set Bolts.
- e. Move the Tilt Motor downward to remove it from the Column Upper Tube Sub–Assembly.
- f. Loosen the Tilt Stopper Support Bolt.
- g. Remove the Upper E–Ring at the end of the Tilt Motor Shaft.
- h. Tilt the Column Upper Tube Sub–Assembly upward and carefully unthread the Tilt Motor from the Tilt Adjust Nut.
- Install a new Lower E–Ring on the new Tilt Motor and lubricate the Tilt Motor Shaft with molybdenum disulfide lithium grease.
- j. Thread the new Tilt Motor into the Tilt Adjust Nut and install a new Upper E–Ring on the end of the Tilt Motor Shaft.
- Install 2 new Tilt Motor
  Bushings in the new Tilt Motor
  Housing and align Column
  Upper Tube Sub–Assembly
  with the Tilt Motor Housing
  bolt holes.
- Carefully insert 2 Tilt Motor Set Bolts into the Tilt Motor. Tighten the Tilt Motor Set Bolts evenly in 2–turn



increments until snug. Torque the Tilt Motor Set Bolts to 20 N•m (210 kgf•cm, 15 ft•lbf).

Repair Procedure (Continued)

- m. Remove the Tilt Support Stopper Bolt and the Stopper Spring.
- n. Carefully install the new Stopper Spring (with plastic insert).

#### HINT:

# Make sure plastic insert does not fall out of new Stopper Spring.

o. Reinstall Support Stopper Bolt. Be careful not to overtighten Support Stopper Bolt.

### 2. Telescopic Motor Replacement

- a. Disconnect the Telescopic Motor Electrical connector.
- Remove the 2 bolts securing the Telescopic Motor to the Column Tube. Remove the Telescopic Motor and Telescopic Cable.
- c. Install the new Telescopic Motor. Torque the 2 Telescopic Motor Bolts to 9 N•m (90 kgf•cm, 78 in•lbf).

### HINT:

Apply a small amount of Molybdenum disulfide lithium based grease to both ends of the Telescopic Cable prior to installation.

- d. Reconnect the Electrical Connector and the negative battery terminal.
- e. Test Steering Column Operation.
- f. Reset the Radio Presets, the Clock and Seat Memory Switch "1".

