

Hesitation on Acceleration and/or P2119

Service

Category Engine/Hybrid System

Section Engine Control Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 - 2012	LS460, LS600H	

SUPERSESSION NOTICE

The information contained in this bulletin supersedes SB No. L-SB-0033-08.

- Part numbers have been updated in the Parts Information table.
- Calibration IDs and ECM part numbers have been updated in the Calibration Information table.

Service Bulletin No. L-SB-0033-08 is Obsolete and any printed versions should be discarded. Be sure to review the entire content of this bulletin before proceeding.

Introduction

Some 2007 – 2012 model year LS 460 and LS 600h vehicles may exhibit a hesitation on acceleration feeling due to inappropriate spark knock or detonation detection, and in some cases set Diagnostic Trouble Code (DTC) P2119 (Throttle Actuator Control Throttle Body Range/Performance). To enhance the smoothness of acceleration, the Engine Control Module/ECM (SAE term: Powertrain Control Module/PCM) calibration has been revised. In some instances, replacement of the cylinder heads may also be required. Use the Repair Procedure in this bulletin to address this condition.

Production Change Information for Cylinder Head Replacement

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
LS 460	2WD JTHBL5EF#C5112283	
L3 400	4WD	JTHCL5EF#C5014570
LS 460L	2WD	JTHGL5EF#C5046385
LS 460L	AMD	JTHDL5EF#C5004680
LS 600h	4WD	JTHDU1EF#C5015340

2 L-SB-0122-17 May 3, 2017 Page 2 of 11

Hesitation on Acceleration and/or P2119

Warranty Information

OP CODE	DESCRIPTION	MODEL	DRIVETRAIN	TIME	OFP	T1	T2
EG8019	Recalibrate ECM (PCM)	I	-	0.4	89661-50A10 89661-50A11 89661-50A12 89661-50C00 89661-50C01 89661-50C03		99
	110011 R & R Cylinder Head (One Side)	LS 460	2WD	17.7	11101-39655 11102-39185	04 50	
110011		LS 460/ LS 460L	4WD	26.2			
		LS 600h	-	28.1			50
		LS 460	2WD	8.2			50
	R & R Cylinder Head (Opposite Side)	LS 460/ LS 460L	4WD	8.4			
		LS 600h	_	8.2			

APPLICABLE WARRANTY

- This repair is covered under the Lexus Powertrain Warranty. This warranty is in effect for 72 months or 70,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

MODEL	PART N	UMBER	PART NAME		
MODEL	PREVIOUS	NEW	PARINAME	QTY	
	11101-39655	11101-39656	Head Sub-assy, Cylinder RH		
	11102-39185	11102-39186	6 Head Sub-assy, Cylinder LH		
	11201-38050	11201-38051	Cover Sub-assy, Cylinder Head RH	1	
	11202-38020	11202-38021	Cover Sub-assy, Cylinder Head LH	1	
ALL	13715-31120 13715-31150 13715-0P010	13715-0P030	Valve, Exhaust	16	
	13711-38030	13711-38031	Valve, Intake	16	
	13734-62020	13734-0P010	Seat, Valve Spring	32	

L-SB-0122-17 May 3, 2017 Page 3 of 11

Hesitation on Acceleration and/or P2119

Parts Information (Continued)

MODEL	PART NUMBER MODEL		PART NAME	
MODEL	PREVIOUS	NEW	TANTROME	
LS 460 (2WD)	89661-50A10 89661-50A11 89661-50A12 89661-50C00 89661-50C01 89661-50C02 89661-50C04 89661-50C90 89661-50C91 89661-50D00 89661-50D01 89661-50D02 89661-50F20 89661-50F21 89661-50J00 89661-50J01 89661-50J01	89661-50C05	Computer, Engine Control (ECM)	_
	04111-38080 04111-38081	04111-38082		1
LS 460 (AWD)	04111-38170 04111-38171	04111-38172 Gasket Kit, Engine Overhau		1
LS 600h	04111-38110	04111-38111		1
ALL	_	00451-00001-LBL	Authorized Modifications Label	1

NOTE

- The ECM (PCM) should NOT be replaced as part of the Repair Procedure.
- Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through *Dealer Daily Parts Dealer Support Materials Orders*.

(2) L-SB-0122-17 May 3, 2017 Page 4 of 11

Hesitation on Acceleration and/or P2119

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*		TS2UNIT	
Techstream Lite	ADE	TSLITEPDLR01	1
Techstream Lite (Green Cable)		TSLP2DLR01	

NOTE

- ONLY ONE of the Techstream units listed above is required.
- Software version 12.00.125 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

REQUIRED TOOLS & MATERIAL	QUANTITY
Toyota Genuine Seal Packing Black, Three Bond 1207B, or Equivalent	As Needed

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	00002-MCGR8	1
Valve Service Tool Set (Valve Spring Compressor)	<u>00002-53464C-02</u> (09202-70020)	1
Starter Armature Bearing Replacer	<u>09201-41020</u>	1
Crankshaft Pulley Holding Tool* (Bolt)	<u>09213-54015-02</u> (90119-08216-01)	1
Companion Flange Holding Tool*	09330-00021	1
Universal Puller Set "C"*	09950-50013-01	1

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

^{*} Essential SST.

Hesitation on Acceleration and/or P2119

Calibration Information (2WD ONLY)

NOTE

Reflash calibration ONLY applies to 2WD vehicles.

MODEL	MODEL YEAR	OPTIONS	CALIBRA	TION ID
MODEL	MODEL YEAR	OFTIONS	PREVIOUS	NEW
	2007 – 2008		35036000 35036100 35036200 35055000 35055100 35055200 35055300 35055400	<u>35055500</u>
	2009		35066000 35066100 35066200	<u>35066300</u>
LS 460/460L	2010 – 2011		35088000 35088100 350B6000 350B6100	350B6200
		Sport Package Brembo Brakes	35088001 35088101 350B6001 350B6101	350B6201
		-	350D2000	350D2100
	2012	Sport Package Brembo Brakes	350D2001	350D2101

L-SB-0122-17 May 3, 2017 Page 6 of 11

Hesitation on Acceleration and/or P2119

Diagnostic Procedure

NOTE

- ONLY complete the Diagnostic Procedure if the cylinder heads were NOT previously replaced per original L-SB-0038-08.
- If cylinder heads were previously replaced, go to the Repair Procedure.
- Connect Techstream unit and test drive the vehicle. Record ALL data duplicating the concern. Review the Knock Correct Learn Value and the Ignition (IGN) Advance.
- If the Knock Correct Learn Value drops from 17.0 CA to below 12.0 CA, and the IGN Advance goes to a negative (–) degree value while duplicating the concern, continue to step 3.
 If the values are comparable to a known good vehicle, the concern may NOT be related to this bulletin diagnose per the Technical Information System (TIS) depending upon symptoms.
- 3. Check the condition of the spark plugs and valve guides.
 - If 1 or more of the spark plugs has a brown residue on the porcelain and electrode, continue to the Repair Procedure.
 - If the spark plugs appear normal, confirm that the valve stem oil clearance is within specification.

Maximum Oil Clearance:

Intake: 0.08 mm (0.0031 in.) Exhaust: 0.1 mm (0.0039 in.)

If greater than specification, continue to the Repair Procedure.

If neither of these conditions are abnormal, the condition may NOT be related to this bulletin. Continue diagnosis using the applicable Repair Manual.

(2) L-SB-0122-17 May 3, 2017 Page 7 of 11

Hesitation on Acceleration and/or P2119

Repair Procedure

NOTE

- For 2007 2012 MY 2WD LS 460 and 2WD LS 460L vehicles ONLY: Begin at step 1.
- For 2009 2012 MY 4WD LS 460, 4WD LS 460L and LS 600h vehicles: Begin at step 4.

	LSB APPLICABILITY				
	I	_S 460	LS 460/600h		
MODEL YEAR		2WD	4WD		
	CYLINDER HEAD REPLACEMENT	REFLASH	CYLINDER HEAD REPLACEMENT	REFLASH	
2007			Not Applicable		
2008			Not Applicable		
2009	Applicable*	Applicable		Not Applicable	
2010		Applicable	Applicable*	Not Applicable	
2011					
2012	Applicable**		Applicable**		

^{*}ONLY applicable if cylinder heads were NOT previously replaced per original L-SB-0033-08.

^{**}Verify VIN breaks to confirm applicability.


(L) L-SB-0122-17 May 3, 2017 Page 8 of 11

Hesitation on Acceleration and/or P2119

Repair Procedure (Continued)

1. Check for the Authorized Modifications Label affixed to the vehicle in the location shown. Confirm if the ECM (PCM) calibration has been updated.

Figure 1. Location of Authorized Modifications Label on 2007 - 2012 LS 460



1	Replacement ECM (PCM) Part Number (i.e., 89661-50C04)
2	New Calibration ID (i.e., 35055200)
3	Dealer Code

4	Date Completed
5	This SB Number

L-SB-0122-17 May 3, 2017 Page 9 of 11

Hesitation on Acceleration and/or P2119

Repair Procedure (Continued)

2. Flash reprogram the ECM (PCM).

NOTE

- The GR8 Battery Diagnostic Station MUST be used in Power Supply Mode to maintain battery voltage at 13.5V while flash reprogramming the vehicle.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the GR8 Instruction Manual located on the Technical Information System (TIS), Diagnostics – Tools & Equipment – Battery Diagnostics.
- 3. Prepare and install the Authorized Modifications Label.
 - A. Using a permanent marker, enter the following information on the label:
 - ECM part number [Refer to the Parts Information section for the CURRENT PART NUMBER]
 - Calibration ID(s) [Refer to the Calibration Identification Chart for the NEW CALIBRATION ID]
 - Dealer Code
 - Repair Date
 - Change Authority [This bulletin number]
 - B. Install the Authorized Modifications Label to the vehicle at the location shown in Figure 1. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.

NOTE

If the cylinder heads were previously replaced in L-SB-0033-08, do NOT replace them again.

4. Replace both valve cover assemblies, both cylinder heads and ALL intake and exhaust valves for the left and right cylinder banks.

Refer to TIS, applicable model and model year Repair Manual:

2007 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket Disassembly / Reassembly"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

• 2008 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

L-SB-0122-17 May 3, 2017 Page 10 of 11

Hesitation on Acceleration and/or P2119

Repair Procedure (Continued)

• 2008 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

• 2009 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

2010 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

2011 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

• 2012 LS 460:

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

Engine/Hybrid System – Engine Mechanical – "1UR-FSE Engine Mechanical: Cylinder Head Gasket <u>(for Bank 1)</u> / <u>(for Bank 2)</u>: Installation"

• 2008 LS 600h:

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket <u>Disassembly</u> / <u>Reassembly</u>"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

(2) L-SB-0122-17 May 3, 2017 Page 11 of 11

Hesitation on Acceleration and/or P2119

Repair Procedure (Continued)

• 2009 LS 600h:

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket Disassembly / Reassembly"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

2010 LS 600h:

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket Disassembly / Reassembly"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

• 2011 LS 600h:

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Removal"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket Disassembly / Reassembly"

Engine/Hybrid System – Engine Mechanical – "2UR-FSE Engine Mechanical: Cylinder Head Gasket (for Bank 1) / (for Bank 2): Installation"

- 5. Reconnect the negative (-) battery terminal.
- 6. Reinitialize ANY affected power systems.

Refer to TIS, applicable Service Bulletin or Repair Manual:

- 2007 LS 460: Service Bulletin <u>PD007-07</u>, "Power System Initialization During PDS"
- 2008 LS 460/600h: Service Bulletin <u>L-SB-0041-08</u>, "Power System Initialization During PDS"
- 2009 / 2010 / 2011 / 2012 LS 460:
 General Introduction "Introduction: Repair Instruction: Initialization"
- 2009 / 2010 / 2011 / 2012 LS 600h:
 General Introduction "Introduction: Repair Instruction: Initialization"
- 7. Test drive the vehicle to confirm hesitation on acceleration and/or P2119 is no longer present.