



**Technical Service
Information Bulletin**

June 8, 2007

Title:

INNER REAR VIEW MIRROR VIBRATION

Models:

'06 – '07 IS 250/350

NVH
NV006-07

Introduction Some 2006 and 2007 model year IS 250/350 vehicle customers may complain of a vibration from the inner rear view mirror while driving, most noticeably with the moon roof open. A new mirror assembly is available to improve this condition.

Applicable Vehicles

- **2006 – 2007** model year **IS 250/350** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

**Production
Change
Information**

MODEL	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
IS 250	Tahara	JTHBK262275039594
		JTHCK262375012263
	TMK	JTHBK262172043430
		JTHCK262672015465
IS 350	Tahara	JTHBE262575015328
	TMK	JTHBE262272010380

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
87810-53120	Same	Mirror Assembly, Inner Rear View	1

**Repair
Procedure**

Remove and replace the inner rear view mirror assembly.
Refer to the Technical Information System (TIS), 2006 or 2007 model year IS 250 or IS 350 Repair Manual:

- *Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”.*
- *Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”.*

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
752021	R & R Inner Rear View Mirror	0.2	87810-#####	62	43

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

