

Technical Service Information Bulletin

October 12, 2001

Title:

MARK LEVINSON AMPLIFIER IMPROVEMENTS

Models:

'01 GS 430/300, LS 430, LX 470 & '02 SC 430



Some owners of vehicles equipped with the Mark Levinson sound system may experience one of the following conditions:

- No sound from the audio system.
- · Audio system goes to maximum volume by itself.
- Tone controls are inoperative or show strange characters.

To remedy these conditions, improvements have been made to the Mark Levinson amplifier.

Applicable Vehicles

- 2001 model year GS 300, GS 430, LS 430 and LX 470 vehicles equipped with the Mark Levinson sound system.
- 2002 model year SC 430 vehicles equipped with the Mark Levinson sound system.

Production Change Information

MODEL YEAR	MODEL	STARTING VIN	
2001	GS 300	JT8BD69S#10008286	
	GS 430	JT8BL69S#10150556	
	LS 430	JTHBN30F#10050752	
	LX 470	JTJHT00W#13512295	
2002	SC 430	JTHFN48Y#20011879	

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
	0.4 86280	0.5	86280-0W030		
000004		86280-0W040	95	_,	
860601	R & R Amplifier Assy, Stereo Component	pplifier Assy, Stereo Component 0.3 86280–0W050		71	
		0.5	86280-0W070		

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

^{*} Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Parts Information

MODEL	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
GS 300, GS 430	86280-0W030		Amplifier Assy, Stereo	1
LS 430	86280-0W040	Same Amplifier Assy, Stereo Component		1
LX 470	86280-0W050		1	
SC 430	86280-0W070			1

Repair Procedure

Order a replacement amplifier from Mark Levinson through the exchange program by calling 1–800–456–4265. Please refer to the service manual for details on the installation method.

Parts Identification

The **model numbers** of the improved parts are **74##** and higher.

