

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	09/05/2012		81768	0484428	FULL SYNTHETIC OIL CHANGE - COMPLETE DEALER RECOMMENDED SERVICE
Dealer Reported	09/05/2012		81768	0484428	PERFORMED WORLD CLASS INSPECTION E - PERFORMED INSPECTION
Dealer Reported	03/04/2008	<u>Park Place Lexus Grapevine</u>	44090	0818076	REPAINTED REAR BUMPER AND REFINISHED BUMPER BLEND PAINT - COMPLETE BUMPER..REAR BUMPER ONLY SEE ME BEFORE STARTING ON REPAIRS - 44090 DAMAGE TO REAR BUMPER RPAINT3 800 REPAIR REAR BUMPER & REFNISH
Dealer Reported	03/04/2008	<u>Park Place Lexus Grapevine</u>	44090	0818076	FULL DETAIL (SEDAN/COUPE) - 44090 FULL DETAIL 340
Dealer Reported	04/03/2007	<u>Park Place Lexus Grapevine</u>	31872	0773129	FOUR WHEEL ALIGNMENT - 31872 TH=1.8 COMPLETED 4 WHEEL ALIGNMENT NOTE: LEFT FRONT LOWER ARM (#2) IS BENT AND CAUSING CASTER TO BE BELOW SPEC. LEFT

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					REAR SHOCK IS NOT DAMPENING PROPERLY. THE VEHICLE HAS AN UNSTABLE FEEL WHEN DRIVEN OVER IRREGULAR ROAD SURFACES RECOMMEND NEW LEFT F
Dealer Reported	04/03/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	31872	0773129	
Dealer Reported	04/03/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	31872	0773129	SIDE MARKER LIGHT BULB 1SD - PLEASE CHECK THERE IS A BULB OUT (SEE HISTORY) LEFT FRONT - BULB BURNED OUT PARTS WARRANTY REPLACE BULB - 31868 LEFT FRONT BULB BURNED OUT 810281=0.2,T172,T2=71 TH=0.2 REPLACED LEFT FRONT BULB
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	SHOCKS IN TRUNK PLEASE CHECK THE REAR TRUNK WILL NOT STAY UP PLEASE PUT PARTS IN TRUNK CLIENT WILL INSTALL HIMSELF F - 29812 TH=0 PLACED TRUNK SHOCKS IN TRUNK

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	SHOCKS IN TRUNK NEEDS 30K SERVICE FLUIDS DIRTY , REC TWO FRONT TIRES AND ALIGNMENT
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	REPLACE BULB LEFT FRONT SIDE MARKER BULB IS INOP - 29812 TH=0.3 REPLACED LEFT FRONT SIDE MARKER BULB
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	REPLACE BULB PLEASE REPALCE THE RIGHT REAR SIDEMARKER - 29812 TH=0.3 REPLACED RIGHT REAR SIDEMARKET BULB
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	
Dealer Reported	03/05/2007	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	29812	0769509	* NO WASH IN HURRY
Dealer Reported	09/20/2006	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	25364	0749154	ADD NAVIGATION UPDATE DVD NAV UPDATE - 25364 DVD UPDATE TH= .5 PERFORMED DVD NAVIGATION UPDATE.
Dealer Reported	09/20/2006	<u>Park Place</u> <u>Lexus</u> <u>Grapevine</u>	25364	0749154	REPLACE PASSENGER SIDE TAIL LIGHT , CHECK LIGHTS, ALL WORK AS DESIGNED PASSENGER SIDE

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					TAIL LIGHT BULB GOING IN OUT - 25364 TAILLIGHT GOING OUT TH= .4 REPLACED PASSENGER'S SIDE TAILLIGHT BULB. CHECKED LIGHTS, ALL WORK AS DESIGNED
Dealer Reported	09/20/2006	Park Place Lexus Grapevine	25364	0749154	* DRIVER SIDE DOME IN CAR GOING IN AND OUT - F - 25364 LIGHT GOING IN AND OUT T1=87,T2=41, OP#812021= 0.0 TH= 0.0 REPLACED DRIVER'S SIDE DOME LIGHT, WAS BEGINNING TO BURN OUT NO CHARGE
Dealer Reported	08/17/2006	South Bay Lexus	24295	0260990	SFI.MFI CUSTOMER STATES:CHECK ENGINE IDLES ROUGH - COULD NOT DUPLICATE ROUGH IDLE.
Dealer Reported	08/17/2006	South Bay Lexus	24295	0260990	FRONT AXLE CUSTOMER STATES:WHEN BRAKING CAN HEAR A CLUNKING NOISE IN FRONT END,ADVISE - COULD NOT DUPLICATE CLUNKING NOISE.

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	08/17/2006	South Bay Lexus	24295	0260990	25000 MILE SERVICE NON WARRANTYNON OEM - OIL/FILTER SERVICE. - CHANGE OIL AND FILTER; CHECK FLUIDS, BELTS, HOSES, AND BRAKES. - REAR BRAKE LINING MEASUREMENTS: 5 MMS. TIRE TREAD DEPTHS: 10/32"".
Dealer Reported	08/17/2006	South Bay Lexus	24295	0260990	473991 FRT BRK PADS FRT BRK PADS W/ KIT - FRONT BRAKE LININGS WORN DOWN TO 1 MM. - REPLACED FRONT BRAKE PADS AND SHIMS, AND MACHINED FRONT BRAKE ROTORS.
Dealer Reported	12/15/2005	South Bay Lexus	20217	0245636	20000 MILE SERVICE NON WARRANTYNON OEM - OIL/FILTER SERVICE. - CHANGE OIL AND FILTER; CHECK FLUIDS, BELTS, HOSES, AND BRAKES. - 20000 MILE SERVICE PERFORMED BRAKE LININGS: FRONT FAIR, REAR GOOD.
Dealer Reported	12/15/2005	South Bay Lexus	20217	0245636	OTHER NONOEM ACCESSORY INSTALL/R&R - DID

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					NOT BALANCE NOR ROTATE TIRES - RECOMMEND REPLACEMENT OF 4 TIRES.
Dealer Reported	12/15/2005	South Bay Lexus	20217	0245636	FRONT AXLE CUSTOMER DROVE OVER SOME DEBRIS CHECK/PERFORM 4 WHEEL ALIGNMENT IF NEEDED ALSO CHECK FOR OTHER DAMAGE.
Dealer Reported	05/19/2005	South Bay Lexus	16553	0233639	120991 ENGINE CHECK ENGINE LIGHT , VSC AND TRAC OFF LIGHT ON AT DASH - DIAGNOSTIC TROUBLE CODE P0133. - REPLACED OXYGEN SENSOR(BANK 2 SENSOR 1).
Dealer Reported	05/19/2005	South Bay Lexus	16553	0233639	
Dealer Reported	05/19/2005	South Bay Lexus	16553	0233639	
Dealer Reported	11/11/2004	South Bay Lexus	14671	0223110	FRONT/REAR BODY RUBBER BUMPER FOR ROOF COMING OFF. PART ORDERED BY 1187 - SPECIAL ORDER PART
Dealer Reported	11/11/2004	South Bay Lexus	14671	0223110	FRONT/REAR BODY CUST SAYS WEATHER STRIP IN TRUNK IS COMING OFF.

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					ORDERED BY - LOSS OF BONDING - REPLACED TRUNK FRONT WEATHERSTRIP
Dealer Reported	10/30/2004	South Bay Lexus	14406	0222532	15000 MILE SERVICE NON WARRANTY CUSTOMER REQUESTS 15000 MILE SERVICE CHANGE OIL AND FILTER; CHECK FLUIDS, BELTS, HOSES, AND BRAKES; BALANCE AND ROTATE TIRES; ADJUST PARING BRAKE; REPLACE AIR FILTER. - 15000 MILE SERVICE PERFORMED TIRE TREAD DEPTHS: FAIR. BRAKE LININGS: GOOD.
Dealer Reported	10/30/2004	South Bay Lexus	14406	0222532	FRONT/REAR BODY CK TRUNK LID WEATHERSTRIP LOOSE - ORDERED WEATHERSTRIP(PART NO. 64463 - 24020).
Dealer Reported	10/30/2004	South Bay Lexus	14406	0222532	FRONT/REAR BODY CK RUBBER BUMPER CAME OFF FROM RIGHT FRONT ROOF AREA - PLEASE

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					REPLACE - RE - ATTACHED RUBBER BUMPER.
Dealer Reported	10/30/2004	<u>South Bay Lexus</u>	14406	0222532	FRONT/REAR BODY CK HEAR A RATTLE FROM FRONT END ON ROUGH ROADS - UNABLE TO DUPLICATE CONDITION; NEED MORE TIME FOR DIAGNOSIS.
Dealer Reported	03/26/2004	<u>South Bay Lexus</u>	10967	0210137	10000 MILE SERVICE NON WARRANTYNON OEM - CUSTOMER REQUESTS 10000 MILE SERVICE CHANGE OIL AND FILTER; CHECK FLUIDS, BELTS, HOSES, AND BRAKES. - 10000 MILE SERVICE PERFORMED TIRE TREAD DEPTHS: GOOD. BRAKE LININGS: GOOD.
Dealer Reported	03/26/2004	<u>South Bay Lexus</u>	10967	0210137	FRONT/REAR BODY CK TRUNK LID WEATHERSTRIP TORN - ORDERED LUGGAGE COMPARTMENT DOOR WEATHERSTRIP.
Dealer Reported	04/28/2003	<u>South Bay Lexus</u>	5830	0149905	5,000 MILE SERVICE CHANGE OIL AND FILTER; ROTATE TIRES, TOP OFF ALL FLUIDS, CHECK

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					BELTS, HOSES AND BRAKES. BRAKES: FRONT AND REAR GOOD TIRES: FRONT AND REAR GOOD
Dealer Reported	01/30/2003	<u>South Bay</u> <u>Lexus</u>	855	0145534	