

# **Automatic Transmission Replacement Precautions**

Service

Category Drivetrain

Section Automatic Transmission/Transaxle

Market USA



### **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
1990 – 2011	ES250, ES300, ES330,		
	ES350, GS300,		
	GS350, GS400,		
	GS430, GS460,		
	GX460, GX470, IS F,		
	IS250, IS250C, IS300,		
	IS350, IS350C, LS400,		
	LS430, LS460, LX450,		
	LX470, LX570, RX300,		
	RX330, RX350,		
	SC300, SC400, SC430		

#### Introduction

The purpose of this TSIB is to provide precautions to follow when installing an automatic transmission/transaxle assembly to avoid MIL "ON," shifting issues, and/or transmission damage. Use the information in this bulletin when installing an automatic transmission/transaxle assembly.

### **Warranty Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	1	ı	-	_

**L-SB-0041-11** July 13, 2011 Page 2 of 2

## **Automatic Transmission Replacement Precautions**

Precautions				
Confirm the following items:				
	Both alignment pins are present on the engine block.			
	ATF lines and cooler have been flushed with the appropriate ATF type.			
	Correct torque converter bolts and washers are used.			
	NOTE  Not all applications will use washers on the torque converter bolts.			
	All ground straps are in the correct locations and are connected properly.			
	Correct shift cable adjustment.			
	Correct park neutral position switch adjustment.			
	Transmission fluid level has been set properly.			
	Transmission learned values have been reset and/or the compensation code has been input (if applicable) and proper initialization has been performed.			