

# Front Door Wind Noise

**Service Category** Vehicle Exterior

**Section** Exterior Panels/Trim

**Market** USA

Lexus Supports  
ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 – 2008	ES350	WMI(s): JTH

### TSB REVISION NOTICE

October 15, 2008 Rev1:

- The parts section has been updated.

Any previous printed versions of this service bulletin should be discarded.

## Introduction

Some 2007-2008 model year ES 350 customers may complain of a wind noise from the front side window area when driving at speeds greater than 40 mph. Perform the inspection procedure to verify the wind noise is heard from the front lower corner of the door window and use the following repair procedure to improve this condition.

### NOTE

It is important to note that this TSIB addresses unusual interior noises caused by slight variations in certain parts and by carefully following the instructions in this TSIB, these noises can be improved. Your customers must be aware that some level of wind turbulence noise, especially in cross wind conditions, is present in all vehicles.

## Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
BO8008	Front Door outside Moldings Replacement (Both Sides)	1.4	75072-33060	59	43

### APPLICABLE WARRANTY

- This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to correction of a problem based upon a customer's specific complaint.

## Front Door Wind Noise

### Production Change Information

This TSB applies to vehicles produced **BEFORE** the Production Change Effective VIN shown below.

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
ES 350	JTHBJ46G#82183272

### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
67495-33020	Same	Cover, Front Door Front Lower Frame, Upper RH	1
67496-33010	Same	Cover, Front Door Front Lower Frame, Upper LH	1
75071-33060	Same	Molding Sub-assy, Front Door, Outside RH	1
75072-33060	Same	Molding Sub-assy, Front Door, Outside LH	1
90269-A0006	Same	Rivet	16
75755-33020	Same	Molding, Front Door Window Frame, Rear RH	1
75756-33020	Same	Molding, Front Door Window Frame, Rear LH	1

### Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST'S)	PART NUMBER	QTY
Plastic Pry Tool Set*	<a href="#">00002-06000-01</a>	1

\* Essential SST.

**NOTE**

Additional SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

REQUIRED EQUIPMENT	QTY
Riveter	1
Drill	1
4 mm ( 5/32 in.) Drill Bit	1