

Last Modified: 7-13-2007		1.7 T
Service Category: Vehicle Interior	Section: Interior Panels/Trim	
Model Year: 2008	Model: ES350	Doc ID: RM000000WT400RX
Title: INTERIOR: REAR SUNSHADE SYSTEM: PROBLEM SYMPTOMS TABLE (2008 ES350)		

## PROBLEM SYMPTOMS TABLE

### HINT:

Use the table below to help determine the cause of the problem symptoms. The potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.

### Rear sunshade system

SYMPTOM	SUSPECTED AREA	SEE PAGE
Rear sunshade does not operate by manual operation	Rear sunshade switch	<a href="#">INFO</a>
	Fuse (GAUGE NO. 1)	<a href="#">INFO</a>
	Wire harness	<a href="#">INFO</a>
	Rear sunshade relay	<a href="#">INFO</a>
Rear sunshade shift-linked function does not operate when shift lever is moved to R position	CAN communication line	<a href="#">INFO</a>
	Park/Neutral position switch	<a href="#">INFO</a>
	Rear sunshade relay	<a href="#">INFO</a>
	Wire harness	<a href="#">INFO</a>

