

Last Modified: 7-13-2007		1.6 A
Service Category: Vehicle Exterior	Section: Lighting (ext)	
Model Year: 2008	Model: ES350	Doc ID: RM000002G1M002X
Title: LIGHTING: HAZARD WARNING SWITCH: REMOVAL (2008 ES350)		

REMOVAL

1. REMOVE SHIFT LEVER KNOB SUB-ASSEMBLY [INFO](#)
2. REMOVE NO. 2 INSTRUMENT PANEL REGISTER ASSEMBLY [INFO](#)
3. REMOVE UPPER CONSOLE PANEL ASSEMBLY WITH FRONT ASH RECEPTACLE [INFO](#)
4. REMOVE INSTRUMENT PANEL FINISH PANEL END LH [INFO](#)
5. REMOVE INSTRUMENT PANEL FINISH PANEL END RH [INFO](#)
6. REMOVE INTEGRATION CONTROL PANEL WITH RADIO RECEIVER ASSEMBLY (w/o Navigation System) [INFO](#)
7. REMOVE NO. 1 RADIO BRACKET (w/o Navigation System) [INFO](#)
8. REMOVE NO. 2 RADIO BRACKET (w/o Navigation System) [INFO](#)
9. REMOVE RADIO RECEIVER ASSEMBLY (w/o Navigation System) [INFO](#)
10. REMOVE HEATER CONTROL HOUSING SUB-ASSEMBLY (w/o Navigation System) [INFO](#)
11. REMOVE CENTER CLUSTER MODULE CONTROL ASSEMBLY (w/o Navigation System) [INFO](#)
12. REMOVE MULTI-DISPLAY WITH RADIO RECEIVER ASSEMBLY (w/ Navigation System) [INFO](#)
13. REMOVE NO. 1 RADIO BRACKET (w/ Navigation System) [INFO](#)
14. REMOVE NO. 2 RADIO BRACKET (w/ Navigation System) [INFO](#)
15. REMOVE MULTI-DISPLAY ASSEMBLY (w/ Navigation System) [INFO](#)

