

Last Modified: 7-13-2007		1.6 S
Service Category: Vehicle Exterior		Section: Sliding Roof/Convertible
Model Year: 2008	Model: ES350	Doc ID: RM000002BFQ00JX
Title: SLIDING ROOF: SLIDING ROOF SYSTEM: DIAGNOSTIC TROUBLE CODE CHART (2008 ES350)		

DIAGNOSTIC TROUBLE CODE CHART

If any trouble code is displayed during DTC check, check the circuit corresponding to the code in the table below. Proceed to the page given for the circuit.

Sliding Roof System

DTC CODE	DETECTION ITEM	TROUBLE AREA	SEE PAGE
B2341	Sensor (Motor) Failure	<ol style="list-style-type: none"> 1. Sliding roof drive gear sub-assembly (Sliding roof control ECU) 2. Roof console box assembly (Sliding roof control switch) 3. Wire harness 	INFO
B2342	Switch Failure	<ol style="list-style-type: none"> 1. Sliding roof drive gear sub-assembly (Sliding roof control ECU) 2. Roof console box assembly (Sliding roof control switch) 3. Wire harness 	INFO
B2343	Position Initialization Incomplete	<ol style="list-style-type: none"> 1. Sliding roof drive gear sub-assembly (Sliding roof control ECU) 2. Roof console box assembly (Sliding roof control switch) 3. Wire harness 	INFO
B2344	Position Failure	<ol style="list-style-type: none"> 1. Sliding roof drive gear sub-assembly (Sliding roof control ECU) 2. Roof console box assembly (Sliding roof control switch) 3. Wire harness 	INFO

