

Last Modified: 7-13-2007		1.7 A
Service Category: Vehicle Interior	Section: Supplemental Restraint Systems	
Model Year: 2008	Model: ES350	Doc ID: RM000000V2W00FX
Title: SUPPLEMENTAL RESTRAINT SYSTEM: FRONT PASSENGER SIDE KNEE AIRBAG ASSEMBLY: REMOVAL (2008 ES350)		

REMOVAL

1. PRECAUTION

CAUTION:

Be sure to read "PRECAUTION" thoroughly before servicing  .

2. DISCONNECT CABLE FROM NEGATIVE BATTERY TERMINAL

NOTICE:

Wait for 90 seconds after disconnecting the cable to prevent the airbag deployment.

3. REMOVE FRONT DOOR SCUFF PLATE RH


4. REMOVE FRONT DOOR OPENING TRIM COVER RH

5. REMOVE SIDE INSTRUMENT PANEL RH

6. REMOVE INSTRUMENT PANEL FINISH PANEL END RH


7. REMOVE NO. 2 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY

8. REMOVE FRONT PASSENGER SIDE KNEE AIRBAG ASSEMBLY



(a) Remove the 3 bolts.

(b) Disconnect the front passenger side knee airbag connector.



(c) Disengage the 2 claws and 2 pins, and remove the front passenger side knee airbag assembly.

NOTICE:

When handling the airbag connector, take care not to damage the airbag wire harness.

