

Last Modified: 7-13-2007		1.6 T
Service Category: Vehicle Exterior	Section: Wiper/Washer	
Model Year: 2008	Model: ES350	Doc ID: RM000000PJ701EX
Title: WIPER AND WASHER: WIPER AND WASHER SYSTEM (w/o Rain Sensor): PROBLEM SYMPTOMS TABLE (2008 ES350)		

PROBLEM SYMPTOMS TABLE

Front Wiper and Washer System:

SYMPTOM	SUSPECTED AREA	SEE PAGE
Front wiper system does not operate.	1. IG1 relay	-
	2. WIP fuse	-
	3. Windshield wiper switch assembly	INFO
	4. Windshield wiper motor assembly	INFO
	5. Wire harness or connector	-
Front wipers do not operate in LO or HI.	1. Windshield wiper switch assembly	INFO
	2. Windshield wiper motor assembly	INFO
	3. Wire harness or connector	-
Front wipers do not operate in INT.	1. Windshield wiper switch assembly	INFO
	2. Windshield wiper motor assembly	INFO
	3. Wire harness or connector	-
Front washer motor does not operate.	1. WASH fuse	-
	2. Windshield wiper switch assembly	INFO
	3. Windshield washer motor assembly	INFO
	4. Wire harness or connector	-
Front wipers do not operate when the front washer switch is ON.	1. Windshield wiper switch assembly	INFO
	2. Windshield wiper motor assembly	INFO
	3. Wire harness or connector	-
Washer fluid does not operate.	Washer hose and nozzle	INFO
When the front wiper switch is in the HI position, the wiper blade is in contact with the body.	1. Front wiper arm installation position	INFO
	2. Windshield wiper motor	INFO

	assembly	
When the front wiper switch is OFF, the wiper blade does not retract or retracts in a wrong position.	1. Front wiper arm installation position	INFO
	2. Windshield wiper motor assembly	INFO

Others:

SYMPTOM	SUSPECTED AREA	SEE PAGE
Washer fluid level warning system does not operate.	1. Washer fluid level warning switch	INFO
	2. Combination meter assembly	-

