



**Technical Service  
Information Bulletin**


August 25, 2007

Title:

**ISC LEARNING PROCEDURE**

Models:

'08 RX 400h



**ENGINE  
EG021-07**

**Introduction** When the 12-volt battery is disconnected or is depleted below 7 volts on 2008 model year RX 400h vehicles, it is necessary to perform the ISC Learning procedure to re-initialize the idle speed control. The information in this TSIB relates to this procedure.

- Applicable Vehicles**
- 2008 model year RX 400h vehicles.

**Required Tools & Equipment**

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
TIS Techstream* NOTE: Software version 2.11.004 or later is required.	ADE	TSPKG1	1



**NOTE:**  
Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

**Warranty Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

