Repair Estimate

M: (2007 LE GS 350 1THP C96367588 1882 RO #276769

130,294 miles Service Advisor

Chris Hodges chodges@lexusofmerrillville.com

Lexus of Merrillville

[Primary]: 08LEZ100 : *ENGINE DIAGNOSIS	and the second s	144,95
Diagnostic - Check Engine Light: As Per Che vehicle in need of a New Hybrid Battery Pac Battery, Adjusting HVAC, and Reflashing the	ck. Recommend Replacing Hybrid	5590.79
	E IIV LCU	
Printed on 04/23/2015 12:26 PM	Subtotal	5735.74
		5735.74 24.98
Printed on 04/23/2015 12:26 PM	Subtotal	

In the process of inspecting your vehicle for safety and reliability, your technician **Kyle H** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Red: requires immediate attention.

Yellow: in need of attention soon.

Diagnostic - Check Engine Light: As Per Check Engine Light Diagnostic, Found vehicle in need of a New Hybrid Battery Pack. Recommend Replacing Hybrid Battery, Adjusting HVAC, and Reflashing the HV ECU

Item Description

When the vehicle's computer senses that there is a problem with some of the components it stores, the corresponding trouble code(s) in its memory light up the "Check Engine" or "Service Engine Soon" light, to tell you that there is a problem and your car needs to be looked at.

Reason

If not serviced when needed a small simple problem can turn in to a large hazardous issue.

