



L-SB-0167-08

December 11, 2008

SRS Light "ON" - DTC B1861

Service Category Vehicle Interior

Section Supplemental Restraint Systems

Market USA

Lexus Supports ASE Certification



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2006 - 2008	IS250, IS350	

Introduction

Some 2006-2008 MY IS250/350 vehicles may exhibit a SRS Light "On" condition with DTG B1861. Use the following information to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL8054	R&R Instrument Panel Wire Harness	4.5	82141-53###	8B	71

APPLICABLE WARRANTY

- This repair is covered under the Lexus Restraint System Warranty. This warranty is in effect for 72 months or 70,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
82141-53###	Same	Wire, Instrument Panel	1

NOTE

A80K-4K

Please see the Parts Identification Method section of this TSIB to determine the correct wire harness part number.