

SERVICE HISTORY

2006 IS350

Edit

Service History for VIN: JTHBE262665001548

Sort By:

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	REPLACED REAR BRAKE PADS,SHIMS,AND RESURFACED ROTORS REPLACE REAR BRAKE PADS (INCLUDES MACHINE ROTORS) - 64080 200 REPLACE REAR BRAKE PADS AND MACHINE ROTORS
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	REPLACED LEFT REAR BRAKE CALIPER *REPLACE LEFT REAR BRAKE CALIPER - 64080 100 REPLACE LEFT REAR BRAKE CALIPER WITH REAR BRAKE SERVICE
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	MOUNT AND BALANCE (4) TIRES. HANKOOK VENTUS V12 EVO 235 35 19 FRONT, 275 30 19 R - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	FOUR WHEEL ALIGNMENT - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	REPLACE A/C CABIN FILTER - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	REPLACE BRAKE FLUID - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	REPLACE SPARK PLUGSSIX CYLINDERENGINES - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	SERVICE DIFFERENTIAL - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	FUEL INDUCTION SERVICE - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	INSTALL NAVIGATION SYSTEM UPDATE - CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	9LG REPL PEDAL PAD, REFLASH, AWFM IS MODELS ONLY - *INSPECT FOR 9LG - 9LG - 64077 9915M5 120 PERFORM 9LG SSC
Dealer Reported	10/30/2012	Park Place Lexus of Grapevine	64080	1061817	R. DSC BRK CALIPER ASSY 1SD - GOODWILL BRAKE CALIPER PART ONLY - PER ROD M - SLIDE PIN IS SEIZED REPLACED CALIPER - 64080 473201 T1=99 T2=83 FP#47850 - 22221
Dealer Reported	04/11/2012	Lexus of New Orleans	56313	0189459	NON WARRANTABLE OPERATION CODE LOANER - (LOANER)
Dealer Reported	04/11/2012	Lexus of New Orleans	56313	0189459	DO NOT WASH VEHICLE - (NO WASH)
Dealer Reported	04/11/2012	Lexus of New Orleans	56313	0189459	SSC 9LG DECLINED RECOMMENDED SERVICES DECLINED BY CUSTOMER: (PRICES SUBJECT TO CHANGE) - 9LG RECALL PENDING - CUSTOMER DECLINED RECALL

Dealer Reported	04/11/2012	Lexus of New Orleans	56313	0189459	OTHER DIAG/REPAIR C/S: EXHAUST LEAK IN CATALYTIC CONVERTER AREA. PLEASE ADVISE EXTENDED WARRANTY VEHICLE - FRONT PIPE IS CORRODED/RUSTED AND CREATED AN EXHAUST LEAK. - REPLACED FRONT PIPE EXHAUST 170151B 0.3 T1 - 64 T2 - 17
Dealer Reported	04/11/2012	Lexus of New Orleans	56313	0189459	
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	ADDITIONAL COMMENTS C/S: CUSTOMER REQUEST SUV LOANER. -
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	NON WARRANTABLE OPERATION CODE LOANER - (LOANER)
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	DO NOT WASH VEHICLE - (NO WASH)
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	NOTES CUSTOMER HAS LEXUS WARRANTY - OK
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	ACCESSORIES C/S: REAR PARKING SENSOR ON THE DRIVER SIDE GOES OFF BY ITSELF. - SHORT CIRCUIT AT TIMES. - REPLACED LEFT REAR PARKING SENSOR 520991 LABOR 1.5 T1 - 87 T2 - 73 PARTS 1030.09 LABOR 176.80 TAX 105.60 RENTAL 100.00 TOTAL 1412.49 VSA 2HT 3348
Dealer Reported	08/25/2011	Lexus of New Orleans	48309	0174519	EXTERIOR C/S: REAR VIEW MIRROR HAS TWO SMUDGES ON THE BACK OF THE CASING. - L - SB - 0186 - 09 REAR VIEW MIRROR POOR APPEARANCE - REPLACED REAR VIEW MIRROR ASSEMBLY INNER 752021 LABOR 0.2 T1 - 67 T2 - 63
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	SSC 9LG DECLINED POTENTIAL FLOOR MAT INTERFERENCE WITH ACCELERATOR PEDAL 2006 - CERTAIN 2010 IS VEHICLES - REPLACED ACCELERATOR PEDAL FOOT PAD WITH A NEWLY DESIGNED ONE. IF EQUIPPED, INSPECTED LEXUS ALL WEATHER FLOOR MATS (AWFM). IF AWFMS WERE OF AN OLDER DESIGN, BOTH FRONT AWFMS WERE REPLACED WITH NEWLY DESIGNED ONES. INSPECTED DRIVER'S CARPET AND CLEANED IF
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	ADD FUEL - THE FOLLOWING AMOUNT OF FUEL WAS ADDED TO THIS VEHICLE: - COMPLETED 8.5 GAL
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	NON WARRANTABLE OPERATION CODE LOANER - (LOANER)
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	DO NOT WASH VEHICLE - (NO WASH)
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	NOTES UNDER NO CERTAIN TERMS PERFORM 9LG - NO WORK PERFORMED
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	CONTACT INFORMATION CONTACT INFORMATION MR. 504 - 717 - 6479 - CONTACT INFORMATION PMT 4PM ON 2/26/11 NOTIFIED CUSTOMER THAT CAR WAS COMPLETE ON 2/26/11 AT 12NOON BY CELLPHONE NUMBER PROVIDED
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	SAFETY RECALL ALE SAFETY RECALL ALE VALVE SPRING CERTAIN 2006 - 2008 IS350, 2007 - 2008 GS350 & GS450H, 2008 GS460, 2007 - 2008 LS460 & LS460L, 2008 LS600HL VEHICLES - INSTALLED NEWLY DESIGNED VALVE SPRINGS. 0528FS 7.0
Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	SAFETY RECALL ALG SAFETY RECALL ALG RUBBER SEAL (BRAKE MASTER CYLINDER CUP) REPLACEMENT - REPLACED THE RUBBER SEAL (BRAKE MASTER CYLINDER CUP) WITH A NEWLY DESIGNED ONE AT NO CHARGE. IF BRAKE FLUID LEAKAGE HAS DAMAGED THE BRAKE BOOSTER IT WAS ALSO REPLACED AT NO CHARGE. 0516K1 1.9
					SAFETY RECALL BLA SAFETY RECALL

Dealer Reported	02/26/2011	Lexus of New Orleans	42981	0161950	BLA INSUFFICIENT TIGHTENING OF THE FUEL PRESSURE SENSOR CERTAIN 2006 GS300, 2007 GS350, 2006 - EARLY 2009 IS250, &2006 - EARLY 2008 IS350 VEHICLES. - INSPECTED VEHICLE FOR FUEL LEAKAGE AT FUEL PRESSURE SENSOR. IF NO LEAK WAS FOUND, TIGHTENED FUEL PRESSURE SENSOR WITH PROPER TORQUE. IF FUEL LEAK WAS FOUND, REPLACED GASKET BETWEEN SENSOR & FUEL DELIVERY PIPE AND TIGHTENED SENSOR TO PROPER TORQUE. 1523A1
Dealer Reported	08/03/2010	Lexus of New Orleans	34309	0148343	COMPLIMENTARY WASH COMPLIMENTARY CAR WASH INCLUDES: WASH & DRY EXTERIOR VACUUM CARPET CLEAN DRIVERS DOOR GLASS - COMPETED.
Dealer Reported	08/03/2010	Lexus of New Orleans	34309	0148343	NON WARRANTABLE OPERATION CODE CUSTOMER REQUESTED A LOAN - (LOANER)
Dealer Reported	08/03/2010	Lexus of New Orleans	34309	0148343	DO NOT WASH VEHICLE - (NO WASH)
Dealer Reported	08/03/2010	Lexus of New Orleans	34309	0148343	NOTES CUSTOMER IS CONCERNED ABOUT RIMS PLEASE USE PROPER TORQUE IF RIMS ARE REMOVED. - RIMS WERE NOT REMOVED
Dealer Reported	08/03/2010	Lexus of New Orleans	34309	0148343	LIGHTS / BULBS C/S: AFS NOT WORKING WILL AUTO FOCUS BUT WONT TURN LEFT OR RIGHT - OPEN CIRCUIT IN HEADLIGHT ASSEMBLY OP810051 PART \$1026.06 LABOR \$152.00 RENT \$100.00 TAX \$103.08 TOTAL \$1381.14 AUTH #VSA1YC4958. - R&R LH HEAD LIGHT ASSEMBLY
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	COMPLIMENTARY WASH COMPLIMENTARY CAR WASH INCLUDES: WASH & DRY EXTERIOR VACUUM CARPET CLEAN DRIVERS DOOR GLASS - COMPETED.
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	NON WARRANTABLE OPERATION CODE CUSTOMER REQUESTED A LOAN - (LOANER)
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	NOTES EXT WARRANTY - PART \$1371.67 LABOR \$142.50 RENT \$250.00 TAX \$132.49 TOTAL \$1896.66 AUTH #VSA1XD1903
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	INTERIOR C/S: DRIVER SEAT CREAKS LOUDLY WHEN TURNING. WHEN WEIGHT IS SHIFTING - EXCESSIVE PLAY IN TRACK - REPLACE FRAME ASSY EX WARR
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	NOISE C/S VEHICLE RATTLE AT START UP. CUSTOMER IS AWARE OF TSIB - IMPROPER FREE PLAY IN INTAKE CAM GEAR ASSYS L - SB - 0156 - 08 - REPLACE BANK 1 & 2 INTAKE GEAR ASSY EG7027 6.0 T1 - 06 T2 - 40
Dealer Reported	06/04/2010	Lexus of New Orleans	32703	0143872	SSC 9LG DECLINED CUSTOMER DECLINES SPECIAL SERVICE CAMPAIGN 9LG. THIS CAMPAIGN IS HIGHLY RECOMMENDED AND DOES THE FOLLOWING: - SHORTENS THE LENGTH OF THE ACCELERATOR PEDAL - REDUCES THE CARPET PADDING UNDER THE ACCELERATOR PEDAL - UPDATES THE VEHICLES COMPUTER SOFTWARE SO TH - CUSTOMER DECLINED SSC 9LG.
Dealer Reported	01/25/2010	Lexus of Quad Cities	28283	0130574	SPECIAL SERVICE CAMPAIGN: 9LA IS250/IS350 REPLACE FUEL DELIVERY PIPES. SPECIAL SERVICE CAMPAIGN - FUEL DELIVERY PIPE REPLACEMENT. - COMPLETED FUEL PIPE UPDATE PER LEXUS
Dealer Reported	01/25/2010	Lexus of Quad Cities	28283	0130574	SPECIAL SERVICE CAMPAIGN: 9LB REPLACE REAR BRAKE DUST BOOT (ONE SIDE) AND THE RE SPECIAL SERVICE CAMPAIGN - REAR BRAKE CALIPER INSPECTION. - COMPLETED BRAKE BOOT UPDATE PER LEXUSM,

Dealer Reported	01/25/2010	Lexus of Quad Cities	28283	0130574	REPLACE RR BRAKE CALIPER SPECIAL SERVICE CAMPAIGN: 9LC REPLACE POWER STEERING LINK ASSEMBLY FOR IS250/IS3 SPECIAL SERVICE CAMPAIGN - ELECTRIC POWER STEERING LINK ASSEMBLY REPLACEMENT. - COMPLETED POWER STEERING RACK UPDATE PER LEXUS
Dealer Reported	01/25/2010	Lexus of Quad Cities	28283	0130574	SUBLET TOWING CHARGE TOWED TO SHOP
Dealer Reported	01/14/2009	McGrath Lexus of Westmont	22129	0476907	NON WARRANTABLE OPERATION CODE CHANGE ENGINE OIL & FILTER \$59.95 LUBRICATE DOOR HINGES CHECK ALL FLUID LEVELS ADJUST TIRE PSI - OIL AND FILTER CHANGED REAR TIRES @ 60% WORN. FRONT AND REAR BRAKES @ 60% WORN.
Dealer Reported	01/14/2009	McGrath Lexus of Westmont	22129	0476907	OTHERS LEFT REAR TIRE LOSES AIR, CHECK AND ADVISE. - TECH FOUND A NAIL IN THE LEFT REAR TIRE. - TECH REMOVED NAIL AND PLUGGED TIRE.
Dealer Reported	03/11/2008	McGrath Lexus of Westmont	16098	0448098	FRONT/REAR BODY REMOVE DENT FROM BODY. LEFT REAR DOOR - REMOVED 2 DENTS LEFT REAR DOOR
Dealer Reported	03/11/2008	McGrath Lexus of Westmont	16098	0448098	NON WARRANTABLE OPERATION CODE CUSTOMER STATES: FRONT TIRES WERE CROSS ROTATED AT THE 15,000 MILE SERVICE. CUSTOMER WOULD LIKE THEM ROTATED BACK. - ROTATED FRONT TIRES LEFT TO RIGHT BACK TO ORIGINAL POSTION.
Dealer Reported	03/11/2008	McGrath Lexus of Westmont	16098	0448098	ACCESSORY INSTALL NEW NAV DISC SEE JOHN HAS REPLACEMENT DISC. NAV SCREEN SHOWS CAR IN THE WRONG LOCATION. - NAV SHOWING WRONG LOCATION - INSTALLED NEW DISC
Dealer Reported	03/11/2008	McGrath Lexus of Westmont	16098	0448098	CAMPAIGNS FUEL PIPE CAMPAIGN - 7LC FUEL PIPE SSC - REPLACE FUEL PIPES PER 7LC SSC CAMPAIGN
Dealer Reported	02/15/2008	McGrath Lexus of Westmont	15791	0445809	NAVIGATION COMPUTER CHECK NAV, NAV SHOWS IN THE MIDDLE OF LAKE MICHIGAN - NAV NEEDS TO BE UPDATED - ORDERD NEW NAV DISC.
Dealer Reported	02/15/2008	McGrath Lexus of Westmont	15791	0445809	15,000M / IS300 05 15,000 MILE SERVICE / MINIMUM / IS300 05 - CHANGE ENGINE OIL AND FILTER CHECK AND SET TIRE PRESSURE CHECK ENGINE COMPARTMENT FLUID LEVELS ROTATE TIRES REPLACE WIPER BLADES REPLACE AIR FILTER INSPECT BODY AND CHASSIS INSPECT STEERING BOX INSPECT STEERING LINKAGE INSPECT BALL JOINTS AND DUST COVERS - 15K SERVICE COMPLETED
Dealer Reported	10/10/2007	McGrath Lexus of Westmont	13852	0433764	OTHERS FLAT TIRE - REPAIR IF POSSIBLE TIRE IN SPARE - INSTALL BACK IN PLACE VALVE STEM BROKE OFF FLAT TIRE PART IN CUPHOLDER - TIRE PRESSURE SENSOR WAS CRACKED DUE TO CHROME VALVE STEM COVER SEIZING ON SENSOR CAUSING LEAK IN TIRE - INSTALLED TIRE BACK ON SPARE, REPLACED LEFT FRONT TIRE PRESSURE SENSOR
Dealer Reported	10/10/2007	McGrath Lexus of Westmont	13852	0433764	NON WARRANTABLE OPERATION CODE CHANGE ENGINE OIL & FILTER \$44.95 LUBRICATE DOOR HINGES CHECK ALL FLUID LEVELS ADJUST TIRE PRESSURES
Dealer Reported	10/10/2007	McGrath Lexus of Westmont	13852	0433764	WINDSHIELD WIPER/WASHER REPLACE WIPER INSERTS - BOTH FRONT \$28.95 - REPLACED BOTH FRONT WIPER INSERTS
Dealer Reported	10/10/2007	McGrath Lexus of Westmont	13852	0433764	NON WARRANTABLE OPERATION CODE REPLACE AIR FILTER \$39 - REPLACED AIR FILTER
Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	TOUCHUP PAINT APPLICATION - HAS DENTS ON HOOD. EST. WANTS IT DONE - CALL WITH EST - DENTS

Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	REMOVED. FRONT/REAR BODY ON TILT - SUNROOF RATTLES - TESTED OPERATION, AND ROAD TESTED - NO ABNORMAL NOISES HEARD AT THIS TIME. - COULD NOT DUPLICATE CONCERN AT THIS TIME... NO CORRECTIONS MADE.
Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	5,000 MILE SERVICE CUSTOMER REQUESTS 5000 MILE SERVICE - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 5000 MILE SERVICE PERFORMED
Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	PERSONAL SETTINGS LEXUS PERSONALIZED SETTINGS - COMPLETED
Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	CAMPAIGNS 6LC RECALL - REPLACED BOTH FRT OUTER SEAT BELTS
Dealer Reported	10/12/2006	McGrath Lexus of Westmont	7122	0401337	OTHERS C/S REAR SUSPENSION LOOKS TO BE SAGGING. - NO PROBLEM FOUND - RIDE HEIGHT IS NORMAL...
Dealer Reported	11/04/2005	Bredemann Lexus	10	0626097	PREDELIVERY SERVICE FOR USA ALL ALTITUDES - OP CODE 0A1A03 - COMPLETE

Information Accuracy

Information presented on this Web site is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus dealership that conducted the service and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind.

Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer

CPO Owner Information

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site but will not be shared with future owners of the vehicle.

Owner-Reported Information and Privacy Terms

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this Web site, please [click here](#).