grey

**SERVICE HISTORY** 

**SERVICE HISTORY FOR: GREY** 

VIN: JTHBP262485001545

68248 MILES DATE: 04/28/2017

**REPAIR#** 0274386

REPORTED BY: Tri-County Lexus

**SERVICE:** HEADLIGHT UNIT (ONE SIDE)

**DESCRIPTION:** HEADLIGHT UNIT (ONE SIDE) ~|~CREDIT RO 274127 FOR HEADLIGHT REPAIR ~|~. HEADLIGHT UNIT (ONE SIDE) ~|~. HEADLIGHT UNIT (ONE SIDE) ~|~. HEADLIGHT UNIT (ONE SIDE) ~|~CREDIT RO 274127 FOR HEADLIGHT REPAIR ~|~. HEADLIGHT UNIT (ONE SIDE) ~|~HEADLIGHT UNIT (ONE SIDE) ~|~

68249 MILES DATE: 04/19/2017

**REPAIR#** 0274127

**REPORTED BY:** Tri-County Lexus

SERVICE:

**DESCRIPTION:** LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED A ~|~LOANER POLICY, CUST RESPONSIBLE FOR GAS, DAMAGE,& ALL MOTOR VEH VIOLAT ~|~ LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED A

**SERVICE:** FREE 27 POINT INSPECTION

**DESCRIPTION:** FREE 27 POINT INSPECTION ~|~FREE 27 POINT

INSPECTION ~ | ~

**SERVICE:** HEADLIGHT UNIT (ONE SIDE)

**DESCRIPTION:** HEADLIGHT UNIT (ONE SIDE) ~ | ~ CUST STATES THE PASSENGER SIDE HEADLIGHT HAS MOISTURE AND HE

THE PASSENGER SIDE HEADLIGHT HAS MOISTURE AND HE WOULD LIKE TO HAVE IT REPLACED. PLEASE CHECK AND ADVISE ~|~LEXUS CUSTOMER CARE GOODWILL 50/50 REPAIR HEADLIGHT UNIT (ONE SIDE) ~|~CUST STATES THE PASSENGER SIDE HEADLIGHT HAS MOISTURE AND HE WOULD LIKE TO HAVE IT REPLACED. PLEASE CHECK AND ADVISE ~|~LEXUS CUSTOMER CARE GOODWILL 50/50 REPAIR

**SERVICE:** CUSTOMER REQUESTS A COMPLIMENTARY EXTERIOR HAND CAR WASH.

**DESCRIPTION:** CUSTOMER REQUESTS A COMPLIMENTARY EXTERIOR HAND CAR WASH. ~|~CUSTOMER REQUESTS A COMPLIMENTARY EXTERIOR HAND CAR WASH. ~|~

**SERVICE:** GLH-REPL PANEL AIRBAG MODULE

**DESCRIPTION:** GLH-REPL PANEL AIRBAG MODULE ~|~SAFETY RECALL GLH - REMEDY NOTICE MULTIPLE MODELS AND MODEL YEARS TAKATA FRONT PASSENGER AIRBAG INFLATOR (ZONE B) ~|~RECALL

62928 MILES DATE: 12/23/2015

REPAIR# 0242483

**REPORTED BY:** Tri-County Lexus

SERVICE:

DESCRIPTION: CUSTOMER DECLINED REPLACEMENT OF HEADLAMP ASSEMBLY. LEXUS AUTHORIZED 50/50SPLIT BUT CUSTOMER DECLI ~| ~CUSTOMER STATES HE HAD THE RIGHT SIDE HEADLAMP ASSEMBLY REPLACED AND NOW THERE IS WATER INSIDE OF THE HEADLIGHT ASSEMBLY. PLEASE CHECK AND ADVISE ~| ~ CUSTOMER DECLINED REPLACEMENT OF HEADLAMP ASSEMBLY. LEXUS AUTHORIZED 50/50SPLIT BUT CUSTOMER DECLI LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED A ~| ~LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED AND PAY FOR ALL TOLLS AND TICKETS. ~| ~ LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED AND FOR ALL TOLLS AND TICKETS. ~| ~ LOANER POLICY. CLIENTS MUST RETURN LOANER CAR WHEN THEIR VEHICLE IS COMPLETED, REPLACE FUEL USED A

**DESCRIPTION:** CUSTOMER REQUEST A 27 POINT INSPECTION ~|~CUSTOMER REQUEST A 27 POINT INSPECTION ~|~SEE YOUR ADVISOR FOR YOUR MULTI POINT INSPECTION SHEET RESULTS ~|~62924 PERFORMED 27PT INSPECTION. FOUND WATER PUMP

**SERVICE:** CUSTOMER REQUEST A 27 POINT INSPECTION

~ I~62924 PERFORMED 27PT INSPECTION. FOUND WATER PUMI LEAKING, BATTERY FAILED TEST, CABIN AIR FILTER IS DIRTY AND FUEL CAP GASKET IS DRY ROTTED. RECOMMEND REPLACEMENT OF WATER PUMP WITH COOLANT FLUSH, REPLACEMENT OF BATTERY, REPLACEMENT OF CABIN AIR FILTER AN

**SERVICE:** ELE-INSP FAN/REPL FAN ASSEMBLY

**DESCRIPTION:** ELE-INSP FAN/REPL FAN ASSEMBLY ~|~LIMITED SERVICE CAMPAIGN (LSC) ELE - CERTAIN 2008 - 2012 MODEL YEAR IS F VEHICLES - ENGINE COOLING FANS. ~|~ELE RECALL & RADIATOR ASSEMBLY ~|~62924 VERIFIED VEHICLE HAS OPEN REALL - LSC. COOLING FANS ARE MAKING NOISE AND ARE MISSING SCREWS. PERFORMED SSC - LSC COOLING FANS ASSEMBLY REPLACEMENT THEN TESTED. PASSED. RADIATOR IS DAMAGED AND LEAKING COOLANT. RADIATOR IS OLD. REMOVED AND REPLACED RA

SERVICE: RADIATOR ASSEMBLY DESCRIPTION:

61223 MILES DATE: 08/11/2015

**REPAIR#** 0234936

**REPORTED BY:** Tri-County Lexus

**SERVICE:** ELF-REPL FUEL PRESSURE GASKE T-IS

F,GS460,LS460,LS600H

**DESCRIPTION:** ELF-REPL FUEL PRESSURE GASKE T-IS

F,GS460,LS460,LS600H ~ | ~SAFETY RECALL ELF - REMEDY NOTICE - VARIOUS MODELS - POTENTIAL FUEL PRESSURE SENSOR LEAK ~ | ~OPEN CAMPAIGN

**SERVICE:** REMOVE SERRATION PATTERN & INSTALL NEW WIPER ARM NUTS

**DESCRIPTION:** REMOVE SERRATION PATTERN & INSTALL NEW WIPER ARM NUTS ~| ~SAFETY RECALL DLA - REMEDY NOTICE - 2006 THROUGH EARLY 2012 MODEL YEAR IS 250 AND IS 350, 2010 THROUGH EARLY 2012 MODEL YEAR IS250C AND IS 350C, AND 2008 THROUGH 2011 MODEL YEAR IS-F FRONT WIPER ARM NUT ~| ~DUE FOR SERVIC

**SERVICE: PART ON BACKORDER** 

**DESCRIPTION:** PART ON BACKORDER  $\sim$ 1  $\sim$ 1 LIMITED SERVICE CAMPAIGN (LSC) ELE - CERTAIN 2008 - 2012 MODEL YEAR IS F VEHICLES - ENGINE COOLING FANS  $\sim$ 1  $\sim$ 

SERVICE: REPLACE INTERNAL TRUNK RELEASE LEVER

DESCRIPTION: REPLACE INTERNAL TRUNK RELEASE LEVER

~ | ~PRODUCT UPDATE DLB - REMEDY NOTICE - CERTAIN 2006 TO

EARLY 2013 MY IS 250, IS 350 & IS-F, CERTAIN 2007 TO EARLY 2013

MY ES 350 & ES 300H, & CERTAIN 2013 MY GS 350 & GS 450H

VEHICLES - INTERNAL TRUNK RELEASE LEVER (HANDLE)

~ | ~OPEN CAMPAIGN

50390 MILES DATE: 02/16/2013

**REPAIR#** 0191521

**REPORTED BY:** Tri-County Lexus

**SERVICE:** PERFORMED 27 POINT SERVICE/SAFTY INSPECTION. **DESCRIPTION:** PERFORMED 27 POINT SERVICE/SAFTY INSPECTION. ~|~PERFORMED 27 POINT SERVICE/SAFTY INSPECTION.

**SERVICE: REPLACED HID BULB** 

**DESCRIPTION:** REPLACED HID BULB ~ | ~ C/S LEFT FRONT

HEADLIGHT BULB IS INOP

35350 MILES DATE: 01/07/2011

**REPAIR#** 0156648

**REPORTED BY:** Tri-County Lexus

**SERVICE:** RE-BALANCED TIRE

**DESCRIPTION:** RE-BALANCED TIRE ~ | ~ CLIENT STATES THAT HE WAS HERE TWO WEEKS AGO FOR ROAD FORCE BALANCE AND

THERE IS STILL A VIBRTION

35091 MILES DATE: 12/24/2010

**REPAIR#** 0156051

**REPORTED BY:** Tri-County Lexus

**SERVICE:** FORCE BALANCED TIRES

 $\textbf{DESCRIPTION:} \ \ \text{FORCE BALANCED TIRES} \ \sim \ | \ \sim C/S \ \text{CHECK FRONT}$ 

TIRE BALANCE. C/S SLIGHT SHAKING WHEN DRIVING

**SERVICE:** HEADLIGHT UNIT (ONE SIDE)

**DESCRIPTION:** HEADLIGHT UNIT (ONE SIDE) ~ | ~ C/S

HEADLIGHT INOP.INSTALL SOP ~ | ~WILL TURN ON,IR ADJUST ~ | ~35091 WILL NOT TURN ON OR ADJUST,ALSO LEAKING INSIDE

THE HOUSING

35013 MILES DATE: 12/20/2010

**REPAIR#** 0155659

**REPORTED BY:** Tri-County Lexus

SERVICE: 9LG REPL PEDAL PAD REFLASH AWFM - IS MODELS

ONLY

**DESCRIPTION:** 9LG REPL PEDAL PAD REFLASH AWFM - IS MODELS ONLY ~ | ~9LG IS PEDAL MODIFICATION ~ | ~RECALL

**SERVICE:** OTHER NON-OEM CLEANING/ PROTECTING

PREPARATION

**DESCRIPTION:** OTHER NON-OEM CLEANING/ PROTECTING PREPARATION  $\sim$  |  $\sim$  C/S THE P/S HEADLIGHT IS HOLDING WATER CHECK AND REPORT  $\sim$  |  $\sim$  35010 HEADLIGHT ORDERED FOR

CLIENT

**20 MILES DATE:** 04/09/2008

**REPAIR#** 0087534

**REPORTED BY:** Tri-County Lexus

SERVICE: SHOWROOM CLEAN

**DESCRIPTION:** SHOWROOM CLEAN ~ | ~ CUSTOMER STATES

SHOWROOM CLEAN ~ | ~ ~ | ~ SHOWROOM CLEAN

**DATE** 04/00/0000

**REPAIR#** 0087389

**REPORTED BY:** Tri-County Lexus

SERVICE: COMP

**DESCRIPTION:** COMP ~ | ~ CUSTOMER STATES PERFORM PRE DEL

INSPECTION ~ | ~ ~ | ~ COMP

SERVICE: ETCH ALL WINDOWS RECORD NUM 725904

DESCRIPTION: ETCH ALL WINDOWS RECORD NUM 725904

~ | ~ CUSTOMER STATES ETCH ALL WINDOWS RECORD ALL NUM

~|~~|~ETCH ALL WINDOWS RECORD NUM 725904

SERVICE: GAS TANK FILL

**DESCRIPTION:** GAS TANK FILL ~ | ~ CUSTOMER STATES GAS

TANK FILL ~ | ~ ~ | ~ GAS TANK FILL

## **TERMS AND CONDITIONS**

## INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicl s service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions concerns regarding this information should be addressed to the applicable Lexus dealer.

## L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

## **OWNER-REPORTED INFORMATION AND PRIVACY TERMS**

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please <u>click</u> <u>here</u> (//www.lexus.com/privacy/online-statement).