



Technical Service Information Bulletin

September 17, 2004

Title: BRAKE BOOSTER

Models: '04 RX 330 (NAP)

BR005-04
BRAKES

Introduction To improve the overall brake pedal feeling during cold starts, the brake booster assembly has been changed.

- Applicable Vehicles**
- **2004** model year **RX 330 (NAP)** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

| MODEL | PLANT | DRIVELINE | PRODUCTION CHANGE EFFECTIVE VIN |
|--------|-------|-----------|---------------------------------|
| RX 330 | TMMC | 2WD | 2T2GA31U#4C015883 |
| | | 4WD | 2T2HA31U#4C030481 |

Parts Information

| MODEL | PREVIOUS PART NUMBER | CURRENT PART NUMBER | PART NAME | QTY |
|-------|----------------------|---------------------|---------------|-----|
| 2WD | 44610-0E010 | Same | Brake Booster | 1 |
| 4WD | 44610-0E020 | Same | | 1 |

Repair Procedure

1. Remove and replace the brake booster following the procedures outlined in the Technical Information System (TIS), 2004 model year RX 330 Repair Manual: *Brake: Brake Booster Assy.*
2. Road test the vehicle to confirm repair.

Warranty Information

| OP CODE | DESCRIPTION | TIME | OFP | T1 | T2 |
|---------|---------------------|------|--|----|----|
| 463011 | R & R Brake Booster | 1.9 | 44610-0E010 (2WD) 44610-0E020 (4WD) | 38 | 48 |

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

