

Service History for 2010 RX350 NONE (9424) V6 - 2GR-FE, 6AT/4WD, 01G0-SMOKY GRANITE MICA [2T2BK1BA6AC010727]

	0.4	\$29.76	\$0	\$0	\$0	\$0	\$29.76
--	-----	---------	-----	-----	-----	-----	---------

RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
01/06/2017	NSH	94233	NORTHBOROU (62006)	0265949	\$72.71	01/06/2017	OLSON,MICHAEL

Condition: 1- Op Code: PRIME ITEM **Pay Type:** CUSTOMER PAY

Op Code CHANGE OIL AND FILTER. INSPECT FILTERS. INSPECT AND TOP OFF ALL UNDER THE HOOD FLUID LEVELS. SET T ~|~CHANGE OIL AND FILTER. INSPECT FILTERS.
Desc: INSPECT AND TOP OFF ALL UNDER THE HOOD FLUID LEVELS. SET TIRE PRESSURES. ~|~ ~|~94233 CHANGED ENGINE OIL AND FILTER, SET TIRE PRESSURES.

Claim #:	Part Qty: 1	Part #: 04152YZZA1	Part Desc: REPLACEABLE ELEMENT
	Part Qty: 1	Part #: 9043012031	Part Desc: GASKET
	Part Qty: 7	Part #: 00279T0W2001	Part Desc: 0W20 BULK TXM WTY
	Part Qty: 1	Part #: WSW	Part Desc: (-20) WASHER SOLVENT

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
	0.4	\$29.76	\$42.95	\$0	\$0	\$0	\$72.71

Condition: 2- Op Code: RS20 **Pay Type:** CUSTOMER PAY

Op Code ABSORBER, SHOCK/STRUT (REAR) - REPLACE, THE RIGHT REAR SHOCK IS LEAKING. ~|~ ~|~ ,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

No Part Info Available

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
	0.0	\$0	\$0	\$0	\$0	\$0	\$0

Condition: 3- Op Code: 000000 **Pay Type:** INTERNAL (DEALER) PAY

Op Code LEXUS MULTI POINT INSPECTION ~|~LEXUS MULTI POINT INSPECTION
Desc: ~|~ ~|~94233 SUGGEST REPLACING RIGHT REAR SHOCK NEXT SERVICE ESTIMATE \$451.00

No Part Info Available

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
ROONEY,GEORGE	0.0	\$0	\$0	\$0	\$0	\$0	\$0

RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
07/27/2016	NSH	88467	NORTHBOROU (62006)	256433C	\$136.77	07/27/2016	ALDRICH,EDWARD

Condition: 1- Op Code: 002469 **Pay Type:** INTERNAL (DEALER) PAY

Op Code SYSTEM, BRAKES - FLUSH ~|~CUSTOMER REQUESTS BRAKE FLUID REPLACEMENT ~|~ ~|~88467 PERFORMED BRAKE FLUID FLUSH PROCEDURE.
Desc: BILL TO SERVICE POLICY PER SERVICE DIRECTOR FOR CUSTOMER SATISFACTION.

Service History for 2010 RX350 NONE (9424) V6 - 2GR-FE, 6AT/4WD, 01G0-SMOKY GRANITE MICA
 [2T2BK1BA6AC010727]

Claim #: Part Qty: 1 Part #: 06002 Part Desc: HEAVY-DUTY BRAKE FLU
 Part Qty: 1 Part #: 0023400192 Part Desc: BULB

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
TAPARAUSKY,NICHOLAS	1.0	\$112.57	\$24.2	\$0	\$0	\$0	\$136.77

RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
07/27/2016	NSH	88467	NORTHBOROU (62006)	0256433	\$142.69	07/27/2016	ALDRICH,EDWARD

Condition: 1- Op Code: PRIME ITEM Pay Type: CUSTOMER PAY

Op Code CHANGE OIL AND FILTER. INSPECT FILTERS. INSPECT AND TOP OFF ALL UNDER THE HOOD FLUID LEVELS. SET T ~|~CHANGE OIL AND FILTER. INSPECT FILTERS.
 Desc: INSPECT AND TOP OFF ALL UNDER THE HOOD FLUID LEVELS. SET TIRE PRESSURES. ~|~ ~|~88467 PERFORMED ENGINE OIL AND FILTER CHANGE

Claim #: Part Qty: 1 Part #: 04152YZZA1 Part Desc: REPLACEABLE ELEMENT
 Part Qty: 1 Part #: 9043012031 Part Desc: GASKET
 Part Qty: 7 Part #: 00279T0W2001 Part Desc: 0W20 BULK TXM WTY
 Part Qty: 1 Part #: WSW Part Desc: (-20) WASHER SOLVENT

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
	0.4	\$29.76	\$37.98	\$0	\$0	\$0	\$67.74

Condition: 2- Op Code: 420000 Pay Type: CUSTOMER PAY

Op Code FOUR WHEEL TIRE ROTATION WITH VISUAL BRAKE INSPECTION ~|~FOUR
 Desc: WHEEL TIRE ROTATION WITH VISUAL BRAKE INSPECTION ~|~ ~|~88467 PERFORMED FOUR WHEEL TIRE ROTATION

No Part Info Available

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
TAPARAUSKY,NICHOLAS	0.4	\$39.95	\$0	\$0	\$0	\$0	\$39.95

Condition: 3- Op Code: 000000 Pay Type: CUSTOMER PAY

Op Code STATE INSPECTION ~|~STATE INSPECTION ~|~ ~|~88467 PERFORMED
 Desc: STATE INSPECTION STICKER.

Claim #: Part Qty: 1 Part #: STICKER Part Desc: INSPECTION STICKER

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
OBRIEN,KEVIN	0.3	\$23.5	\$11.5	\$0	\$0	\$0	\$35

Condition: 4- Op Code: 862000 Pay Type: CUSTOMER PAY

Op Code MOVED TO: 256433C LINE: A ~|~MOVED TO: 256433C LINE: A
 Desc: ~|~

No Part Info Available

Service History for 2010 RX350 NONE (9424) V6 - 2GR-FE, 6AT/4WD, 01G0-SMOKY GRANITE MICA [2T2BK1BA6AC010727]

FRANCIS,FRITZ	0.3	\$23.5	\$11.5	\$0	\$0	\$0	\$35
---------------	-----	--------	--------	-----	-----	-----	------

Condition: 3- Op Code: 420000 **Pay Type: CUSTOMER PAY**

Op Code Desc: FOUR WHEEL TIRE ROTATION WITH VISUAL BRAKE INSPECTION ~|~FOUR WHEEL TIRE ROTATION WITH VISUAL BRAKE INSPECTION ~|~ ~|~75910 THE TECH REPORTS - THE TIRE(S) ROTATIONAL SERVICE ALONG WITH (VISUAL) BRAKE(S) INSPECTION HAS BEEN COMPLETED. THE TIRES MEASURE - 6/32MDS FRONT & 5/32NDS REAR. THE BRAKES MEASURE - 10 MM FRONT & REAR.

No Part Info Available

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
FRANCIS,FRITZ	0.4	\$39.95	\$0	\$0	\$0	\$0	\$39.95

Condition: 4- Op Code: 000000 **Pay Type: CUSTOMER PAY**

Op Code Desc: STRUTS - FRONT: LEVEL 1 LEAK RF STRUT. (198900729) ~|~STRUTS - FRONT: LEVEL 1 LEAK RF STRUT. (198900729) ~|~ ~|~75910 THE TECH REPORTS - THE RIGHT FRONT STRUT HAS BEEN REMOVED & REPLACED. (AS IT WAS CONFIRMED AS LEAKING)

Claim #: **Part Qty:** 1 **Part #:** 4815848040 **Part Desc:** INSULATOR, FR COIL S
Part Qty: 1 **Part #:** 486090E050 **Part Desc:** SUPPORT SUB-ASSY, FR
Part Qty: 1 **Part #:** 485108Z073 **Part Desc:** ABSORBER SET, SHOCK,

Technician	Hours	Labor	Parts	Sublet	Fluids	Body Shop	Total Condition Amt
FRANCIS,FRITZ	2.0	\$291.96	\$346.59	\$0	\$0	\$0	\$638.55

RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
12/18/2013	WARRANTY	52699	NORTHBOROU (62006)	200474	\$164.75	019884	WARRANTY PAY

Claim #: 019884 **Part #:** **Part Desc:** **Replaced Part:** Y **Goodwill Indicator:** N

Op Code: ELSBOS **Repair:** UPDATE ECM SOFTWARE AND INSTALL UPDATE LABEL

T1: **T2:** **T3:**

Condition Desc: BSL

Cause Desc: BSL

Remedy Desc: 52692 COMPLETED.

RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
07/20/2012	WARRANTY	32047	NORTHBOROU (62006)	171265	\$79.18	010001	WARRANTY PAY

Claim #: 010001 **Part #:** **Part Desc:** **Replaced Part:** N **Goodwill Indicator:** N

Op Code: 9LG4PR **Repair:** RPLC ACCEL PEDAL & INSPECT & RPLC THE AWFMS AS NECESSARY

T1: **T2:** **T3:**

Condition Desc: 9LG

Cause Desc: 9LG

Service History for 2010 RX350 NONE (9424) V6 - 2GR-FE, 6AT/4WD, 01G0-SMOKY GRANITE MICA [2T2BK1BA6AC010727]

Remedy Desc: 32047 9LG PERFORMED SSC 9LG, REPLACED THE GAS PEDAL ASSEMBLY AS REQUIRED FOR IN STOCK VEHICLES. THE							
RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
06/14/2010	WARRANTY		NORTHBOROU (62006)		\$116.84	994622	WARRANTY PAY
Claim #: 994622	Part #:		Part Desc:		Replaced Part: N		Goodwill Indicator: N
Op Code: 00110F	Repair: 10,000 MILE FULL SERVICE						
T1:	T2:	T3:					
Condition Desc:							
Cause Desc:							
Remedy Desc:							
RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
11/04/2009	WARRANTY		NORTHBOROU (62006)		\$111.02	983819	WARRANTY PAY
Claim #: 983819	Part #:		Part Desc:		Replaced Part: N		Goodwill Indicator: N
Op Code: 001050	Repair: 5,000 MILE SERVICE						
T1:	T2:	T3:					
Condition Desc:							
Cause Desc:							
Remedy Desc:							
RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
08/08/2009	WARRANTY	927	NORTHBOROU (62006)	107342	\$380.61	980132	WARRANTY PAY
Claim #: 980132	Part #: 851100E020		Part Desc: MOTOR ASSY, FR WIPER		Replaced Part: N		Goodwill Indicator: N
Op Code: 850161	Repair: WINDSHIELD WIPER MOTOR ASSY						
T1: 81	T2: 71	T3:					
Condition Desc: VERIFIED CONCERN. WIPER MOTOR FAULTY. REPLACED WIPER MOTOR. VERIFIED REPAIR.							
Cause Desc: VERIFIED CONCERN. WIPER MOTOR FAULTY. REPLACED WIPER MOTOR. VERIFIED REPAIR.							
Remedy Desc: 926 WIPER MOTOR CHECKED THE WIPER OPERATION,MOTOR HAS POWER BUT IS NOT MOVING,CAN MOVE THE WIPERS BY							
RO Close	Source	Mileage	Dealer	RO Number	Amount	Claim #	Pay Type
08/08/2009	WARRANTY		NORTHBOROU (62006)		\$47.42	980133	WARRANTY PAY
Claim #: 980133	Part #:		Part Desc:		Replaced Part: N		Goodwill Indicator: N
Op Code: 001010	Repair: 1,000 MILE SERVICE						
T1:	T2:	T3:					
Condition Desc:							
Cause Desc:							
Remedy Desc:							

Note : This vehicle has older service records that are not included in this printout.