

Quality Vehicle Inspection

Customer Name: Car Choice Motors
 Phone: 954-532-9280
 Service Advisor:

Vehicle Year/Model: 1996 Lexus SC 400
 VIN Number: JT8CH32Y6T0049779
 Technician:

Date/Time: 8/19/2011 3:04 PM
 Mileage: 99689
 RO Number: 407860

INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------	--------------------------------	------------------------------

<input type="checkbox"/>	C H E C K & F I L L	<input type="checkbox"/>	Washer fluid
<input type="checkbox"/>		<input checked="" type="checkbox"/>	Brake fluid ¹
<input type="checkbox"/>		<input checked="" type="checkbox"/>	Power steering fluid ²
<input type="checkbox"/>		<input checked="" type="checkbox"/>	Coolant ³
<input type="checkbox"/>		<input type="checkbox"/>	Wheel Lock
<input type="checkbox"/>		<input type="checkbox"/>	Enter tire size
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Operation of horn, interior lights, exterior lights(turn,hazard,brake)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Windshield washer spray, wiper operation, and wiper blades
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Heater operation for leaks or damage
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Check Transmission Fluid Condition ⁴
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check for Oil and/or Fluid Leaks
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Constant velocity (CV) drive boots (if equipped)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exhaust system (leaks, damage, loose parts)
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Shocks/struts and other suspension components for leaks and/or damage ⁵
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check Drive Belt(s)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Brake Adjustment
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Condition (If Equipped-Reset Service Rem. Light if changing oil)
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Inspect Engine Air Filter ⁶
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect AC filter(if equipped)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	BATTERIES.

Front / Rear Brake Linings

LF		RF
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
<input type="checkbox"/>		<input type="checkbox"/>
<input type="checkbox"/>		<input type="checkbox"/>
LR		RR
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>

Inspection Not Taken

More than 50% remaining
20% - 50% remaining
Less than 20% remaining

Check Tires / Tread Depth

(see note)

LF		RF
<input type="checkbox"/>		<input type="checkbox"/>
<input type="checkbox"/>		<input type="checkbox"/>
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
LR		RR
<input type="checkbox"/>		<input type="checkbox"/>

7/32" or Greater
4/32" to 6/32"
3/32" or Less

Check Battery Performance

<input type="checkbox"/>	Good		<input type="checkbox"/>
<input type="checkbox"/>	Bad		Actual Cold Cranking Amps

Quality Vehicle Inspection

Customer Name: Car Choice Motors

Vehicle Year/Model: 1996 Lexus SC 400

Date/Time: 8/19/2011 3:04 PM

Phone: 954-532-9280

VIN Number: JT8CH32Y6T0049779

Mileage: 99689

Service Advisor:

Technician:

RO Number: 407860

General Comments

LEFT ELECTROCHROMATIC MIRROR LENS FAILED.
PARTS: \$380
LABOR: .6hrs

ANTENNA MISSING
PARTS: \$525
LABOR: .6hrs

RECOMMEND T-BELT, CAP & ROTORS, AND WIRES

KEYFOB BATTERY DEAD

Tire Inspection Comments

- BOTH FRONT TIRES HEAVILY CHOPPED ON INSIDE EDGE. BOTH REAR TIRES BALD AND CHOPPED. REQUIRES 4 TIRES

Inspection Comment 1

- BRAKE FLUID BLACK. REQUIRES FLUSH

Inspection Comment 2

- P/S FLUID BLACK, LEVEL LOW. LEAKS AT PUMP AND PRESSURE HOSE
PARTS: \$1,423
LABOR: 3.8hrs

Inspection Comment 3

- NO COOLANT IN RESEVOIR. RADIATOR APPEARS NEW. WOULD LIKE TO KNOW OF OVERHEAT EVENT IN HISTORY?

Inspection Comment 4

- TRANSMISSION FLUID BLACK. HEAVY LEAK FROM TRANSMISSION. CODE P0773 (SHIFT SOLENOID "E"). BECAUSE OF OVERALL CONDITION, RECOMMEND TRANSMISSION REPLACEMENT.

PARTS: \$3100
LABOR: 6.5hrs

Inspection Comment 5

- L/R AND R/F STRUTS BLOWN. R./R STRUT RATTLE. REQUIRES ALL 4 STRUTS.
PARTS: \$1240
LABOR: 6.7hrs

Inspection Comment 6

- AIR FILTER DIRTY