

FRONT MARKER LAMP LENS LH


REPLACEMENT

65034-02

HINT:

COMPONENTS: See page 65-5

1. REMOVE RADIATOR GRILLE (See page 76-2)
2. REMOVE FRONT FENDER LINER LH (See page 76-2)
3. REMOVE FRONT FENDER LINER RH (See page 76-2)
4. REMOVE FRONT BUMPER COVER (See page 76-2)



5. REMOVE FRONT MARKER LAMP ASSY LH
 - (a) Remove the screw.
 - (b) Remove the front marker lamp assy.
 - (c) Remove the bulb socket and front marker lamp assy LH.