



**Technical Service  
Information Bulletin**

February 15, 2002

Title:

**MARK LEVINSON AMPLIFIER  
INSTALLATION CAUTIONS**

Models:

'01 – '02 GS 430/300, LS 430, LX 470;  
'02 ES 300 & SC 430

AUDIO  
AU001-02

**Introduction** Some replacement Mark Levinson amplifiers may appear to be inoperative when first installing them into a vehicle. The following cautions should ensure the amplifier will work properly when installed.

- Applicable Vehicles**
- **2001 – 2002** model year **GS 300, GS 430, LS 430** and **LX 470** vehicles **equipped with the Mark Levinson sound system.**
  - **2002** model year **ES 300** and **SC 430** vehicles **equipped with the Mark Levinson sound system.**

- Installation Cautions**
1. With the ignition key out of the ignition, install the replacement amplifier into the vehicle.
  2. Insert the ignition key into the ignition, turn the ignition key to “ACC” and wait for 5 minutes.

**NOTE:**

**During this 5 minute period, the amplifier is initializing itself to match the vehicle's audio settings.**

3. After 5 minutes, turn the ignition key to “LOCK” and wait 1 minute.
4. After 1 minute, turn the ignition key to “ACC” and push the “Power” button on the radio to confirm normal sound system operation.

**Warranty Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

