



Title:

REPAIR MANUAL CORRECTIONS INDEX

Models:

All Models

Introduction Correction pages are available for the service publications listed below. This bulletin summarizes service publication content changes that have been released between February 2003 and March 2004. These changes have already been implemented in the Toyota Technical Information System (TIS). For the most accurate service information content, technicians are strongly encouraged to refer to TIS (<http://tis.toyota.com>). Internet access is also available to Lexus service information content by subscription (<http://techinfo.lexus.com>).

NOTE:

Inventory quantities of printed correction pages are limited, and part numbers are obsolete when supplies are exhausted. When ordering a technical publication (i.e., Repair Manual, Electrical Wiring Diagram) from the MDC, any correction page(s) associated with that particular publication which were published at the time of purchase will automatically be included with your order.

Parts Information Correction pages may be ordered from the Materials Distribution Center (MDC) through Dealer Daily or by calling the MDC at 1-800-622-2033 using the corresponding part numbers from the following table.

Publication	Number	Page(s)	Part Number
ES 300	2002 ES 300 RM 911-U1 . . .	05-748, 05-749,	00245-RM911-3157
		05-749-1, 05-749-2	↓
	2003 ES 300 RM989-U1	05-93, 05-99	00245-RM911-3272
		05-844, 05-845,	00245-RM989-3152
		05-845-1, 05-845-2	↓
GX 470	2003 GX 470 RM1006-U1 . .	02-32 to 02-34	00245-RM100-3112
		05-883, 05-884,	00245-RM100-3161
		05-884-1, 05-884-2	↓
		03-43	00245-RM100-3193
		RM1006-U2	27-7, 27-8
		30-38	00245-RM100-3112B
IS 300	2002 IS 300 RM869-U2	BE-38, BE-39	00245-RM869-3050B
		BE-95	00245-RM869-3098B
	2003 IS 300 RM980-U2	BE-38, BE-39	00245-RM980-3051B
		BE-95	00245-RM980-3095B



	Publication	Number	Page(s)	Part Number
LS 430	2001 LS 430	RM812-U2	BE-101	00245-RM812-2202B
	2002 LS 430	EWD457-U	414	00245-EWD45-3190
		RM874-U2	BE-101	00245-RM874-2201B
			BO-94 to BO-97,	00245-RM874-3039B
			BO-97-1, BO-97-2,	↓
			BO-99 to BO-104,	↓
			BO-104-1, BO-104-2	↓
			BE-31, BE-32	00245-RM874-3047B
			BE-69	00245-RM874-3120B
	2003 LS 430	EWD504-U	414	00245-EWD45-3191
		RM988-U2	BE-101	00245-RM988-2200B
			BO-94 to BO-97,	00245-RM988-3040B
			BO-97-1, BO-97-2,	↓
			BO-99 to BO-104,	↓
			BO-104-1, BO-104-2	↓
		BE-31, BE-32	00245-RM988-3048B	
		BE-69	00245-RM988-3121B	
LX 470	2002 LX 470	RM914-U2	BE-39, BE-40	00245-RM914-3055B
	2003 LX 470	EWD508-U	72, 73, 86, 87, 102,	00245-EWD50-2203
			103, 269, 288, 289, 437,	↓
			442, 443, 451, 456,	↓
			Overall M:13 (cont'd), M:27	↓
		RM973-U1	SS-23	00245-RM973-3197
			DI-136, DI-137, DI-143,	00245-RM973-3268
			DI-144, DI-150, DI-151,	↓
			DI-171, DI-172	↓
		RM973-U2	BE-121	00245-RM973-2186B
		BE-41, BE-42	00245-RM973-3056B	
RX 300	2002 RX 300	RM876-U1	DI-221, DI-223	00245-RM876-3315
	2003 RX 300	RM961-U1	DI-122, DI-124, DI-129,	00245-RM961-3269
			DI-131, DI-136, DI-138, DI-158	↓
			DI-278, DI-280	00245-RM961-3316
RX 330	2004 RX 330	EWD523-U	400, Overall M:33-1	00245-EWD52-3192
		RM1027-U1	03-30, 05-343, 05-347	00245-RM102-3034
		RM1027-U2	26-8	00245-RM102-3034B
			05-1164 to 05-1168	00245-RM102-3122B
		RM1027-U3	82-4 to 82-7, 82-7-1,	00245-RM102-3185C
			82-7-2	↓
SC 430	2003 SC 430	RM962-U2	73-8	00245-RM962-2182B