



**Technical Service
Information Bulletin**

February 28, 1997

Title:
DRIVEABILITY IMPROVEMENT

Models:
'96 LS 400



**ENGINE
EG002-97**

Introduction Early Production 1996 Model Year LS 400 vehicles may experience an engine idle speed reduction just before stopping the vehicle after a continuous long drive. To correct this condition, the ECM logic has been changed.

Production Change Information

- Early production 1996 LS 400 with VINs **before JT8BH22F3T0041045**

Parts Information

PREVIOUS PART NUMBER	NEW PART NUMBER	PART NAME
89661-50302	89661-50303	ECM

Warranty Information

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
895011	LS 400 Driveability Improvement	0.8	89661-50302	08	71

Warranty Coverage:
4 Years or 50,000 Miles.

