

99531 MILES

**DATE:** 04/08/2017

**REPAIR#** 0265000

**REPORTED BY:** Plaza Lexus

**SERVICE:** COMPLIMENTARY CAR WASH

**DESCRIPTION:** COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH  
~|~

**SERVICE:** LUBE OIL AND FILTER

**DESCRIPTION:** LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~OIL CHANGE  
~|~99529 OIL CHANGE CHANGED OIL AND FILTER

**SERVICE:** MULTI POINT INSPECTION

**DESCRIPTION:** MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~MPI  
~|~99529 MPI CABIN AIR FILTER REPLACEMENT ENGINE AIR FILTER

REPLACEMENT BRAKE FLUSH FUEL INDUCTION SERVICE BRAKE JOB - REAR  
(REPLACE PADS/RESURFACE ROTORS) COOLANT FLUSH

**SERVICE:** ROTATE TIRES

**DESCRIPTION:** ROTATE TIRES ~|~ROTATE TIRES ~|~TIRE ROTATION ~|~99529  
TIRE ROTATION ROTATED TIRES

96275 MILES

**DATE:** 03/17/2017

**REPAIR#** 0263917

**REPORTED BY:** Plaza Lexus

**SERVICE:** COMPLIMENTARY CAR WASH

**DESCRIPTION:** COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH  
~|~CAR WASH ~|~96273 CAR WASH CAR WASHED

**SERVICE:** MISCELLANEOUS MAINTENANCE - REPAIR

**DESCRIPTION:** MISCELLANEOUS MAINTENANCE - REPAIR ~|~CUST STATES  
STEERING WHEEL VIBRATION AT HIGHWAY SPEEDS PLEASE BALANCE FRONT  
TIRES AND TEST DRIVE ~|~BALANCE WHEELS ~|~96273 BALANCE WHEELS 4  
WHEELS WERE ROAD FORCED BALANCED

**SERVICE:** MULTI POINT INSPECTION

**DESCRIPTION:** MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION  
~|~MULTI POINT ~|~96273 MULTI POINT CABIN AIR FILTER REPLACEMENT  
ENGINE AIR FILTER REPLACEMENT BRAKE JOB - REAR (REPLACE  
PADS/RESURFACE ROTORS): PADS IN THE REAR ARE DOWN TO 2-3MM AND  
SHOULD BE CHANGED IF NOT NOW IN THE NEXT SERVICE

96198 MILES

**DATE:** 03/16/2017

REPAIR# 0263907

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH  
~|~

SERVICE: NO INSPECTION NEEDED

DESCRIPTION: NO INSPECTION NEEDED ~|~NO INSPECTION NEEDED ~|~

94165 MILES

DATE: 02/25/2017

REPAIR# 0263024

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH  
~|~COMPLIMENTARY CAR WASH ~|~94163 COMPLIMENTARY CAR WASH CAR  
WASHED

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION

~|~MULTI POINT INSPECTION ~|~94163 MULTI POINT INSPECTION MPI

PERFORMED, 2 TIRES AND AIR FILTERS RECOMMENDED

SERVICE: OIL AND FILTER - CHANGE

DESCRIPTION: OIL AND FILTER - CHANGE ~|~OIL AND FILTER - CHANGE

~|~OIL AND FILTER CHANGE ~|~94163 OIL AND FILTER CHANGE OIL AND  
FILTER CHANGED

SERVICE: PERFORM COMPLETE 4 WHEEL ALIGNMENT

DESCRIPTION: PERFORM COMPLETE 4 WHEEL ALIGNMENT ~|~ALIGNMENT

CHECK (COMPLIMENTARY) ~|~ALIGNMENT CHECK ~|~94163 ALIGNMENT

CHECK ALIGNMENT WAS CHECKED AND TOE WAS FOUND TO BE OUT. 4

WHEEL ALIGNMENT PERFORMED

87876 MILES

DATE: 12/30/2016

REPAIR# 0260302

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~CAR WASH ~|~87876 CAR WASH

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~PERFORM

OIL CHANGE ~|~87876 PERFORM OIL CHANGE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~MPI.

~|~87876 MPI. CABIN AIR FILTER REPLACEMENT ENGINE AIR FILTER

REPLACEMENT [OTHER]: NO HISTORY OF 30K SERVICE [OTHER]: NO HISTORY

OF 60K SERVICE BRAKE FLUSH: NO HISTORY

SERVICE: PERFORM COMPLETE 4 WHEEL ALIGNMENT

DESCRIPTION: PERFORM COMPLETE 4 WHEEL ALIGNMENT ~|~ALIGNMENT

CHECK (COMPLIMENTARY) ~|~PERFORM 4 WHEEL ALIGMENT ~|~87876

PERFORM 4 WHEEL ALIGMENT

82971 MILES

DATE: 11/19/2016

REPAIR# 0258198

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~82971 30

PERFORMED LOF

SERVICE: MISC MAINT REPAIR

DESCRIPTION: MISC MAINT REPAIR ~|~CUSTOMER STATES THERE IS A LOT OF  
PLAY IN THE STEERING - ADVISE ~|~ ~|~82971 80 TEST DROVE VEHICLE.

VEHICLE IS STEERING AS DESIGNED AT THIS TIME. TIRES ARE CHOPPY AND  
FEATHERED. THIS COULD BE CAUSING THE CONCERN CUSTOMER IS

DESCRIBING.

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

~|~82971 PERFORMED MULTIPPOINT INSPECTION.

75818 MILES

DATE: 09/12/2016

REPAIR# 0254465

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~

SERVICE: INSTALL NEW FRONT BRAKE PADS AND RESURFACE BRAKE ROTORS

DESCRIPTION: INSTALL NEW FRONT BRAKE PADS AND RESURFACE BRAKE ROTORS ~|~INSTALL NEW FRONT BRAKE PADS AND RESURFACE BRAKE ROTORS - NOTED FROM PREVIOUS TIME IN. ~|~ ~|~75818 REPLACED FRONT BRAKE PADS, MACHINED ROTORS AND CLEANED AND LUBRICATED CALIPER SLIDES

SERVICE: NO INSPECTION NEEDED

DESCRIPTION: NO INSPECTION NEEDED ~|~NO INSPECTION NEEDED ~|~

SERVICE: STATE INSPECTION EMISSIONS

DESCRIPTION: STATE INSPECTION EMISSIONS ~|~STATE INSPECTION

EMISSIONS ~|~

75650 MILES

DATE: 09/10/2016

REPAIR# 0254436

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~CAR WASH ~|~75650 CAR WASH CAR WASH

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~OIL CHANGE

~|~75650 OIL CHANGE OIL CHANGED

SERVICE: MISC MAINT REPAIR

DESCRIPTION: MISC MAINT REPAIR ~|~CUSTOMER STATES STEERING WHEEL

SHAKES WHEN DRIVING - BALANCE TIRES ~|~CHECK TIRES / VIBES ~|~75650

CHECK TIRES / VIBES ALL ARE CUPPED ON EDGES...ESP INSIDE... SUGGEST

TIRES AND ALIGN

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION

~|~MULTI ~|~75650 MULTI MULTI PERFORMED

67947 MILES

DATE: 07/29/2016

REPAIR# 0252133

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~ ~|~67947 CAR WASH

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~67947

PERFORM OIL CHANGE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~  
~|~67947 MPI RECOMMEND ENGINE/CABIN FILTERS NAIL IN R/R TIRE NOT  
FIXABLE TO CLOSE TO THE SIDEWALL

SERVICE: ROTATE TIRES

DESCRIPTION: ROTATE TIRES ~|~ROTATE TIRES ~|~ ~|~67947 ROTATE TIRES  
NAIL IN R/R TIRE NOT FIXABLE TO CLOSE TO THE OUTER SIDEWALL  
59499 MILES

DATE: 05/14/2016

REPAIR# 0247768

REPORTED BY: Plaza Lexus

SERVICE: NO INSPECTION NEEDED

DESCRIPTION: NO INSPECTION NEEDED ~|~, ~|~

SERVICE: R/F TIRE LOSING AIR

DESCRIPTION: R/F TIRE LOSING AIR ~|~R/F TIRE LOSING AIR ~|~TIRE IS  
PUNCTURED ON THE OUTER TREAD PATTERN NEAR THE SIDE WALL ~|~59499  
TIRE IS PUNCTURED ON THE OUTER TREAD PATTERN NEAR THE SIDE WALL  
TIRE IS NOT REPAIRABLE DUE TO THE LOCATION OF THE PUNCTURE -- RF  
TIRE WILL NEED TO BE REPLACED 225/45R18

59184 MILES

DATE: 05/11/2016

REPAIR# 0247611

REPORTED BY: Plaza Lexus

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~  
SERVICE: N

DESCRIPTION: N ~|~COMPLIMENTARY CAR WASH ~|~

SERVICE: OIL AND FILTER - CHANGE

DESCRIPTION: OIL AND FILTER - CHANGE ~|~OIL AND FILTER - CHANGE ~|~  
~|~59184 OIL CHANGE COMPLETE

SERVICE: WHEELS - ROTATE

DESCRIPTION: WHEELS - ROTATE ~|~WHEELS - ROTATE ~|~ ~|~59184  
PERFORMED TIRE ROTATION

52708 MILES

DATE: 03/02/2016

REPAIR# 0243540

REPORTED BY: Plaza Lexus

SERVICE:

DESCRIPTION: BRAKE JOB - REAR (REPLACE PADS/RESURFACE ROTORS): REAR BRAKE PADS ARE ~3MM AND WILL NEED TO BE REP ~|~BRAKE JOB - REAR (REPLACE PADS/RESURFACE ROTORS): REAR BRAKE PADS ARE ~3MM AND WILL NEED TO BE REPLACED SOON (274325998) ~|~ ~|~52708 411: REPLACED REAR BRAKE PADS AND RESURFACED REAR ROTORSBRAKE JOB - REAR (REPLACE PADS/RESURFACE ROTORS): REAR BRAKE PADS ARE ~3MM AND WILL NEED TO BE REP WINDSHIELD WIPER INSERTS REPLACEMENT: INSERTS ARE SHOWING SIGNS OF WEAR AND WILL NEED TO BE REPLAC ~|~ WINDSHIELD WIPER INSERTS REPLACEMENT: INSERTS ARE SHOWING SIGNS OF WEAR AND WILL NEED TO BE REPLACED SOON (274326182) ~|~ ~|~52708 308: REPLACED WIPER INSERTS WINDSHIELD WIPER INSERTS REPLACEMENT: INSERTS ARE SHOWING SIGNS OF WEAR AND WILL NEED TO BE REPLAC

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH ~|~

SERVICE: LOANER VEHICLE

DESCRIPTION: LOANER VEHICLE ~|~LOANER VEHICLE ~|~

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~52708 PERFORMED OIL CHANGE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~ ~|~52708 MADE RECOMMENDATIONS IN ASR PRO

SERVICE: ROTATE TIRES

DESCRIPTION: ROTATE TIRES ~|~TIRE ROTATION: TO ENSURE PROPER AND EVEN WEAR OF TIRES WHILE DRIVING (274326092) ~|~ ~|~52708 286: PERFORMED TIRE ROTATION

49203 MILES

DATE: 01/18/2016

REPAIR# 0241138

REPORTED BY: Plaza Lexus

SERVICE: BALANCE TIRES

DESCRIPTION: BALANCE TIRES ~|~CUSTOMER STATES, SHAKES AT HIGHWAY SPEEDS, HAS NEW TIRE, BALANCE THEM ~|~ ~|~49203 PERFORMED ROAD FORCE BALANCE, R/R TIRE IS OUT OF ROUND WITH HIGHLY EXCESSIVE ROAD

FORCE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

46689 MILES

DATE: 12/21/2015

REPAIR# 0239788

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY CAR WASH

DESCRIPTION: COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH

~|~

SERVICE: COMPLIMENTARY EXTERIOR CAR WASH

DESCRIPTION:

SERVICE: INSPECT AIR CLEANER FILTER

DESCRIPTION:

SERVICE: INSPECT AND ADJUST ALL FLUID LEVELS

DESCRIPTION:

SERVICE: INSPECT BODY PAINT AND CORROSION

DESCRIPTION:

SERVICE: INSPECT BRAKE LINES, HOSES AND CONNECTIONS

DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS

DESCRIPTION:

SERVICE: INSPECT ENGINE COOLANT LEVEL

DESCRIPTION:

SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER\ 'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT RACK AND PINION ASSEMBLY

DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE

DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS

DESCRIPTION:

SERVICE: INSPECT WIPER BLADES

DESCRIPTION:

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~  
SERVICE: REPLACE BATTERY(S) IN MASTER KEY

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 45,000 MILES

DESCRIPTION: SERVICE - 45,000 MILES ~|~SERVICE - 45,000 MILES ~|~45,000 MILE  
SERVICE ~|~46689 45,000 MILE SERVICE 45,000 MILE SERVICE W/O ROTATENEEDS  
NEW TIRES

SERVICE: TIGHTEN BODY AND CHASSIS MOUNTING NUTS AND BOLTS

DESCRIPTION:

40763 MILES

DATE: 10/06/2015

REPAIR# 0235404

REPORTED BY: Plaza Lexus

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~40763 LOF

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~  
~|~40763 MPI...499. AIR AND CABIN FILTERS SUGGESTED. TIRES AT 4/32

SERVICE: ROTATE TIRES

DESCRIPTION: ROTATE TIRES ~|~ROTATE TIRES ~|~ ~|~40763 ROTATED THE  
TIRES. THEY WILL NEED REPLACEMENT SOON AND ARE AT 4/32 TREAD  
32692 MILES

DATE: 07/09/2015

REPAIR# 0229945

REPORTED BY: Plaza Lexus

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~32690  
PERFORM LOF

SERVICE: MULTI POINT INSPECTION



DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~  
~|~32692 PEERFORM MULTIPPOINT INSP. CUST DECLINED 30K

SERVICE: ROTATE TIRES

DESCRIPTION: ROTATE TIRES ~|~ROTATE TIRES ~|~ ~|~32692 PERFORM TIRE  
ROTATION. TEST DROVE VEHICLE

SERVICE: TIRE - REPAIR

DESCRIPTION: TIRE - REPAIR ~|~CUSTOMER CONCERN OF LOW TIRE WARNING  
LIGHT ON ~|~FOUND 2 NAILS IN LF TIRE. BOTH REPAIRABLE ~|~32692 FOUND 2  
NAILS IN LF TIRE. BOTH REPAIRABLE REPAIRED LF TIRE AND INFLATED TO  
PROPER LEVEL

25025 MILES

DATE: 04/18/2015

REPAIR# 0224973

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY EXTERIOR CAR WASH

DESCRIPTION:

SERVICE: INSPECT AIR CLEANER FILTER

DESCRIPTION:

SERVICE: INSPECT AND ADJUST ALL FLUID LEVELS

DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER\ 'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE

DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS

DESCRIPTION:

SERVICE: INSPECT WIPER BLADES

DESCRIPTION:

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 25,000 MILES

DESCRIPTION: SERVICE - 25,000 MILES ~|~SERVICE - 25,000 MILES ~|~

SERVICE: TIGHTEN BODY AND CHASSIS MOUNTING NUTS AND BOLTS

DESCRIPTION:

19514 MILES

DATE: 03/16/2015

REPAIR# 0223041

REPORTED BY: Plaza Lexus

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~ ~|~19514 OIL CHANGE COMPLETE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

SERVICE: ROTATE TIRES

DESCRIPTION: ROTATE TIRES ~|~ROTATE TIRES ~|~ ~|~19514 PERFORMED TIRE ROTATION

11339 MILES

DATE: 12/19/2014

REPAIR# 0218294

REPORTED BY: Plaza Lexus

SERVICE: COMPLIMENTARY EXTERIOR CAR WASH

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER\ 'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT WIPER BLADES

DESCRIPTION:

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 10,000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL VEHICLES

DESCRIPTION: SERVICE - 10,000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL VEHICLES ~|~SERVICE - 10,000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL VEHICLES ~|~. ~|~11339 PERFORMED 10K SERVICE 9342 MILES

**DATE:** 11/15/2014

REPAIR# 0216781

REPORTED BY: Plaza Lexus

SERVICE: FLAT REAPIR

DESCRIPTION: FLAT REAPIR ~|~LEFT REAR TIRE WENT FLAT, CUSTOMER PUT FIX A FLAT IN TIRE. REPAIR AS NEEDED ~|~GLASS IN CENTER OF TIRE TREAD AREA. ~|~9342 GLASS IN CENTER OF TIRE TREAD AREA. FOUND HOLE IN CENTER OF TIRE TREAD. REMOVED TIRE FROM WHEEL AND CLEANED FIX-AFLAT FROM TIRE SO THAT IT COULD BE INSPECTED. FOUND PIECE OF GLASS STUCK IN TIRE. REMOVED GLASS, AND INSPECTED TIRE FOR DAMAGE. TIRE HAS

5861 MILES

**DATE:** 10/04/2014

REPAIR# 0214436

REPORTED BY: Plaza Lexus

SERVICE: 5,000 MILE LIGHT SERVICE

DESCRIPTION: 5,000 MILE LIGHT SERVICE ~|~5,000 MILE LIGHT SERVICE ~|~5K MAINTENANCE ~|~5861 PERFORMED 5000 MILE MAINTENANCE SERVICE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~NONE

10 MILES

**DATE:** 01/24/2014

REPAIR# 0199520

REPORTED BY: Plaza Lexus

SERVICE: PERFORM PRE DELIVERY INSPECTION

DESCRIPTION: PERFORM PRE DELIVERY INSPECTION ~|~PERFORM PRE  
DELIVERY INSPECTION ~|~PDI ~|~10 PDI PERFORMED PDI.