47276 MILES

DATE: 08/19/2017 REPAIR# 0497826 REPORTED BY:

SERVICE: UCD DETAIL

DESCRIPTION: UCD DETAIL ~ | ~ USED CAR FULL DETAIL DERRICK ~ | ~ REQUESTED, 4.0 PET

HAIR ~ | ~ COMPLETE DERRICK

47276 MILES **DATE:** 08/15/2017 REPAIR# 0497372 REPORTED BY:

SERVICE: BODY CONCERN

DESCRIPTION: BODY CONCERN ~ | ~ REQUEST ORDER NEW FLOORMATS ~ | ~ FLOOR MATS HAVE EXCESSIVE STAINS SEVERELY DAMAGED MATS ~ | ~ REPLACED FLOOR MATS N/C LABOR

SERVICE: BODY MISC

DESCRIPTION: BODY MISC ~ | ~ REQUEST REPLACE FRONT LICENSE PLATE BRACKET HOLES DRILLED IN FASCIA ~ | ~ NO FRONT LP BRACKET ON VEHICLE REQUEST INSTALL

~|~INSTALLED FRONT LP BRACKET

SERVICE: ELECTRICAL

DESCRIPTION: ELECTRICAL ~|~REQUEST REPLACE BATTERY ~|~BATTERY FAILED LOAD TEST ~|~REPLACED BATTERY

SERVICE: ENGINE AIR FILTER

DESCRIPTION: ENGINE AIR FILTER ~|~INSPECT AND/OR REPLACE ENGINE AIR FILTER (RECOMMENDED @ 30K) ~|~PER RECOMMENDATION OR REQUEST ~|~COMPLETE

SERVICE: FRONT/REAR AXLE

DESCRIPTION: FRONT/REAR AXLE ~|~REQUEST REMOVE LOCKING LUG NUTS ~|~NO KEY FOR LOCKING LUG NUTS, HAD TO REMOVE WITHOUT KEY ~|~REMOVED LOCKING LUG NUTS AND INSTALLED REGULAR LUG NUTS

SERVICE: FUEL INDUCTION CLEAN

DESCRIPTION: FUEL INDUCTION CLEAN ~|~PERFORM INTAKE CLEANING SERVICE AS REQUIRED TO MAINTAIN INTAKE VALVES (90.30 + 49.65) ~|~RECOMMENDED EVERY 15K MILES ~|~PERFORM SERVICE AND ROAD TEST

SERVICE: POLLEN AIR FILTER

DESCRIPTION: POLLEN AIR FILTER ~ | ~ INSPECT POLLEN AIR FILTER ~ | ~ AIR FILTER DIRTY ~ | ~ REPLACE POLLEN AIR FILTER(LOCATED BEHIND GLOVE BOX)

SERVICE: REPLACE (?)TIRES

DESCRIPTION: REPLACE (?)TIRES ~|~REPLACE 1 OR MORE TIRES (PLEASE SPECIFY BELOW) BOTH REAR ~|~REAR TIRES WORN TO 3/32 ~|~COMPLETED TIRE REPLACEMENT

SERVICE: RR PADS MACHINE RTRS

DESCRIPTION: RR PADS MACHINE RTRS ~ | ~ REPLACE REAR PADS/MACHINE ROTORS PER REQUEST/RECOMMENDATION NOTES: ~ | ~ REAR PADS WORN TO 5MM, REQUEST REPLACE ~ | ~ COMPLETED / PLEASE MAKE ANY NOTES BELOW

SERVICE: USED CAR INSPECTION

DESCRIPTION: USED CAR INSPECTION ~ | ~ (?) COMPLETE (YES PLAN) USED CAR INSPECTION ~ | ~ TIRES: LF 8, RF 8, LR 3, RR 3 BRAKES: LF 7/6, RF 6/7, LR 6/5, RR 5/6 ~ | ~ COMPLETE

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~ | ~ PERFORM 2 OR 4 WHEEL ALIGNMENT PER SPECS ~ | ~ PERFORMED 4 WHEEL ALIGNMENT REPLACED 2 TIRES ~ | ~ PERFORMED 4 WHEEL

ALIGNMENT

SERVICE: WIPER INSERTS

DESCRIPTION: WIPER INSERTS ~ | ~ CUSTOMER REQUESTS: WIPER INSERTS TO BE REPLACED ~ | ~ WIPER INSERTS DAMAGED FROM WEATHER ~ | ~ INSTALLED WIPER INSERTS

22127 MILES **DATE:** 01/05/2016 REPAIR# 0882151

REPORTED BY: Lexus of Palm Beach

SERVICE:

DESCRIPTION: CHANGE OIL AND FILTER, TOP ALL FLUIDS, AND RESET MAINT REQUIRED LIGHT IF APPLICABLE. ~|~CHANGE OIL AND FILTER, TOP ALL FLUIDS, AND RESET MAINT REQUIRED LIGHT IF APPLICABLE. ~|~~|~22127 30 OIL AND FILTER CHANGE

COMPLETED.CHANGE OIL AND FILTER, TOP ALL FLUIDS, AND RESET MAINT REQUIRED LIGHT IF APPLICABLE.

SERVICE: CUSTOMER REQUESTS TO HAVE THE MULTI-POINT INSPECTION PERFORMED ON THIS VISIT.

DESCRIPTION: CUSTOMER REQUESTS TO HAVE THE MULTI-POINT INSPECTION PERFORMED ON THIS VISIT. ~|~CUSTOMER REQUESTS TO HAVE THE MULTI-POINT INSPECTION PERFORMED ON THIS VISIT. ~|~~|~22127 MULTI-POINT INSPECTION COMPLETED.

SERVICE: INDICATES BRAKE LININGS ARE IN GOOD CONDITION.

DESCRIPTION:

SERVICE: INDICATES TIRES ARE IN GOOD CONDITION.

DESCRIPTION:

SERVICE: ROTATE WHEELS

DESCRIPTION: ROTATE WHEELS ~ | ~ ROTATE WHEELS ~ | ~ ~ | ~ 22127 20 WHEEL ROTATION COMPLETED.

12780 MILES **DATE:** 06/24/2015 REPAIR# 0852788

KEI AIK# 0052700

REPORTED BY: Lexus of Palm Beach

SERVICE:

DESCRIPTION: THANK YOU FOR VISITING LEXUS OF PALM BEACH, WHERE 100% CUSTOMER SATISFACTION IS MY GOAL. PLEASE CA ~ | ~ THANK YOU FOR VISITING LEXUS OF PALM BEACH, WHERE 100% CUSTOMER SATISFACTION IS MY GOAL. PLEASE CALL ME DIRECTLY IF YOU HAVE ANY QUESTIONS OR CONCERNS. USMAN ATHAR (561) 656-5893. ~ | ~ THANK YOU FOR VISITING LEXUS OF PALM BEACH, WHERE 100% CUSTOMER SATISFACTION IS MY GOAL. PLEASE CA

SERVICE: CUSTOMER REQUESTS TO HAVE A MULTI-POINT INSPECTION PERFORMED

DESCRIPTION: CUSTOMER REQUESTS TO HAVE A MULTI-POINT INSPECTION PERFORMED

~ | ~ CUSTOMER REQUESTS TO HAVE A MULTI-POINT INSPECTION PERFORMED ~ | ~

SERVICE: INDICATES BRAKE LININGS ARE IN GOOD CONDITION.

DESCRIPTION:

SERVICE: INDICATES TIRES ARE IN GOOD CONDITION.

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER\'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT WIPER BLADES

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION.

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 10,000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL VEHICLES

DESCRIPTION: SERVICE - 10,000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL VEHICLES ~ | ~ SERVICE - 10.000 MILE COMPLIMENTARY SERVICE - SYNTHETIC OIL

VEHICLES ~ | ~ MT ~ | ~ 12780 SERVICE 10K 00110F 50 PERFORMED 10K SERVICE.CH

5339 MILES

DATE: 12/08/2014

REPAIR# 0820717

REPORTED BY: Lexus of Palm Beach SERVICE: 5,000 MILE LIGHT SERVICE

DESCRIPTION: 5,000 MILE LIGHT SERVICE ~ | ~5,000 MILE LIGHT SERVICE ~ | ~5X ~ | ~5339 00105L

30 PERFORMED 5KL BH

SERVICE: CUSTOMER REQUESTS TO HAVE THE MULTI-POINT INSPECTION PERFORMED

ON THIS VISIT.

DESCRIPTION: CUSTOMER REQUESTS TO HAVE THE MULTI-POINT INSPECTION

PERFORMED ON THIS VISIT. ~ | ~ CUSTOMER REQUESTS TO HAVE THE MULTI-POINT

INSPECTION PERFORMED ON THIS VISIT. ~ | ~

SERVICE: INDICATES BRAKE LININGS ARE IN GOOD CONDITION.

DESCRIPTION:

SERVICE: INDICATES TIRES ARE IN GOOD CONDITION.

DESCRIPTION:

15 MILES

DATE: 07/08/2014

REPAIR# 0799913

REPORTED BY: Lexus of Palm Beach

SERVICE: SPOT DELIVERY

DESCRIPTION: SPOT DELIVERY ~ | ~ SPOT DELIVERY ~ | ~

14 MILES

DATE: 07/03/2014 REPAIR# 0799223

REPORTED BY: Lexus of Palm Beach

SERVICE: INSTALL DOOR EDGE GUARDS & DOOR CUP GUARDS

DESCRIPTION: INSTALL DOOR EDGE GUARDS & DOOR CUP GUARDS ~ | ~ INSTALL DOOR

EDGE GUARDS & DOOR CUP GUARDS ~ | ~ ~ | ~ 6 DEG 50

SERVICE: NEW CAR DETAIL AND APPLY APPEARANCE PACKAGE

DESCRIPTION: NEW CAR DETAIL AND APPLY APPEARANCE PACKAGE ~ | ~ NEW CAR

DETAIL AND APPLY APPEARANCE PACKAGE ~ | ~ ~ | ~6 DETN 200

SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES ~ | ~ PRE-DELIVERY

SERVICE FOR USA ALL ALTITUDES ~ | ~ ~ | ~14 001013 200 PDS