

25084 MILES

**DATE:** 09/06/2016

REPAIR# 0876087

REPORTED BY: Northtown Lexus

SERVICE:

DESCRIPTION: AS PART OF YOUR SERVICE APPOINTMENT, WE PERFORMED THE NORTHTOWN "N-TIRE CHECK." IT SHOWED 5/32 T ~|~PERFORM FREE 27 POINT CHECK ON VEHICLE ~|~AS PART OF YOUR SERVICE APPOINTMENT, WE PERFORMED THE

NORTHTOWN "N-TIRE CHECK." IT SHOWED 5/32 TYOUR BRAKES PADS HAVE 6MM - 4MM OF STOPPING MATERIAL. THEY MAY NEED ATTENTION AT THIS TIME OR BY N

SERVICE: NEW YORK STATE INSPECTION WITH LOW ENHANCED EMISSIONS TEST

DESCRIPTION: NEW YORK STATE INSPECTION WITH LOW ENHANCED EMISSIONS TEST

~|~CUSTOMER REQUESTS NEW YORK STATE SAFETY & EMISSION INSPECTION ~|~

SERVICE: PERFORM GOLD PACKAGE DETAIL

DESCRIPTION: PERFORM GOLD PACKAGE DETAIL ~|~CUSTOMER REQUESTS GOLD PACKAGE DETAIL ~|~

SERVICE: ROTATE TIRES & SET ALL AIR PRESSURES TO FACTORY SPECS

DESCRIPTION: ROTATE TIRES & SET ALL AIR PRESSURES TO FACTORY SPECS ~|~CUSTOMER REQUESTS TIRE ROTATION AND AIR PRESSURES SET ~|~

21082 MILES

**DATE:** 06/29/2016

REPAIR# 0871994

REPORTED BY: Northtown Lexus

SERVICE:

DESCRIPTION: PERFORM FREE 28 POINT LEXUS SAFETY CHECK-NO ADDITIONAL CONCERNS FOUND AT THIS TIME/RECOMMEND 25,00 ~|~CUSTOMER REQUEST FREE 28

POINT VEHICLE INSPECTION ~|~PERFORM FREE 28 POINT LEXUS SAFETY CHECK-NO ADDITIONAL CONCERNS FOUND AT THIS TIME/RECOMMEND 25,00AS PART OF YOUR SERVICE APPOINTMENT, WE PERFORMED THE NORTHTOWN "N-TIRE CHECK." IT SHOWED 6/32 ~|~PROVIDE COURTESY INSPECTION OF TIRES AND BRAKES ~|~AS PART OF YOUR SERVICE APPOINTMENT, WE PERFORMED THE NORTHTOWN "N-TIRE CHECK." IT SHOWED 6/32

SERVICE: BATTERY

DESCRIPTION: BATTERY ~|~CUSTOMER REQUESTS BATTERY REPLACEMENT. CUSTOMER STATES BATTER KEEPS DYING ~|~BATTERY FAILED LOAD TEST ~|~21081 REPLACE BATTERY & CHECK CHARGING SYSTEM

SERVICE: BATTERY COMB: BATTERY

DESCRIPTION:

18533 MILES

**DATE:** 05/06/2016

REPAIR# 0868658

REPORTED BY: Northtown Lexus

SERVICE:

DESCRIPTION: PERFORMED ROAD FROCE AND SMART TRACK BALANCE OF ALL 4 TIRES AND SET TIRE PRESSURES ~|~PERFORMED ROAD FORCE AND SMART TRACK BALANCE OF ALL 4 TIRES AND SET TIRE PRESSURES TO ADDRESS PULLING AND/OR VIBRATION CONDITION ~|~

SERVICE: 4 WHEEL ALIGNMENT

DESCRIPTION: 4 WHEEL ALIGNMENT ~|~4 WHEEL ALIGNMENT ~|~

SERVICE: PERFORM SILVER DETAIL ON VEHICLE

DESCRIPTION: PERFORM SILVER DETAIL ON VEHICLE ~|~PERFORM SILVER DETAIL ON VEHICLE ~|~

SERVICE: SERVICE REMINDER LETTER

DESCRIPTION: PERFORMED ROAD FORCE AND SMART TRACK BALANCE OF ALL 4 TIRES AND SET TIRE PRESSURES

199 MILES

**DATE:** 10/08/2014

REPAIR# 0833144

REPORTED BY: Northtown Lexus

SERVICE: INSTALL FILM ON DOOR CUPS & DOOR EDGES ON LEFT SIDE

DESCRIPTION: INSTALL FILM ON DOOR CUPS & DOOR EDGES ON LEFT SIDE ~|~INSTALL FILM ON DOOR HANDLES & DOOR EDGES ON LEFT SIDE ~|~

7 MILES

**DATE:** 09/11/2014

REPAIR# 0831253

REPORTED BY: Northtown Lexus

SERVICE: PERFORMED NEW YORK STATE SAFETY INSPECTION/STICKEWR#11987073

DESCRIPTION: PERFORMED NEW YORK STATE SAFETY INSPECTION/STICKEWR#11987073 ~|~CUSTOMER REQUESTS NEW YORK STATE SAFETY INSPECTION ONLY ~|~

2 MILES

**DATE:** 09/11/2014

REPAIR# 0831250

REPORTED BY: Northtown Lexus

SERVICE:

DESCRIPTION: DETAIL VEHICLE THAT WAS PREVIOUSLY DETAILED FOR THE LOT TO GET READY FOR DELIVERY ~|~DETAIL VEHICLE THAT WAS PREVIOUSLY DETAILED FOR THE LOT TO GET READY FOR DELIVERY ~|~DETAIL VEHICLE THAT WAS PREVIOUSLY DETAILED FOR THE LOT TO GET READY FOR DELIVERY

2 MILES

**DATE:** 08/05/2014

REPAIR# 0828568

REPORTED BY: Northtown Lexus

SERVICE: DETAIL VEHICLE NOT PREVIOUSLY LOT DETAILED TO GET READY FOR CUSTOMER DELIVERY

DESCRIPTION: DETAIL VEHICLE NOT PREVIOUSLY LOT DETAILED TO GET READY FOR CUSTOMER DELIVERY ~|~DETAIL VEHICLE NOT PREVIOUSLY LOT DETAILED TO GET READY FOR CUSTOMER DELIVERY ~|~

SERVICE: INSTALL BODY SIDE MOLDINGS

DESCRIPTION: INSTALL BODY SIDE MOLDINGS ~|~INSTALL BODY SIDE MOLDINGS ~|~

2 MILES

**DATE:** 07/24/2014

REPAIR# 0827660

REPORTED BY: Northtown Lexus

SERVICE: INSTALL PAINT FILM ON HOOD, FENDERS, MIRRORS, DOOR HANDLE POCKETS AND DOOR EDGES

DESCRIPTION: INSTALL PAINT FILM ON HOOD, FENDERS, MIRRORS, DOOR HANDLE POCKETS AND DOOR EDGES ~|~APPLY CLEAR PAINT PROTECTION FILM ~|~

10 MILES

**DATE:** 02/18/2014

REPAIR# 0073337

REPORTED BY: Prestige Lexus

SERVICE: PERFORM PDI SERVICE FOR USA DELIVERY

DESCRIPTION: PERFORM PDI SERVICE FOR USA DELIVERY ~|~PERFORM PDI SERVICE FOR USA DELIVERY ~|~. ~|~2 PDI FOR DELIVERY INSPECTED WHEEL PRESENCE AND FIT