


1998 Lexus GS 400

Fig. 4: Identifying Engine Room No. 1 Relay Block Fuses & Relays
 Courtesy of TOYOTA MOTOR SALES, U.S.A., INC.



G00157936