white / 2007 GS350

Service History for VIN: JTHBE96S370017357

Sort By:

SERVICE TYPE	DATE	SERVICE PROVIDER	R MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	03/05/2015	Bell Lexus North Scottsdale	58579	0355805	BUYERS INSPECTION - BUYERS INSPECTION OF VEHICLE INCLUDES INSPECTION OF THE FOLLOWING AREAS: - CARFAX REPORT - VEHICLE HEALTH REPORT - VISUAL INSPECTION OF COOLING SYSTEM, STEERING, SUSPENSION, ENGINE, TRANSMISSION, BRAKES, TIRES, FUEL LINES, LIGHTS, HORN, BELTS, AND WINDOW - SEE YOUR SERVICE REPRESENTITIVE FOR INSPECTION RESULTS
Dealer Reported	07/28/2014	Bell Lexus North Scottsdale	55253	0333630	55000 MILE SERVICE NON WARRANTY - NON OEM - PERFORM 55,000 MILE SERVICE. CHANGE ENGINE OIL AND FILTER. ROTATE TIRES,SET TIRE PRESSURE INCLUDING SPARE. CHECK CONDITION OF TIRES, MEASURE TREAD DEPTH CHECK ALL FLUID LEVES AND TOP OFF AS NEEDED. ADVISE ON CONDITION. SERVICE BATTERY, LOAD TEST, CLEAN CA - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 55,000 MILE SERVICE PERFORMED TIRES FR 7/32 REARS 5/32 BRAKES FR 8MM REARS 8MM
Dealer Reported	07/28/2014	Bell Lexus North Scottsdale	55253	0333630	LOANER CAR BLNS - BELL LEXUS NORTH SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS TAKEN. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$65.00 RENTAL FEE, PER DAY WILL BE ADDED TO YOUR INVOICE LOANER#
Dealer Reported	12/09/2013	Bell Lexus North Scottsdale	51352	0310974	DLG - SAFTEY RECALL - SAFETY RECALL DLG - INTAKE VVT ACTUATOR GEAR INSPECTION AND REPAIR REPLACE CAM GEARS
Dealer Reported	12/09/2013	Bell Lexus North Scottsdale	51352	0310974	
Dealer Reported	12/09/2013	Bell Lexus North Scottsdale	51352	0310974	FRONT/REAR BODY - CUSTOMER STATES THAT THERE IS A RATTLE IN THE DASH ALL THE TIME WHEN IT IS WARM WHEN PUSHING AGAINST THE INSTRUMENT CLUSTER COVER IT GOES AWAY PLEASE ADVISE - LACK OF INSULATION - INSULATED INSTRUMENT PANEL
Dealer Reported	12/09/2013	Bell Lexus North Scottsdale	51352	0310974	
Dealer Reported	12/09/2013	Bell Lexus North Scottsdale	51352	0310974	NON WARRANTABLE OPERATION CODE - CUSTOMER STATES THAT MAINTENANCE LIGHT IS COMING ON - RESET
					50000 MILE SERVICE NON WARRANTY - NON OEM - PERFORM 50,000 MILE SERVICE. CHANGE OIL AND OIL FILTER

Dealer Reported	08/20/2013	Bell Lexus North Scottsdale	49271	0301728	ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS ALIGNMENT WEAR. CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVELS AND CABLE ENDS. CHECK POWER STEERING FLUID - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 50,000 MILE SERVICE PERFORMED TIRES 8/32 R/F 6/32 BRAKES FR 8MM REARS NEW TODAY
Dealer Reported	08/20/2013	Bell Lexus North Scottsdale	49271	0301728	FRONT/REAR BODY - CUSTOMER STATES THAT VEHICLE IS LEAKING WATER ONTO THE RIGHT FRONT FLOOR AND THE RIGHT REAR FLOOR IS WET AS WELL - EVAPORATOR DRAIN HAS BLOCKAGE - REMOVE DRAIN AND CLEARED BLOCKAGE
Dealer Reported	08/20/2013	Bell Lexus North Scottsdale	49271	0301728	NON WARRANTABLE OPERATION CODE - INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# - LOANER
Dealer Reported	08/20/2013	Bell Lexus North Scottsdale	49271	0301728	OTHERS - TECH NOTED AT TIME OF SERVICE THAT REAR BRAKES ARE AT 4MM - REPLACE REAR BRAKE PADS AND RESURFACED REAR ROTORS LUBE CALIPERS
					04 30,000 MILE SVC - PERFORM 30,000 MILE SERVICE. CHANGE OIL & FILTER.
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	LUBE ALL HINGES. INSPECT COOLING SYSTEM & TRANSMISSION FLUID. INSPECT EVAPORATIVE EMISSION SYSTEM & FUEL TANK CAP GASKET. CLEAN THROTTLE BODY AND ADD FUEL SYSTEM CLEANER. ROTATE TIRES & CHECK TIRE PRESSURE - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 30,000 MILE SERVICE PERFORMED TIRES FR 6 - 7/32 REARS 7/32 BRAKES FR NEW TODAY REARS 5MM
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	NON WARRANTABLE OPERATION CODE - REPLACE A/C AIR FILTER REPLACED A/C FILTER(S)
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	NON WARRANTABLE OPERATION CODE - INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# - LOANER
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	OTHERS - CUSTOMER FEELS VEHICLE HAS EXCESSIVE BRAKE DUST - FRONT BRAKES ARE AT 4MM - REPLACE FRONT BRAKE PADS AND RESURFACE FRONT BRAKE ROTORS LUBE CALIPERS
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	OTHERS - AT TIMES WHEN STARTING UP IT SEEMS TO HAV AN EXTENDED START IT MAKES A LOUD NOISE IT DOES NOT DO IT EVERY TIME CUSTOMER STATES - CAM GEARS MAKING NOISE - REPLACE CAM GEARS TSIB 0157 - 08
Dealer Reported	01/06/2012	Bell Lexus North Scottsdale	36667	0256362	FRONT/REAR BODY - RATTLE IN RIGHT FRONT DOOR IT HAPPENS ALL THE TIME IF YOU PUSH ON THE PANEL IT SEEMS TO GET ALITTLE LESS NOISEY -

-p					FOUND MISSING DOOR PANEL SCREW - REINSTALLED SCREW NOISE GONE
Dealer Reported	03/24/2011	Bell Lexus North Scottsdale	32037	0233447	INSPECT BATTERY CHARGE LEVEL - CUSTOMER REQUEST THAT BATTERY BE INSPECTED - BATTERY FAILED LOAD TEST - REPLACE BATTERY
Dealer Reported	03/24/2011	Bell Lexus North Scottsdale	32037	0233447	NON WARRANTABLE OPERATION CODE - INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# - LOANER
Dealer Reported	03/24/2011	Bell Lexus North Scottsdale	32037	0233447	FUEL PRES SNSR GSKT - PERFORM BLA CAMPAIGN - TIGHTENED FUEL PRESSURE SENSOR GASKET
Dealer Reported	12/29/2010	Bell Lexus North Scottsdale	30798	0226052	FRONT/REAR BODY - RIGHT MIRROR WILL NOT ADJUST CUSTOMER STATES - MIRROR ACTUATOR INTERNAL FAILURE - REPLACE RIGHT MIRROR ACTUATOR
Dealer Reported	12/09/2010	Bell Lexus North Scottsdale	30344	0224554	VALVE SPRINGS - PERFORM ALE CAMPAIGN - PERFORMED ALE CAMPAIGN
Dealer Reported	12/09/2010	Bell Lexus North Scottsdale	30344	0224554	FRONT/REAR BODY - CUSTOMER STATES THAT RIGHT MIRROR WILL NOT ADJUST BACK IN POSITION FROM REVERSE - ORDERED MIRROR ACTUATOR - WILL NOTIFY CUSTOMER WHEN PART ARRIVES
Dealer Reported	06/18/2010	Bell Lexus North Scottsdale	26805	0210241	SEE SECTION - REPLACE MISSING DRIVERS FLOOR A/C DUCT - REPLACE MISSING LEFT FRONT FLOOR DUCT
Dealer Reported	06/18/2010	Bell Lexus North Scottsdale	26805	0210241	FRONT/REAR BODY - CUSTOMER STATES THAT TRIM PIECE ON LEFT FRONT DOOR IS RATTLING - INSULATED TRIM BEHIND DRIVERS INNER DOOR HANDLE
Dealer Reported	06/07/2010	Bell Lexus North Scottsdale	26527	0209199	25000 MILE SERVICE NON WARRANTY - NON OEM - PERFORM 25,000 MILE SERVICE CHANGE OIL AND OIL FILTER ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS ALIGNMENT WEAR. CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVELS AND CABLE ENDS. CHECK POWER STEERING FLUID - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 25,000 MILE SERVICE PERFORMED TIRES 7/32 BRAKES FR 8MM REARS 7MM
Dealer Reported	06/07/2010	Bell Lexus North Scottsdale	26527	0209199	CERTIFIED PRE - OWNED 1ST OIL CHANGE - PERFORM CERTIFIED PRE - OWNED OIL CHANGE - COMPLETED
Dealer Reported	06/07/2010	Bell Lexus North Scottsdale	26527	0209199	MISC - CUSTOMER STATES THAT NO AIR IS COMING OUT OF REAR VENTS OR THE FLOOR VENT OR THE VENILATED SEATS. THERE IS A SMALL AMOUNT OF AIR FROM THE VERY FRONT OF THE SEAT - CENTER DUCT LOOSE AND NOT CONNECTED TO REAR DUCT - REMOVED NAV SYSTEM AND CENTER CONSOLE TO REPAIR DUCT WORK
Dealer Reported	06/07/2010	Bell Lexus North Scottsdale	26527	0209199	FRONT/REAR BODY - CUSTOMER STATES THE MIRROR ON LEFT SIDE IS RATTLING. IT DOES IT ALL THE TIME DRIVING DOWN THE ROAD - TECH TEST DROVE VEHICLE AND COULD NOT DUPLICATE CUSTOMER CONCERN, THE DIAGNOSTIC SPECIALIST TEST DROVE

					VEHICLE AND COULD HEAR NO ABNORMAL NOISE - CUSTOMER WILL DEMONSTRATE NOISE TO DIAGNOSTIC SPECIALIST WHEN HE PICKS UP VEHICLE
Dealer Reported	06/07/2010	Bell Lexus North Scottsdale	26527	0209199	SEE SECTION - CUSTOMER STATES THAT THERE IS NO AIR BLOWING ON DRIVERS FLOOR - LEFT FLOOR DUCT IS MISSING - NEEDS LEFT FLOOR DUCT CUSTOMER HAS DECLINED REPAIR
Dealer Reported	02/19/2010	Bell Lexus North Scottsdale	22952	0199664	NON WARRANTABLE OPERATION CODE - INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# - LOANER
Dealer Reported	02/19/2010	Bell Lexus North Scottsdale	22952	0199664	FRONT/REAR BODY - LEFT MIRROR WILL NOT COME BACK UP TO POSITION AFTER BEING IN REVERSE CUSTOMER STATES - OPEN CIRCUIT IN MIRROR CONTROL MOTOR - REPLACE LEFT MIRROR
Dealer Reported	02/19/2010	<u>Bell Lexus North</u> <u>Scottsdale</u>	22952	0199664	DISTRIBUTOR/HDLIGHT/T. SGNL - LEFT FRONT HEADLAMP HAS WATER IN IT AND DOES NOT WORK CUSTOMER STATES - INSUFFICIENT SEALANT ON HEADLAMP LENS LETTING WATER IN THAT SHORTED BULB - REPLACE HEADLAMP ASSEMBLY AND HIGH BEAM BULB
Dealer Reported	02/15/2010	Bell Lexus North Scottsdale	22872	0199158	FRONT/REAR BODY - WHEN LEFT MIRROR TILTS DOWN WHEN IN REVERSE IT DOES NOT COME BACK UP THE TO SET POSITION CUSTOMER STATES - ORDERED LEFT MIRROR
Dealer Reported	02/15/2010	Bell Lexus North Scottsdale	22872	0199158	DISTRIBUTOR/HDLIGHT/T. SGNL - HEADLAMP HAS WATER IN IT AND IT WILL NOT LIGHT UP CUSTOMER STATES - ORDERED LEFT FRONT HEADLAMP
Dealer Reported	12/18/2009	Lexus of Tucson	22283	0152020	FRONT/REAR BODY - CLEAN HEAD LIGHTS
Dealer Reported	12/03/2009	Lexus of Tucson	22283	0151461	FRONT/REAR BODY - PREP & DYE WORK
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	CERTIFIED PRE - OWNED PDI - PRE - OWNED VEHICLE CERTIFICATION PRE - OWNED CERT IS DONE
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	NON WARRANTABLE OPERATION CODE - FULL DETAIL. 4.0
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	ACCESSORY - MATS
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	TIRE REPLACEMENT - REPL. 4 TIRES - REPLACE FOUR TIRES,MOUNT AND BALANCE
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	ACCESSORY - REPL. EXUST PIPE - REPLACED EXUST PIPE
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	FRONT/REAR BODY - WHEEL LOCK KEY MISSING/#59
Dealer Reported	11/27/2009	Lexus of Tucson	22283	0151070	FRONT/REAR BODY - PAINTLESS REPAIR
Dealer Reported	10/20/2009	Lexus of Tucson	21755	0150124	FRONT WHEEL ALIGNMENT - 2 - WHL ALIGNMENT - ALIGNMENT
Dealer Reported	08/19/2009	Lexus of Tucson	20180	0148393	18750 MILE SERVICE NON WARRANTY - OIL AND FILTER CHANGE, CHECK ALL FLUID LEVELS, ADJUST TIRE PRESSURES, CHECK BELTS, HOSES AND CLAMPS, CHECK AIR FILTER - SCHEDUII ED MAINTENANCE DUE TO

					TIME OR MILEAGE - 18750 MILE SERVICE COMPLETED
Dealer Reported	08/19/2009	Lexus of Tucson	20180	0148393	OTHERS - REPLACE FRONT BRAKE PADS DUE TO NORMAL WEAR - COMPETED
Dealer Reported	04/30/2009	Lexus of Tucson	17909	0144841	9LA FUEL PIPE REPL - PERFORM 9LA FUEL DELIVERY PIPE REPLACEMENT SSC - 9LA CAMPAIGN - PERFORMED 9LA SPECIAL SERVICE CAMPAIGN
Dealer Reported	03/10/2009	<u>Lexus of Tucson</u>	16461	0143105	15000 MILE SERVICE NON WARRANTY - CHANGE ENGINE OIL AND FILTER, DRAIN AND FILL TRANSMISSION FLUID, DRAIN AND FILL DIFFERENTIAL FUID (4X4 MODELS INCLUDE BOTH DIFFERENTIALS AND TRANSFER CASE FLUIDS), ROTATE AND BALANCE TIRES, REPLACE ENGINE AIR FILTER, BRAKE PAD INSP - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - PERFORMED A 15,000 MILE SERVICE; BRAKES MEASURED 8MM ON FRONT AND REAR. BATTERY TESTE GOOD. ALT OUTPUT134 AMPS.NO DRAW.
Dealer Reported	11/21/2008	Lexus of Tucson	14935	0139464	FRONT/REAR BODY - CK CUSTOMER CONCERN FOR RATTLE FROM DASH AREA - TSIB L - SB - 0040 - 08 - PERFORMED TSIB L - SB - 0040 - 08 OP#NV8040 T91/43 FP#55708 - 30100
Dealer Reported	09/13/2008	Lexus of Tucson	13050	0137352	11250 MILE SERVICE NON WARRANTY - OIL AND FILTER CHANGE, CHECK ALL FLUID LEVELS, ADJUST TIRE PRESSURE, CHECK BELTS, HOSES AND CLAMPS, CHECK AIR FILTER - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - PERFORMED 11250 SERVICE
Dealer Reported	06/30/2008	Lexus of Tucson	11181	0134923	BATTERY/COIL SPK PLUG - ENGINE WOULD NOT CRANK,WAS JUMP STARTED BY SHOP FOREMAN OE BATTERY - BATTERY HAD BEEN DEPLETED - RECHARGED BATTERY
Dealer Reported	01/10/2008	Lexus of Tucson	7663	0128777	7,500 MILE SERVICE - CHANGE ENGINE OIL AND FILTER, TIRE ROTATION, BRAKE PAD INSPECTION, ELECTRICAL SYSTEM CHECK, CHECK ALL FLUID LEVELS, ADJUST TIRES PRESSURES, CHECK BELTS, HOSES, AND CLAMPS. TEST DRIVE VEHICLE - 7500 MILE SERVICE COMPLETED FRONT BRAKES 8.4MM REAR 8.4MM
Dealer Reported	09/12/2007	Lexus of Tucson	4817	0124662	FRONT/REAR BODY - CK CUSTOMER CONCERN FOR FUEL DOOR NOT CLOSING - FOUND FUEL DOOR RELEASE SOLINOID STICKY - REPLACED FUEL DOOR LOCK ASSY FPN - 7703030160 OP# - 237991 T=99/13 .5
Dealer Reported	09/12/2007	Lexus of Tucson	4817	0124662	3,750 MILE SERVICE - CUSTOMER REQUESTS 3750 MILE SERVICE WARRANTY FIRST SERVICE POINT - SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE - 3750 MILE SERVICE COMPLETED.
Dealer Reported	03/02/2007	Lexus of Tucson	2	0118060	NON WARRANTABLE OPERATION CODE - WASH VEHICLE TO PREP FOR INVENTORY/DELIVERY CLEAN VEHICLE FOR NEW CAR PREP CLEAN FOR NEW CAR PREP.
Dealer Reported	02/28/2007	Lexus of Tucson	1	0117981	PRE - DELIVERY SERVICE FOR USA ALL ALTITUDES - PDI - COMPLETE
Dealer Reported	02/28/2007	Lexus of Tucson	1	0117981	NON WARRANTABLE OPERATION CODE - PUT ON PLATE FRAMES AND FILL WITH FUEL DONE

NON WARRANTABLE OPERATION CODE -WASH VEHICLE TO PREP FOR INVENTORY/DELIVERY. - CLEAN VEHICLE FOR NEW CAR PREP. - CLEAN FOR NEW CAR PREP.

## **Information Accuracy**

Information presented on this Web site is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus dealership that conducted the service and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind.

Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer

## **CPO Owner Information**

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site but will not be shared with future owners of the vehicle.

## **Owner-Reported Information and Privacy Terms**

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this Web site, please <u>click here</u>.