

2008 IS350

SERVICE HISTORY**SERVICE HISTORY FOR:** 2008 IS350**VIN:** JTHBE262485018206**66574 MILES****DATE:** 12/21/2015**REPAIR#** 1306342**REPORTED BY:** Park Place Lexus Plano**SERVICE:** IS350-BASIC SERVICE-70,000
MILE SERVICE**DESCRIPTION:** IS350-BASIC SERVICE-
70,000 MILE SERVICE ~|~IS350 70,000
SERVICE: 10000 MILE SERVICE:
REPLACE ENGINE OIL; REPLACE
ENGINE OIL FILTER; REPLACE DRAIN
PLUG GASKET; RESET MAINTENANCE
REMINDER LIGHT (IF APP); ROTATE,
INSPECT TIRES AND ADJUST AIR
PRESSURES; REPLACE SMART KEY
BATTERY; ADD WASHER SOLVENT CO
~|~ ~|~66574 100 PERFORMED 70,000
MILE SERVICE, NO ROTATED TIRES
ARE STAGGERED, PUT CORRECT TIRE
PRESSURE IN TIRES, RESET MAINT ON
CLUSTER, RESET MAINT ON NAV,
REPLACED MAINT STICKER, FILLED
OUT LOG BOOK, TIRES ARE DF 7/32 PF
7/32 DR 6/32 PR 7/32 FRONT BRAKES
AR**SERVICE:** OBD II PERFORM STATE
INSPECTION**DESCRIPTION:** OBD II PERFORM
STATE INSPECTION ~|~OBD II
PERFORM STATE INSPECTION ~|~
~|~66574 50 COMPLETED STATE
INSPECTION BOTH COPIES IN GLOVE
BOX**63842 MILES****DATE:** 07/15/2015**REPAIR#** 1264609

REPORTED BY: Park Place Lexus Plano

SERVICE: ELF-REPL FUEL PRESSURE

GASKE T-IS250,IS350,GS300,350,450H

DESCRIPTION: ELF-REPL FUEL

PRESSURE GASKE T-

IS250,IS350,GS300,350,450H ~|~CLIENT

STATES: PERFORM LEXUS ELF

CAMPAIGN ~|~ELF CAMPAIGN

~|~63842 AGGB7B 310 PERFORMED ELF

CAMPAIGN

SERVICE: IS350-BASIC SERVICE-65,000

MILE SERVICE

DESCRIPTION: IS350-BASIC SERVICE-

65,000 MILE SERVICE ~|~IS350 65,000

SERVICE: 5000 MILE SERVICE:

REPLACE ENGINE OIL; REPLACE

ENGINE OIL FILTER; REPLACE DRAIN

PLUG GASKET; RESET MAINTENANCE

REMINDER LIGHT (IF APP); ROTATE,

INSPECT TIRES AND ADJUST AIR

PRESSURES; ADD WASHER SOLVENT

CONCENTRATE; CHECK BATTERY

AND ~|~ ~|~63842 100 PERFORMED

SERVICE TIRES FR 7 RR 8 BRAKES

BOTH 7MM

SERVICE: REMOVE TINT FROM

GLASS AND RETINT WINDOW

DESCRIPTION: REMOVE TINT FROM

GLASS AND RETINT WINDOW

~|~CLIENT STATES: STRIP AND

RETINT PASSENGER SIDE FRONT

WINDOW (TINT IS PEELING) CLIENT

IS AWARE TINT WILL NOT MATCH ~|~

~|~63842 150 STRIPPED AND REINTED

RF WINDOW CLIENT WAS ADVISED

THAT TINT WAS NOT GOING TO

MATCH

59488 MILES

DATE: 12/18/2014

REPAIR# 1212621

REPORTED BY: Park Place Lexus Plano

SERVICE: ***FOUR WHEEL

ALIGNMENT SPECIAL***

DESCRIPTION: ***FOUR WHEEL

ALIGNMENT SPECIAL*** ~|~***FOUR

WHEEL ALIGNMENT SPECIAL*** ~|~

~|~59488 ALIGNMENT 180

SERVICE: ABSORBER, SHOCK/STRUT

(REAR) - REPLACE

DESCRIPTION: ABSORBER,

SHOCK/STRUT (REAR) - REPLACE

~|~ABSORBER, SHOCK/STRUT (REAR) -

REPLACE ~|~ ~|~59488 REAR SHOCKS

PERFORMED THE 4 WHEEL ALIGNMENT AFTER REPLACING THE REAR SHOCKS SET TO FACTORY SPECS TEST DROVE FOUND THE STEERING WHEEL IS STRAIGHT AND THERE IS NOP PULL PRESENT

290 REPLACED BOTH THE LEAKING REAR SHOCKS

SERVICE: IS350-BASIC SERVICE-60,000 MILE SERVICE

DESCRIPTION: IS350-BASIC SERVICE-60,000 MILE SERVICE ~|~IS350 60,000 SERVICE: 60000 MILE SERVICE: REPLACE ENGINE OIL; REPLACE ENGINE OIL FILTER; REPLACE DRAIN PLUG GASKET; RESET MAINTENANCE REMINDER LIGHT (IF APP); ROTATE, INSPECT TIRES AND ADJUST AIR PRESSURES; REPLACE ENGINE AIR FILTER; REPLACE AIR CONDITION ~|~ ~|~59488 60K STATE 12/15 560 PERFORMED THE 60K SERVICE CHANGED THE ENGINE OIL AND FILTER SET TIRE PRESSURE INSPECTED THE BRAKES REPLACED THE ENGINE AIR FILTER AND CABIN FILTER FLUSHED BRAKE FLUID REPLACED KEY BATTERY REPLACED ALL 6 SPARK PLUGS TIRES FRONT 9/

SERVICE: MOUNT AND BALANCE (1) TIRE

DESCRIPTION: MOUNT AND BALANCE (1) TIRE ~|~MOUNT AND BALANCE (1) TIRE 255/40/18 ~|~ ~|~59488 1 TIRE 50 MOUNT AND BALANCED 1 PASS REAR TIRE2R3ADAE4613 NEW DOT 2R3ADAE3714

SERVICE: OTHERS R&R

DESCRIPTION: OTHERS R&R ~|~BATTERY - REPLACE ~|~FAILED LOAD TEST ~|~59488 BATTERY 71/72 00544-MF240-575 190011 A 60 FOUND BATTERY FAILS LOAD TEST REMOVED AND REPLACED WITH A NEW ONE

SERVICE: PADS, BRAKE (REAR) -

REPLACE AND RESURFACE ROTORS OFF-VEHICLE
DESCRIPTION: PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~ ~|~59488 REAR BRAKES 200 REPLACED THE REAR PADS AND MACHINED THE REAR ROTORS

SERVICE: REPLACE BATTERY

DESCRIPTION: REPLACE BATTERY ~|~10/28/2011 RO#941877 --BATTERY REPLACED AT THIS DATE -- LINE FOR PRORATE ~|~

55335 MILES**DATE: 06/24/2014****REPAIR#** 1166229**REPORTED BY:** Park Place Lexus Plano**SERVICE:**

DESCRIPTION: FUEL INDUCTION SERVICE. REC. EVERY 30K SERVICE TO DECARBONISE ENGINE. NO HISTORY OF SERVICE. ~|~ ~|~,CUSTOMER DECLINED SERVICE -A FUEL INDUCTION SERVICE. REC. EVERY 30K SERVICE TO DECARBONISE ENGINE. NO HISTORY OF SERVICE.

SERVICE: FLUID, DIFFERENTIAL (REAR) - REPLACE. FLUID DIRTY.

DESCRIPTION: FLUID, DIFFERENTIAL (REAR) - REPLACE. FLUID DIRTY. ~|~ ~|~,CUSTOMER DECLINED SERVICE -A

SERVICE: MOUNT AND BALANCE (2) TIRES.

DESCRIPTION: MOUNT AND BALANCE (2) TIRES. ~|~BRIDGESTONE RE760'S 225/40/18 MOUNT AND

SERVICE: ***FOUR WHEEL ALIGNMENT SPECIAL***

DESCRIPTION: ***FOUR WHEEL ALIGNMENT SPECIAL*** ~|~CLIENT STATES: ***FOUR WHEEL ALIGNMENT SPECIAL*** ~|~ ~|~55335 FOUR WHEEL ALIGNMENT 180 COMPLETE FOUR WHEEL ALIGNMENT, ADJUSTED ALL TO LEXUS SPECS. TEST DROVE TO VERIFY NO ABNORMAL PULL AND STEERING WHEEL STRAIGHT.

SERVICE: IS350-BASIC SERVICE-55,000 MILE SERVICE

DESCRIPTION: IS350-BASIC SERVICE-55,000 MILE SERVICE ~|~IS350 55,000 SERVICE: 5000 MILE SERVICE: REPLACE ENGINE OIL; REPLACE ENGINE OIL FILTER; REPLACE DRAIN PLUG GASKET; RESET MAINTENANCE REMINDER LIGHT (IF APP); ROTATE, INSPECT TIRES AND ADJUST AIR PRESSURES; ADD WASHER SOLVENT CONCENTRATE; CHECK BATTERY AND ~|~ ~|~55335 55K 100 COMPLETE 55K SERVICE, BATTERY OK, FRONT AND REAR TIRES NEW, FRONT BRAKES AT 8MM, REAR 4MM, STATE INSP. EXPIRES 6/15..... REC. FIF, REC. REAR DIFF SERVICE. AT NEXT SERVICE.

SERVICE: OBD II (1996-2002) STATE INSPECT

DESCRIPTION: OBD II (1996-2002) STATE INSPECT ~|~CLIENT STATES: OBD II (1996-2002) STATE INSPECT ~|~

BALANCE (2) TIRES. ~|~ ~|~55335 FRONT TIRES AT 2/32 100 COMPLETE MOUNT AND BALANCE OF TWO NEW BRIDGESTONE POTENZA TIRES. DOT#S H4T7 DEM 4513 AND 4213 MOUNT AND BALANCE (2) TIRES. ~|~255/40/18 BRIDGESTONE RE760'S MOUNT AND BALANCE (2) TIRES. ~|~ ~|~55335 REAR TIRES AT 2/32 100 COMPLETE MOUNT AND BALANCE OF TWO NEW BRIDGESTONE POTENZA TIRES ON THE REAR. DOT#S 2R3A DAE 4913 AND 4613

~|~55335 OBD 50 COMPLETE OBD STATE INSP.

SERVICE: REPLACE WINDSHIELD WIPER INSERTS.

DESCRIPTION: REPLACE WINDSHIELD WIPER INSERTS. ~|~NEED TO REPLACE BOTH AFTER MARKET WIPER BLADES WITH NEW AFTER MARKET WIPER BLADES. INSERTS ARE TEARING. ~|~ ~|~55335 INSERTS TORN 20 REPLACED BOTH AFTER MARKET BLADES WITH NEW AFTER MARKET BLADES.

SERVICE: SEE NOTES.

DESCRIPTION: SEE NOTES. ~|~ ~|~,CUSTOMER DECLINED SERVICE -A

52190 MILES

DATE: 01/31/2014

REPAIR# 1131229

REPORTED BY: Park Place Lexus Plano

SERVICE: IS350-BASIC SERVICE-50,000 MILE SERVICE

DESCRIPTION: IS350-BASIC SERVICE-50,000 MILE SERVICE ~|~IS350 50,000 SERVICE: 10000 MILE SERVICE: REPLACE ENGINE OIL; REPLACE ENGINE OIL FILTER; REPLACE DRAIN PLUG GASKET; RESET MAINTENANCE REMINDER LIGHT (IF APP); ROTATE, INSPECT TIRES AND ADJUST AIR PRESSURES; REPLACE SMART KEY

SERVICE: MOUNT AND BALANCE (2) TIRES. REAR-4/32(NOTES)

DESCRIPTION: MOUNT AND BALANCE (2) TIRES. REAR-4/32(NOTES) ~|~ ~|~,CUSTOMER DECLINED SERVICE -A

BATTERY; ADD WASHER SOLVENT CO
 ~|~|~52190 50K CP 100 50K.BATTERY
 PASSED.BKFT-8,REAR-4MM.TIRES 4/32
 X 4,BALD TO FT INTERIOR.ST-
 06/2014.LG-GLOVEBOX..1522/DRT

SERVICE: REMOVE SERRATION
 PATTERN & INSTALL NEW WIPER
 ARM NUTS
DESCRIPTION: REMOVE SERRATION
 PATTERN & INSTALL NEW WIPER
 ARM NUTS ~|~CLIENT STATES: DLA
 CAMPAIGN---PERFORM WIPER ARM
 CAMPAIGN ~|~DLA CAMPAIGN
 ~|~DLA 3624AA 60 REMOVED
 SERRATION AND NUTS AS
 REQUIRED..1522/DRT

SERVICE: REPLACE CAMSHAFT
 TIMING GEAR ON IS
DESCRIPTION: REPLACE
 CAMSHAFT TIMING GEAR ON IS
 ~|~CLIENT STATES: PERFORM LEXUS
 DLG CAMPAIGN ~|~DLG ~|~52190 DLG
 3528HB 670 R&R CAM GEAR SET AS
 REQUIRED..1522/DRT

47241 MILES

DATE: 06/24/2013

REPAIR# 1078276

REPORTED BY: Park Place Lexus Plano

SERVICE: 50,000 MILE SERVICE ALL
 MODELS
DESCRIPTION: 50,000 MILE SERVICE
 ALL MODELS ~|~50,000 MILE SERVICE
 ALL MODELS ~|~|~47239 50,000 MILE
 SERVICE ALL MODELS 100 50,000 MILE
 SERVICE: CHANGE OIL AND FILTER,
 CHECK FLUIDS AND TIRE PRESSURE,
 RESET REMINDERS, STATE DUE 6/14.
 65

SERVICE: PADS AND ROTORS FRONT
 - REPLACE
DESCRIPTION: PADS AND ROTORS
 FRONT - REPLACE ~|~PADS AND
 ROTORS FRONT - REPLACE ~|~
 ~|~47241 PADS AND ROTORS FRONT -
 REPLACE 200 REPLACED FRONT
 BRAKE PADS AND ROTORS. 65

SERVICE: OBD II (1996-2002) STATE
 INSPECT
DESCRIPTION: OBD II (1996-2002)
 STATE INSPECT ~|~OBD II (1996-2002)
 STATE INSPECT ~|~|~47239 OBD II
 (1996-2002) STATE INSPECT 50 STATE
 INSPECTION COMPLETE. 65

SERVICE: REPLACE INTERNAL
 TRUNK RELEASE LEVER
DESCRIPTION: REPLACE INTERNAL
 TRUNK RELEASE LEVER ~|~DLB
 CAMPAIGN---PERFORM INTERNAL
 TRUNK RELEASE HANDLE
 CAMPAIGN ~|~SC ~|~47239 DLB
 CAMPAIGN---PERFORM INTERNAL

TRUNK RELEASE HANDLE
 CAMPAIGN 3611AA=0.3 30 REPLACE
 INTERNAL TRUNK RELEASE LEVER.
 65

SERVICE: WATER PUMP ASSY &/OR

GSKT

DESCRIPTION: WATER PUMP ASSY

&/OR GSKT ~|~PUMP, COOLANT -
 REPLACE ~|~LEAKING ~|~47241 PUMP,
 COOLANT - REPLACE T1=66, T2=40,
 161011=2.6, FPN-16100-39436 260 FOUND
 WATER PUMP LEAKING, REPLACED
 PUMP. 65

42885 MILES

DATE: 12/11/2012

REPAIR# 1034803

REPORTED BY: Park Place Lexus Plano

SERVICE: 04 & NEWER 6 CYL-

INTERMEDIATE-45,000 MILE SERVICE

DESCRIPTION: 04 & NEWER 6 CYL-

INTERMEDIATE-45,000 MILE SERVICE

~|~04 & NEWER 6 CYL 45,000 SERVICE:

45,000 MILE SERVICE ALL MODELS:
 REPLACE ENGINE OIL AND FILTER;
 ROTATE TIRES; REPLACE ENGINE AIR
 FILTER; REPLACE AIR CONDITIONER
 AIR FILTER; ROAD TEST VEHILCE;
 INSPECT BRAKES: LININGS,
 DISCS/DRUMS, LINES, HOSES;
 INSPECT STE ~|~ ~|~42885 45K SERVICE
 130 TIRES: FRONT- 6/32, LR-7/32,RR-6/32
 OF TREAD LEFT. BRAKES: FRONT AND
 REAR- APPROX. 5MM OF PAD LEFT.
 STATE INSPECTION EXPIRES- 6/2013.
 COMPLETED. 45K SERVICE, RESET
 MAINT. REMINDER, STAMPED
 SERVICE BOOK, AND PUT NEW
 MAINT. STICKER ON

SERVICE: OTHERS R&R

DESCRIPTION: OTHERS R&R

~|~CLIENT STATES: PASSENGER SIDE
 WINDSHIELD MOLDING WILL NOT
 STAY IN PLACE---SEE HISTORY
 ~|~DEFORMED RUBBER ~|~42885
 751991-1.0, T1-62, T2-12 100 FOUND
 TWO PIECES OF PASSENGER SIDE
 WINDSHIELD MOULDING BROKEN
 CAUSING PIECE TO NOT STAY IN
 PLACE. REPLACED PASSENGER SIDE
 WINDSHIELD MOULDING AND 5
 CLIPS FOR MOULDING. FP#
 MOULDING-75551-53020. FP# CLIPS-
 75545-53011

SERVICE: PARK PLACE LEXUS TO PERFORM MULTI-POINT COURTESY VEHICLE INSPECTION.
DESCRIPTION: PARK PLACE LEXUS TO PERFORM MULTI-POINT COURTESY VEHICLE INSPECTION.
 ~|~CLIENT STATES: PARK PLACE LEXUS TO PERFORM MULTI-POINT COURTESY VEHICLE INSPECTION.

SERVICE: REPLACE FRONT ROTORS AND FRONT BRAKE PADS
DESCRIPTION: REPLACE FRONT ROTORS AND FRONT BRAKE PADS ~|~
 ~|~ ~|~CUSTOMER DENIED SERVICE - A

SERVICE: WE NEED TO HOLD THIS OVER UNTILL TOMORROW. THANKS!
DESCRIPTION: WE NEED TO HOLD THIS OVER UNTILL TOMORROW. THANKS! ~|~ ~|~ ~|~CUSTOMER DENIED SERVICE - A

40085 MILES

DATE: 06/18/2012

REPAIR# 0993664
REPORTED BY: Park Place Lexus Plano

SERVICE: OBD II (1996-2002) STATE INSPECT
DESCRIPTION: OBD II (1996-2002) STATE INSPECT ~|~CLIENT STATES: OBD II (1996-2002) STATE INSPECT ~|~ ~|~40085 STATE INSPECTION DUE 5000 COMPLETED STATE INSPECTION

37754 MILES

DATE: 02/27/2012

REPAIR# 0968580
REPORTED BY: Park Place Lexus Plano

SERVICE: 04 && NEWER 6 CYL-MINOR-40,000 MILE SERVICE

SERVICE: CLIENT REQUESTS PARK PLACE LEXUS TO PERFORM MULTI-

DESCRIPTION: 04 && NEWER 6 CYL-MINOR-40,000 MILE SERVICE ~|~04 && NEWER 6 CYL 40,000 SERVICE: 40,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSPECT STEERING LINK ~|~ ~|~37754 40K SERVICE CP 100 TIRES: FRONT AND REAR-6/32 OF TREAD LEFT. BRAKES: FRONT AND REAR APPROX. 6MM OF PAD LEFT. STATE INSPECTION EXPIRES-6/2012. CHANGED ENGINE OIL AND OIL FILTER, CHECKED ALL FLUID LEVELS AND TIRE PRESSURES, RESET REMINDER, AND STAMPED

SERVICE: REPLACE WINDSHIELD WIPER INSERTS.

DESCRIPTION: REPLACE WINDSHIELD WIPER INSERTS. ~|~REPLACE WINDSHIELD WIPER INSERTS. ~|~ ~|~37754 REPLACE WIPER BLADES. CP 20 WIPER INSERTS WOULD NOT FIT AFTERMARKET WIPER BLADES. RECOMMENDED RERPLACING WIPER BLADES. REPLACED WIPER BLADES PER CLIENT REQUEST.

POINT COURTESY VEHICLE INSPECT
DESCRIPTION: CLIENT REQUESTS PARK PLACE LEXUS TO PERFORM MULTI-POINT COURTESY VEHICLE INSPECT ~|~CLIENT STATES: CLIENT REQUESTS PARK PLACE LEXUS TO PERFORM MULTI-POINT COURTESY VEHICLE INSPECTION.

SERVICE: WNDSHIELD OUTSD MOULDING-ALL

DESCRIPTION: WNDSHIELD OUTSD MOULDING-ALL ~|~CLIENT STATES: BOTH FRONT WINDSHIELD MOLDINGS ARE STARTING TO CRANK AT THE BOTTOM ~|~POOR APPEARANCE ~|~37754 WINDSHIELD MOULDINGS CRACKED. 751291-3.8,T1-67,T2-16 380 FOUND WINDSHIELD MOULDINGS TO BE CRACKING AND COMING APART. REPLACED WINDSHIELD MOULDINGS AND CLIPS. FP#'S MOULDINGS 75551-53020, 75552-53020, WINDSHIELD CLIPS-75545-53011.

36451 MILES

DATE: 11/14/2011

REPAIR# 0945755

REPORTED BY: Park Place Lexus Plano

SERVICE: BATTERY

SERVICE: COMB: BATTERY

DESCRIPTION: BATTERY

~|~BATTERY REPLACED ON 10-28-11
AT 35954 MILES ON RO #941877
(VEHICLE HAS TO BE JUMPSTARTED)
~|~FAILED LOAD TEST

SERVICE: LEXUS ROADSIDE

ASSISTANCE

DESCRIPTION: LEXUS ROADSIDE

ASSISTANCE ~|~LEXUS ROADSIDE
ASSISTANCE(JUMPSTART)INVOICE
#025691 CASE #11093227 ~|~JUMPSTART

DESCRIPTION:

SERVICE: Z=.20 HANDLING FEE

DESCRIPTION:

36421 MILES

DATE: 11/14/2011

REPAIR# 0945069

REPORTED BY: Park Place Lexus Plano

SERVICE: CLIENT REQUESTS PARK
PLACE LEXUS TO PERFORM MULTI-
POINT COURTESY VEHICLE INSPECT

DESCRIPTION: CLIENT REQUESTS
PARK PLACE LEXUS TO PERFORM
MULTI-POINT COURTESY VEHICLE
INSPECT ~|~CLIENT STATES: CLIENT
REQUESTS PARK PLACE LEXUS TO
PERFORM MULTI-POINT COURTESY
VEHICLE INSPECTION.

SERVICE: OTHERS R&R*

DESCRIPTION: OTHERS R&R*
~|~CLIENT STATES: C/S NO CRANK
NO START- SENT OUT RDS AND
COULD NOT START- BEING TOWED
IN- KEYS IN SCOTT'S OFFICE
~|~BROKEN ~|~36421 INTERNAL OPEN
IN STARTER RELAY T1-17;T2-71;
281991-.9 90 REPLACED OPEN STARTER
RELAY; FP#28300-28010

35954 MILES

DATE: 10/28/2011

REPAIR# 0941877

REPORTED BY: Park Place Lexus Plano

SERVICE: BATTERY

DESCRIPTION: BATTERY ~|~CLIENT
STATES:THAT THE VEHICLE HAD TO
BE JUMP STARTED ~|~FAILED

SERVICE: COMB: BATTERY

DESCRIPTION:

BATTERY ~|~35954 WEAK CELL T1-
71;T2-71; 190011-.3;A-.3 60 REPLACED
BATTERY; FAIL CODE AP30;
FP#ORIGINAL

33664 MILES**DATE: 06/03/2011****REPAIR#** 0908845**REPORTED BY:** Park Place Lexus Plano

SERVICE: 04 && NEWER 6 CYL-
MINOR-35,000 MILE SERVICE
DESCRIPTION: 04 && NEWER 6 CYL-
MINOR-35,000 MILE SERVICE ~|~04 &&
NEWER 6 CYL 35,000 SERVICE:
PERFORM 35,000 MILE SERVICE PER
LEXUS GUIDELINES.: REPLACE
ENGINE OIL AND FILTER; ROTATE
TIRES; INSPECT ENGINE AIR FILTER;
INSPECT AIR CONDITIONER AIR
FILTER; ROAD TEST VEHILCE;
INSPECT BRAKES: LININGS,
DISCS/DRUMS, LINES ~|~ ~|~33664
MAINT. 35K 100 COMPLETED. BRAKES:
6MM FRONT AND REAR. TIRES: 8/32
FRONT AND REAR. STATE EXP: NEW.

SERVICE: OBD II (1996-2002) STATE
INSPECT
DESCRIPTION: OBD II (1996-2002)
STATE INSPECT ~|~CLIENT STATES:
OBD II (1996-2002) STATE INSPECT ~|~
~|~33664 EXPIRED SI5 050 COMPLETED.

30855 MILES**DATE: 02/16/2011****REPAIR#** 0884950**REPORTED BY:** Park Place Lexus Plano

SERVICE: ALE REPL COMP SPRINGS
& LASH ADJUSTERS FOR IS 350
DESCRIPTION: ALE REPL COMP
SPRINGS & LASH ADJUSTERS FOR IS
350 ~|~ALE - CAMPAIGN ~|~ALE -
CAMPAIGN ~|~30855 CAMPAIGN

SERVICE: CLIENT STATES: MOUNT
AND BALANCE (2) TIRES. REPLACE
REAR TIRES WITH 760"S
DESCRIPTION: CLIENT STATES:
MOUNT AND BALANCE (2) TIRES.
REPLACE REAR TIRES WITH 760"S
~|~CLIENT STATES: MOUNT AND

0528FS-7.0 700 REPLACED VALVE
SPRINGS PER CAMPAIGN

BALANCE (2) TIRES. REPLACE REAR
TIRES WITH 760'S ~|~|~30853 WORN
100 MOUNT AND BALANCE 2 REAR
TIRES; DOT#2R3ADAE4510,2510

28694 MILES

DATE: 10/28/2010

REPAIR# 0864336

REPORTED BY: Park Place Lexus Plano

SERVICE: 04 & NEWER 6 CYL 30,000
SERVICE: 30,000 MILE SERVICE (2004 &
NEWER): REPLACE ENG
DESCRIPTION: 04 & NEWER 6 CYL
30,000 SERVICE: 30,000 MILE SERVICE
(2004 & NEWER): REPLACE ENG ~|~04
& NEWER 6 CYL 30,000 SERVICE: 30,000
MILE SERVICE (2004 & NEWER):
REPLACE ENGINE OIL AND FILTER;
ROTATE TIRES; REPLACE ENGINE AIR
FILTER; REPLACE AIR CONDITIONER
AIR FILTER; REPLACE BRAKE FLUID;
ROAD TEST VEHILCE; INSPECT
BRAKES: LININGS, DISCS/DRUMS, ~|~
~|~28694 30K MAINT 250 TIRES-FRONT
AT 9/32, REAR AT 4/32, BRAKES-FRONT
AT 8MM, REAR AT 6MM, STATE EXP 8-
11

27116 MILES

DATE: 08/27/2010

REPAIR# 0851921

REPORTED BY: Park Place Lexus Plano

SERVICE: 9LG REPL PEDAL PAD,
REFLASH, AWFM - IS MODELS ONLY
DESCRIPTION: 9LG REPL PEDAL
PAD, REFLASH, AWFM - IS MODELS
ONLY ~|~CLIENT STATES: PERFORM

SERVICE: CLIENT STATES: FOUR
WHEEL ALIGNMENT SPECIAL

DESCRIPTION: CLIENT STATES:
FOUR WHEEL ALIGNMENT SPECIAL
~|~CLIENT STATES: FOUR WHEEL

9LG RECALL - SSC 9LG - POTENTIAL FLOOR MAT INTERFERENCE WITH ACCELERATOR PEDAL ~|~CAMPAIGN ~|~27116 9LG 9915M5 120 COMPLETED 9LG

SERVICE: CLIENT STATES: MOUNT AND BALANCE (2) TIRES. USE 760"S
DESCRIPTION: CLIENT STATES: MOUNT AND BALANCE (2) TIRES. USE 760"S ~|~CLIENT STATES: MOUNT AND BALANCE (2) TIRES. USE 760"S ~|~ ~|~27116 TWO TIRES 100 COMPLETED INSTALLING TWO NEW TIRES, RE760'S

ALIGNMENT SPECIAL ~|~ ~|~27116 FWA 180 COMPLETED FWA SPECIAL

SERVICE: CLIENT STATES: OBD II (1996-2002) STATE INSPECT
DESCRIPTION: CLIENT STATES: OBD II (1996-2002) STATE INSPECT ~|~CLIENT STATES: OBD II (1996-2002) STATE INSPECT ~|~ ~|~27116 OBDII STATE INSP 50 COMPLETED STATE INSP

23631 MILES

DATE: 04/07/2010

REPAIR# 0822662

REPORTED BY: Park Place Lexus Plano

SERVICE: 04 & NEWER 6 CYL 25,000 SERVICE: PERFORM 25,000 MILE SERVICE PER LEXUS GUIDELINE
DESCRIPTION: 04 & NEWER 6 CYL 25,000 SERVICE: PERFORM 25,000 MILE SERVICE PER LEXUS GUIDELINE ~|~04 & NEWER 6 CYL 25,000 SERVICE: PERFORM 25,000 MILE SERVICE PER LEXUS GUIDELINES: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHI LCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, ~|~ ~|~23631 MAINT 100 COMPLETED 25K SERVICE. TIRES 7/32-FRONT; 6/32-REAR; FB NEW-; RB APPX 7MM; STATE EXP 9/10

SERVICE: RE-ATTACH SPOILER

SERVICE: CLIENT STATES: DETAIL CARS WAS EXTERIOR, WASH ENGINE, SHAMPOO INTERIOR AND TREAT
DESCRIPTION: CLIENT STATES: DETAIL CARS WAS EXTERIOR, WASH ENGINE, SHAMPOO INTERIOR AND TREAT ~|~CLIENT STATES: DETAIL CARS WAS EXTERIOR, WASH ENGINE, SHAMPOO INTERIOR AND TREAT LEATHER. ~|~ ~|~23631 340 FULL DETAILED

SERVICE: REPLACE FRONT BRAKE PADS (INCLUDES MACHINE ROTORS)

DESCRIPTION: RE-ATTACH SPOILER
 ~|~FRONT SPOILER IS LOOSE - CAN
 WE RE-ATTACH ~|~ ~|~23631 IMPACT
 DAMAGE 50 R&R LOWER FRONT
 BUMPER VALANCE. REPAIR BENT
 TABS AND REINSTALL.

DESCRIPTION: REPLACE FRONT
 BRAKE PADS (INCLUDES MACHINE
 ROTORS) ~|~REPLACE FRONT BRAKE
 PADS (INCLUDES MACHINE ROTORS)
 ~|~ ~|~23631 FRONT PADS WORN TO
 1MM TOTAL PAD 200 REPLACED
 FRONT PADS AND SHIMS. MACHINED
 ROTORS. LUBED CALIPERS.

18997 MILES

DATE: 10/12/2009

REPAIR# 0787909

REPORTED BY: Park Place Lexus Plano

SERVICE: PROGRAM KEYS

DESCRIPTION: PROGRAM KEYS

~|~C/S PLEASE GET A NEW KEY ~|~
 ~|~18997 MISSING CP 050
 PROGRAMMED REMOTE, AND SOP
 SHANK FOR CLIENT..1522/DT

4519 MILES

DATE: 07/10/2008

REPAIR# 0325575

REPORTED BY: Sterling McCall Lexus

SERVICE: 5,000 MILE SERVICE

DESCRIPTION: 5,000 MILE SERVICE

~|~5K FACTORY SERVICE (SEDANS
 EVERY 5,000 MILES) ~|~.

SERVICE: ADDITIONAL SERVICE
 REQUEST

DESCRIPTION: ADDITIONAL
 SERVICE REQUEST ~|~ADDITIONAL
 SERVICE REQUEST

7 MILES

DATE: 11/14/2007

REPAIR# 0290982

REPORTED BY: Sterling McCall Lexus

SERVICE: PRE-DELIVERY SERVICE

FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY

SERVICE FOR USA ALL ALTITUDES

~|~PRE-DELIVERY SERVICE FOR USA

ALL ALTITUDES ~|~PDI

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) (//www.lexus.com/privacy/online-statement).