2008 IS F

#### SERVICE HISTORY

SERVICE HISTORY FOR: 2008 IS F

### **VIN:** JTHBP262X85003350

#### 87732 MILES

87587 MILES

REPAIR# 0313864 REPORTED BY: Lexus of Arlington

SERVICE: DRIVER FRONT TIRE HAS SMALL RIM LEAK REC RESEALING RIM DESCRIPTION: DRIVER FRONT TIRE HAS SMALL RIM LEAK REC RESEALING RIM ~!~ ~!~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER SERVICE: QUOTE TIRE SENSOR FIT KIT ---LEAKING DESCRIPTION: QUOTE TIRE SENSOR FIT KIT ---LEAKING ~|~ ~|~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

DATE: 04/03/2017

DATE: 04/05/2017

**REPAIR#** 0313536 **REPORTED BY:** Lexus of Arlington

# SERVICE:

DESCRIPTION: CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT ~1~32 CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT \$45.00 PER DAY. ~1~ CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT

SERVICE: GLH-REPL PANEL AIRBAG MODULE DESCRIPTION: GLH-REPL PANEL AIRBAG MODULE ~|~PERFORM THE GLH SERVICE CAMPAIGN ~|~GLH SERVICE CAMPAIGN COMPLETED ~|~BGG23X(4.2)---PERFORM GLP--COMPLETED WARRANTY AUTHORIZATION # E3C99AD2

SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~

#### 82739 MILES

REPAIR# 0296013 REPORTED BY: Lexus of Arlington

SERVICE: DESCRIPTION: PADS, BRAKE (FRONT) - REPLACE (LESS THEN SERVICE: MICROFILTER - REPLACE DESCRIPTION: MICROFILTER - REPLACE ~|~~|~,CUSTOMER

https://secure.drivers.lexus.com/lexusdrivers/history?vehicleId=8...3350,8431561,2008,2008%20%20IS%20F&label=2008%20%20IS%20F&print=Y Page 1 of 9

# DAT

SERVICE: EFTERMARKET EXHAUST CAUSING TROUBLE CODES. DESCRIPTION: EFTERMARKET EXHAUST CAUSING TROUBLE CODES. ~I~CHECK ENGINE LIGHT ON //~I~~I~P0607--- DUE TO AFTERMARKET EXHAUST READINGS CAUSING ENGINE LIGHT

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~OIL AND FILTER -CHANGE ~ | ~ ~ | ~ PERFORM OIL CHANGE/PSI

#### DATE: 07/13/2016

.5MM ALMOST METAL ON METAL) QUOTE ROTORS AND SHIMS ~|~~|~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER PADS, BRAKE (FRONT) - REPLACE (LESS THEN .5MM ALMOST METAL ON METAL) QUOTE ROTORS AND SHIMS

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ LOF COMPLETE DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

**SERVICE:** PERFORM MULTI-POINT VEHICLE INSPECTION **DESCRIPTION:** PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~

~|~COMPLETE

#### 77588 MILES

DATE: 02/17/2016

REPAIR# 0286406 REPORTED BY: Lexus of Arlington

# SERVICE:

DESCRIPTION: CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT ~1~15J ~1~ CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~OIL AND FILTER -CHANGE ~ | ~ ~ | ~ LOF COMPLETE

SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~ ~|~COMPLETE

#### 75503 MILES

REPAIR# 0284280 REPORTED BY: Lexus of Arlington

# SERVICE:

DESCRIPTION: PROGRAMMED ALL SENSORS TO SECOND SETTING OF VEHICLE/// NO FAULTS FOUND AFTER PROGRAMING ~!~PROGRAM 4 NEW SENSOR TWO 2ND SET (HAS DIFF WHEEL, WINTER TIRES AND SENSORS) LABOR 1.0HR ~!~ ~!~PROGRAMMED SENSORS TO 2ND SET PROGRAMMED ALL SENSORS TO SECOND SETTING OF VEHICLE/// NO FAULTS FOUND AFTER PROGRAMING

#### 72554 MILES

REPAIR# 0280550 REPORTED BY: Lexus of Arlington **SERVICE:** MICROFILTER - REPLACE

**DESCRIPTION:** MICROFILTER - REPLACE ~|~ ~|~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

**SERVICE:** PADS, BRAKE (FRONT) - REPLACE (2MM) QUOTE ROTORS AND SHIMS

**DESCRIPTION:** PADS, BRAKE (FRONT) - REPLACE (2MM) QUOTE ROTORS AND SHIMS ~|~~|~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

DATE: 01/13/2016

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~OIL AND FILTER -CHANGE ~ | ~ ~ | ~ CHANGED OIL AND FILTER

# 70377 MILES

DATE: 10/06/2015

REPAIR# 0276965 REPORTED BY: Lexus of Arlington

### SERVICE:

DESCRIPTION: CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT ~|~08K ~|~ CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT

**SERVICE:** RECOMMENDED REPLACING DISPLAY UNIT **DESCRIPTION:** RECOMMENDED REPLACING DISPLAY UNIT

~|~GUEST STATES VEHICLES NAV UNIT IS NOT RESPONDING/// PLEASE CHECK AND ADVISE ~|~~|~FOUND OPEN CIRCUIT IN NAV DISPLAY UNIT

**SERVICE:** REPLACED DISPLAY UNIT ATHO#C195622 **DESCRIPTION:** REPLACED DISPLAY UNIT ATHO#C195622

~|~DISPLAY BAD , NAVIGATION - REPLACE (LABOR ONLY)~|~ ~|~NAV DISPLAY INOP REPLACED FAULTY NAV DISPLAY ( OP# 866101 ) SERVICE: BAR, REAR STABILIZER - ADD BUSHINGS // REPLACE DESCRIPTION: BAR, REAR STABILIZER - ADD BUSHINGS // REPLACE ~|~~|~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

**SERVICE:** REPLACED BOTH REAR LINKS// ALLSTATE TO PAY FOR NET 2196.36 ATHO# C195622

**DESCRIPTION:** REPLACED BOTH REAR LINKS// ALLSTATE TO PAY FOR NET 2196.36 ATHO# C195622 ~|~LINKS, STABILIZER REAR (BOTH LINKS) ~|~~|~REPLACED REAR STAB BAR LINKS (BOTH SIDES )

#### 67333 MILES

REPAIR# 0270852 REPORTED BY: Lexus of Arlington

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ LOF COMPLETE

# 62909 MILES

REPAIR# 0266830 REPORTED BY: Lexus of Arlington

SERVICE: ELF-REPL FUEL PRESSURE GASKE T-IS F,GS460,LS460,LS600H DESCRIPTION: ELF-REPL FUEL PRESSURE GASKE T-IS F,GS460,LS460,LS600H ~|~SAFETY RECALL ELF - REMEDY NOTICE -VARIOUS MODELS - POTENTIAL FUEL PRESSURE SENSOR LEAK. ~|~ELF COMPLETE ~|~ELF AGGB7B ELF RECALL COMPLETED ( REPLACED FUEL PRESSURE SENSOR GASKET ) SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~ ~|~INSPECTION COMPLETE

DATE: 04/08/2015

DATE: 06/17/2015

62181 MILES

DATE: 03/28/2015

DATE: 01/03/2015

REPAIR# 0266221 REPORTED BY: Lexus of Arlington

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ CHANGED OIL AND FILTER. SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~

~|~PERFORMED INSPECTION.

#### **57130 MILES**

REPAIR# 0261350 REPORTED BY: Lexus of Arlington

# SERVICE:

**DESCRIPTION:** CUSTOMER PROVIDED LEXUS LOANER

VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT ~1~CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT \$45.00 PER DAY. ~1~ CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT ~1~CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT \$45.00 PER DAY. ~1~ CUSTOMER PROVIDED LEXUS LOANER VEHICLE AT N/C: VALUE ADDED AMENITY PROVIDED BY ARLINGTON LEXUS AT

SERVICE: FOUND DRIVE BELT OK AT THIS TIME DESCRIPTION: FOUND DRIVE BELT OK AT THIS TIME ~|~BELT, DRIVE - REPLACE ~|~~|~DID NOT REPLACE

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ CHANGED OIL AND FILTER

#### **SERVICE:** ELE-INSP FAN/REPL SCREWS

**DESCRIPTION:** ELE-INSP FAN/REPL SCREWS ~ | ~LIMITED

SERVICE CAMPAIGN (LSC) ELE - CERTAIN 2008 - 2012 MODEL YEAR IS F VEHICLES - ENGINE COOLING FANS. ~|~PERFORMED SC AGGB3A ~|~AGGB3A INSPECT AND REPLACE THE COOLING FAN MOTOR SCREWS (INSPECTION PASS)

SERVICE: FOUND RESIDUAL COOLANT FROM LAST WATER PUMP REPLACEMENT

**DESCRIPTION:** FOUND RESIDUAL COOLANT FROM LAST WATER PUMP REPLACEMENT ~|~PUMP, COOLANT - REPLACE, WATER PUMP LEAKING ~|~. ~|~DID NOT REPLACE WATER PUMP. RESIDUAL COOLANT FROM LAST TIME IT WAS LEAKING

# SERVICE: OTHER INSPECTION

**DESCRIPTION:** OTHER INSPECTION ~1~SAFETY RECALL ELF (E2F) - INTERIM NOTICE - VARIOUS MODELS - POTENTIAL FUEL PRESSURE SENSOR LEAK. ~1~~1~NO REMEDY YET

#### DATE: 09/24/2014

# 52455 MILES

REPAIR# 0256064 REPORTED BY: Lexus of Arlington

# SERVICE:

DESCRIPTION: REPLACED LEAKING WATER PUMP, ALLSTATE EXT WARRANTY NET \$660.08 DED \$100 ATHO#C104800 ~|~CUSTOMER STATES VEHICLE IS DRIPPING PINK FLUID ON THE FLOOR, PLEASE CHECK AND ADVISE ~|~~|~FOUND WATER PUMP LEAKING REMOVED LEAKING WATER PUMP AND **SERVICE:** BELT, DRIVE - REPLACE

**DESCRIPTION:** BELT, DRIVE - REPLACE ~ | ~ ~ | ~, CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER INSTALLED NEW ONW, ADDED NEW COOLANT REPLACED LEAKING WATER PUMP, ALLSTATE EXT WARRANTY NET \$660.08 DED \$100 ATHO#C104800 TIRES - MOUNT AND BALANCE 2 TIRES, 275/30/19 MICHELIN PILOT SUPER SPORT, LR TIRE WEARING ON INSID ~1~~1~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER TIRES - MOUNT AND BALANCE 2 TIRES, 275/30/19 MICHELIN PILOT SUPER SPORT, LR TIRE WEARING ON INSID

SERVICE: COMPLETE COOLING SYSTEM FLUID EXCHANGE DESCRIPTION: COMPLETE COOLING SYSTEM FLUID EXCHANGE ~!~ ~!~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ CHANGED OIL SERVICE: NO WASH PER CLIENT REQUEST

SERVICE: OIL AND FILTER - CHANGE

CHANGE ~ | ~ ~ | ~ CHANGED OIL AND FILTER.

**DESCRIPTION:** NO WASH PER CLIENT REQUEST ~1~NO WASH PER CLIENT REQUEST ~1~NO WASH PERFORMED AT THIS TIME PER CLIENT REQUEST

SERVICE: REAR DIFFERENTIAL SERVICE: EXCHANGE REAR DIFFERENTIAL OIL. DESCRIPTION: REAR DIFFERENTIAL SERVICE: EXCHANGE REAR DIFFERENTIAL OIL. ~!~~!~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -

#### 46203 MILES

DATE: 06/04/2014

REPAIR# 0250003 REPORTED BY: Lexus of Arlington

SERVICE: ELEMENT, AIR CLEANER - REPLACE DESCRIPTION: ELEMENT, AIR CLEANER - REPLACE ~ | ~ ~ | ~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

SERVICE: REAR DIFFERENTIAL SERVICE: EXCHANGE REAR DIFFERENTIAL OIL. DESCRIPTION: REAR DIFFERENTIAL SERVICE: EXCHANGE REAR DIFFERENTIAL OIL. ~!~~!~,CUSTOMER DECLINED SERVICE -CUSTOMER WILL HAVE WORK PERFORMED LATER

#### 41452 MILES

36492 MILES

DATE: 03/14/2014

**REPAIR#** 0245824 **REPORTED BY:** Lexus of Arlington

SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~ | ~ OIL AND FILTER -CHANGE ~ | ~ ~ | ~ LOF

SERVICE: RESET MAINTENANCE REMINDER SYSTEM DESCRIPTION: RESET MAINTENANCE REMINDER SYSTEM ~|~RESET MAINTENANCE REMINDER SYSTEM ~|~~|~RESET MAINT SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~ ~|~PERFORMED INSPECTION

DATE: 10/10/2013

REPAIR# 0236917 REPORTED BY: Lexus of Arlington

SERVICE: ALIGNMENT, WHEEL - FOUR - ADJUST

**DESCRIPTION:** ALIGNMENT, WHEEL - FOUR - ADJUST ~!~ ~!~ ~!~CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER

### SERVICE: NO WORK PERFORMED

DESCRIPTION: NO WORK PERFORMED ~ | ~ SPEAKER - REPLACE

LEFT REAR DOOR CENTER SPEAKER INOP ~|~~|~36491 UPON REMOVAL OF REAR DOOR PANEL, FOUND CENTER DOOR SPEAKER NEVER INSTALLED IN VEHICLE AND NO ELECTRICAL WIRING FOR SPEAKER. NORMAL OPERATION OF SPEAKERS AFTER OTHER SPEAKER REPLACEMENT.

**SERVICE:** REMOVE SERRATION PATTERN & INSTALL NEW WIPER ARM NUTS

DESCRIPTION: REMOVE SERRATION PATTERN & INSTALL NEW WIPER ARM NUTS ~|~SAFETY RECALL DLA - REMEDY NOTICE -2006 THROUGH EARLY 2012 MODEL YEAR IS 250 AND IS 350 2010 THROUGH EARLY 2012 MODEL YEAR IS250C AND IS 350C AND 2008 THROUGH 2011 MODEL YEAR IS-F FRONT WIPER ARM NUT. ~|~REMOVED SERRATION PATTERN, REPLACED NUTS ~|~36491 3524AA PERFORMED DLA SERVICE CAMPAIGN, REMOVED SERRATION PATTERN AND REPLACED NUTS.

# **SERVICE:** REPLACED REAR SHELF SPEAKER ASS.

**DESCRIPTION:** REPLACED REAR SHELF SPEAKER ASS. ~|~SPEAKER - REPLACE REAR SHELF SUB WOOFER DISTORTED ~|~~|~36491 REPLACED REAR SHELF SPEAKER ASSEMBLY.

# SERVICE: SPEAKER REPLACED

**DESCRIPTION:** SPEAKER REPLACED ~1~SPEAKER - REPLACE RIGHT REAR LOWER DOOR SPEAKER DISTORTED ~1~~1~36491 REPLACED RIGHT REAR LOWER DOOR SPEAKER.

# SERVICE: CUSTOMER RECOMMENDED SPEAKER (MULTIPLE) REPLACEMENTS

**DESCRIPTION: CUSTOMER RECOMMENDED SPEAKER** 

(MULTIPLE) REPLACEMENTS ~|~CUSTOMER STATES THAT BOTH REAR DOOR CENTER SPEAKERS AND SUB WOOFER ARE BLOWN, PLEASE CHECK AND ADVISE ~|~ ~|~36491 FOUND REAR SHELF SPEAKER, BOTH REAR DOOR CENTER SPEAKERS, AND RIGHT REAR LOWER DOOR SPEAKER DISTORTED OR NO SOUND. RECOMMEND REPLACEMENT.

SERVICE: PERFORM MULTI-POINT VEHICLE INSPECTION DESCRIPTION: PERFORM MULTI-POINT VEHICLE INSPECTION ~|~PERFORM MULTI-POINT VEHICLE INSPECTION ~|~~|~36491 DONE

SERVICE: REPLACE INTERNAL TRUNK RELEASE LEVER DESCRIPTION: REPLACE INTERNAL TRUNK RELEASE LEVER ~|~PRODUCT UPDATE DLB - REMEDY NOTICE - CERTAIN 2006 TO EARLY 2013 MY IS 250 IS 350 & IS-F CERTAIN 2007 TO EARLY 2013 MY ES 350 & ES 300H & CERTAIN 2013 MY GS 350 & GS 450H VEHICLES - INTERNAL TRUNK RELEASE LEVER (HANDLE). ~|~TRUNK LEVER REPLACED ~|~36491 3611AA PERFORMED DLB SERVICE CAMPAIGN, REPLACED INNER TRUNK RELEASE LEVER.

#### SERVICE: SEE LINE E

**DESCRIPTION:** SEE LINE E ~1~SPEAKER - REPLACE RIGHT REAR CENTER DOOR SPEAKER INOP ~1~~1~36491 SEE LINE E

SERVICE: TIRES - MOUNT AND BALANCE 225/40/ZR19 255/35/ZR19 4/32"" TO 3/32"" TREAD DEPTH U DESCRIPTION: TIRES - MOUNT AND BALANCE 225/40/ZR19 255/35/ZR19 4/32"" TO 3/32"" TREAD DEPTH U ~|~~|~ ~|~CUSTOMER DENIED SERVICE - CUSTOMER WILL HAVE WORK PERFORMED LATER

#### 30378 MILES

**REPAIR#** 0087276 **REPORTED BY:** Lexus of Chester Springs

SERVICE: 30,000 MILE SERVICE \*\*RESET """MAINTENANCE REQ'D"""" LIGHT\*\* DESCRIPTION: 30,000 MILE SERVICE \*\*RESET ""MAINTENANCE REQ'D"" LIGHT\*\* ~1~30,000 MILE SERVICE \*\*RESET ""MAINTENANCE REQ'D"" LIGHT\*\*

SERVICE: STATE INSPECTION/EXEMPT DESCRIPTION: STATE INSPECTION/EXEMPT ~I~MAY STATE AND SERVICE: OTHER OP CODE DESCRIPTION: OTHER OP CODE ~|~484.753.5749

# DATE: 05/16/2012

EMISSION INSPECTION

.....

26578 MILES

DATE: 05/06/2011

**REPAIR#** 0072189 **REPORTED BY:** Lexus of Chester Springs

SERVICE: 9LG REPLACE PEDAL PAD, REFLASH - IS MODELS ONLY DESCRIPTION: 9LG REPLACE PEDAL PAD, REFLASH - IS MODELS ONLY ~|~RECALL ~|~SPECIAL SERVICE CAMPAIGN

**SERVICE:** MAY STATE AND EMISSION INSPECTION **DESCRIPTION:** MAY STATE AND EMISSION INSPECTION ~|~MAY STATE AND EMISSION INSPECTION SERVICE: CHANGE OIL AND FILTER AND CHECK ALL FLUIDS DESCRIPTION: CHANGE OIL AND FILTER AND CHECK ALL FLUIDS ~I ~CHANGE OIL AND FILTER AND CHECK ALL FLUIDS

SERVICE: REPLACE MISSING SHIFTER LOCK COVER DESCRIPTION: REPLACE MISSING SHIFTER LOCK COVER ~|~CUSTOMER STATES PLASTIC CHIFT LOCK COVER MISSING

# 17944 MILES

DATE: 07/25/2009

DATE: 06/05/2009

REPAIR# 0339851 REPORTED BY: Rallye Lexus

SERVICE: OIL AND FILTER CHANGE FOR IS-F \$99.95 DESCRIPTION: OIL AND FILTER CHANGE FOR IS-F \$99.95 ~ | ~OIL AND FILTER CHANGE FOR IS-F \$99.95 ~ | ~ ~ | ~17944 40 PREFOEMD LOF SERVICE REC WIPERS, CABIN AIR FILTERS. ALSO REC FOUR TIRES FT TWO HAVE INNER EDGE WEAR (CORDS ARE STARTING TO POP OUT OF THE RUBBER ON THE L/F BOTH ARE BALD ON THE INNER EGDE) REAR TIRE DETHP IS 3/32 CUST DECLINED AT THIS TIME SERVICE: TECH RECOMENDED FOUR NEW TIRES, ALIGNEMENT, ENGINE AND CABIN AIR FILTERS, AND WI DESCRIPTION: TECH RECOMENDED FOUR NEW TIRES, ALIGNEMENT, ENGINE AND CABIN AIR FILTERS, AND WI ~1~AS PER CUSTOMER REQUEST PERFORM MULTIPOINT MAINTANCE INSPECTION.

#### 14829 MILES

REPAIR# 0293433 REPORTED BY: Lexus of Cherry Hill

SERVICE: DIFFERENTIAL CARRIER ASSY

DESCRIPTION: DIFFERENTIAL CARRIER ASSY ~1~CU/STS WAS TRAVELING AT ABOUT 55MPH AND A LOUD CLUNKING SOUND CAME FROM THE REAR OF THE CAR. PULLED CAR TO THE SHOULDER AND IT SOUNDED LIKE THERE WERE LOOSE BOLTS HITTING UNDERNEATH THE VEHICLE. THE CAR NO LONGER SHIFTED IN DRIVE OR REVERSE. HAD VEHICLE T ~1~INTERNAL FAILURE ~1~14829 VEHICLE TOWED IN FOUND REAR

DIFFERENTIAL GEARS TO BE BROKEN, AND AXLE DAMAGE, FLUID STILL IN REAR NO LEAKS. CAUSE WEAK CONSTRUCTION OF DIFFERENTIAL GEARS REPLACED REAR DIFFERENTIAL AND BOTH AXLES NOTE: FRT BUMPER DAMAGED BEFORE VEHICLE WORKED ON

10321 MILES

<b>REPAIR#</b> 0330493	
<b>REPORTED BY:</b> Rallye Lexus	
SERVICE: 2 TIRES	SERVICE: CALLED
DESCRIPTION: 2 TIRES ~  ~REPLACE 2 REAR TIRES 956.00 ~ -	- DESCRIPTION: CALLED ~ ~CALL 917- 701-4591
~ ~10321 REAR TIRES WORN OUT TO MEATAL CORDS 200 REPLACED REAR TIRES. BRIDGESTONE POTENZA RE050A.255/35ZR19. DOT ON BOTH TIRES EJAP DAA1108.	
SERVICE: RALLYE LEXUS RECOMENDED 10,000 MILE SERVI	CE
\$139.95 DESCRIPTION: RALLYE LEXUS RECOMENDED 10,000 MILE	
SERVICE \$139.95 ~ ~RALLYE LEXUS RECOMENDED 10,000 MII SERVICE \$139.95 ~ ~ ~ ~10319 80 PERFORMED 10K SERVICE RE WORE OUT NOT SAFE TO DRIVE LIKE THAT \$359 EACH NOT	AR
STK FT BRAKES @4MM REAR @6MM	
6274 MILES	DATE: 02/13/2009
<b>REPAIR#</b> 0286887	
<b>REPORTED BY:</b> Lexus of Cherry Hill	
SERVICE: OTHER INSPECTION	
<b>DESCRIPTION:</b> OTHER INSPECTION ~ ~CU/STS HEARS RUE	BING

NOISE COMING FROM FRONT END GETS LOUDER WHEN BRAKING ~|~~|~6274 NEEDS TIRES/NOISY/REAR ARE 0/32

# 5003 MILES

**REPAIR#** 0286353 **REPORTED BY:** Lexus of Cherry Hill

**SERVICE:** 5,000 MILE SERVICE DESCRIPTION: 5,000 MILE SERVICE ~ | ~5,000 MILE SERVICE ~|~MT ~|~5002 PERFORMED 5K SERVICE. REAR TIRES ARE WORN, SHOULD BE REPLACED.

# **15 MILES**

**REPAIR#** 0266844 **REPORTED BY:** Lexus of Edison

SERVICE: 1LB (SSC) DESCRIPTION: 1LB (SSC) ~|~PERFORM PDI INSPECTION ~|~PD ~|~MAINTENANCE

**TERMS AND CONDITIONS** 

DATE: 07/08/2008

# INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicl s service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions concerns regarding this information should be addressed to the applicable Lexus dealer.

# L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

# **OWNER-REPORTED INFORMATION AND PRIVACY TERMS**

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please <u>click here</u> (//www.lexus.com/privacy/online-statement).