I purchased vehicle 1/27/2016 2/8/16 oil change with 82096 (Toyota 0W20 and OEM filter) 2/11/16 new OEM front rotors, pads, replaced right front air strut (remaining three struts were replaced prior to ownership in history below) 11/11/16 87,591 oil change (Toyota 0W20 and OEM filter) 3/30/18 92,682 5qts WS fluid change

77416 MILES **DATE:** 07/23/2015 REPAIR# 0011584 **REPORTED BY: Lexus of Las Vegas** SERVICE: ELF-REPL FUEL PRESSURE GASKE T-IS F,GS460,LS460,LS600H DESCRIPTION: ELF-REPL FUEL PRESSURE GASKE T-IS F,GS460,LS460,LS600H ~ | ~ ELF SAFETY RECALL ELF - REMEDY NOTICE - VARIOUS MODELS - POTENTIAL FU ~|~ELF SSC ~|~ELF-REPL FUEL PRESSURE GASKE T-IS F,GS460,LS460,LS600H SERVICE: OIL & FILTER CHANGE W/ LUBE DESCRIPTION: OIL & FILTER CHANGE W/ LUBE ~ | ~ CUSTOMER STATES OIL & FILTER CHANGE W/ LUBE (\$115.00) ~ | ~ OIL CHANGE IS DUE ~ | ~ OIL & FILTER CHANGE W/ LUBE SERVICE: PERFORM EXPRESS VEHICLE INSPECTION DESCRIPTION: PERFORM EXPRESS VEHICLE INSPECTION ~| ~CUSTOMER STATES PERFORM EXPRESS VEHICLE INSPECTION ~ | ~ OCI ~ | ~ PERFORM EXPRESS VEHICLE INSPECTION SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ | ~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ | ~ LOANER ~ | ~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE SERVICE: REPLACE WATER PUMP DESCRIPTION: REPLACE WATER PUMP ~ | ~ CUSTOMER STATES OK TO REPLACE LEAKING WATER PUMP ~|~WATER PUMP LEAKING ~|~REPLACE WATER PUMP 72337 MILES **DATE:** 12/24/2014 REPAIR# 0095320 **REPORTED BY: Lexus of Las Vegas** SERVICE: PERFORM EXPRESS VEHICLE INSPECTION DESCRIPTION: PERFORM EXPRESS VEHICLE INSPECTION ~| ~CUSTOMER STATES PERFORM EXPRESS VEHICLE INSPECTION ~ | ~ OCI ~ | ~ PERFORM EXPRESS VEHICLE INSPECTION SERVICE: PERFORMED OIL & FILTER CHANGE W/ LUBE TIRES@34PSI; TREAD 4-5/32; BRAKES 6MM+ DESCRIPTION: PERFORMED OIL & FILTER CHANGE W/ LUBE TIRES@34PSI; TREAD 4-5/32; BRAKES 6MM+~I~CUSTOMER STATES OIL & FILTER CHANGE W/ LUBE (WAITER, \$115.00) ~|~LOF ~|~PERFORMED OIL & FILTER CHANGE W/ LUBE TIRES@34PSI; TREAD 4-5/32; BRAKES 6MM+ 68944 MILES **DATE:** 07/28/2014 REPAIR# 0083775 **REPORTED BY: Lexus of Las Vegas** 

SERVICE: CUSTOMER WAS CHARGED \$62.06 FOR PRO RATE. BATTERY IS 100% WARRANTY. TED PUT

DESCRIPTION: CUSTOMER WAS CHARGED \$62.06 FOR PRO RATE. BATTERY IS 100% WARRANTY. TED PUT ~|~CUSTOMER STATES DEAD BATTERY. HAD TO JUMP START TO GET HERE. LAST REPLACED 7/2/12 RO#28486 @ 51,932MI. TEST AND ADVISE ~|~BATTERY FAILED LOAD TEST DUE TO INTERNAL SHORT. T1-71 T2-73 WARRANTY CODE: 813P ~|~CUSTOMER WAS CHARGED \$62.06 FOR PRO RATE. BATTERY IS 100% WARRANTY. TED PUT POP UP NOTE TO CREDIT NEXT SERVICE

SERVICE: R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK.

DESCRIPTION: R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK. ~|~CUSTOMER STATES HAD TO JUMP START TO GET HERE. LAST REPLACED 7/2/12 RO#28486 @ 51,932MI. TEST AND ADVISE. REPLACE UNDER 50/50 PRO RATE WARRANTY ~|~BATTERY FAILED LOAD TEST DUE TO INTERNAL SHORT. T1-71 T2-73 WARRANTY CODE: 813P ~|~R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK.

68944 MILES

**DATE:** 07/26/2014

REPAIR# 0083775

REPORTED BY: Lexus of Las Vegas

SERVICE: R&R BATTERY RESET WINDOWS, NAV, AND CLOCK.

DESCRIPTION: R&R BATTERY RESET WINDOWS, NAV, AND CLOCK. ~|~CUSTOMER STATES DEAD BATTERY. HAD TO JUMP START TO GET HERE. LAST REPLACED 7/2/12 RO#28486 @ 51,932MI. TEST AND ADVISE ~|~BATTERY FAILED LOAD TEST DUE TO INTERNAL SHORT. T1-71 T2-73 WARRANTY CODE: 813P ~|~R&R BATTERY RESET WINDOWS, NAV, AND CLOCK. SERVICE: R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK.

DESCRIPTION: R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK. ~|~CUSTOMER STATES HAD TO JUMP START TO GET HERE. LAST REPLACED 7/2/12 RO#28486 @ 51,932MI. TEST AND ADVISE. REPLACE UNDER 50/50 PRO RATE WARRANTY ~|~BATTERY FAILED LOAD TEST DUE TO INTERNAL SHORT. T1-71 T2-73 WARRANTY CODE: 813P ~|~R&R BATTERY. RESET WINDOWS, NAV, AND CLOCK.

67170 MILES

**DATE:** 05/16/2014

REPAIR# 0078242

REPORTED BY: Lexus of Las Vegas

SERVICE: OIL & FILTER CHANGE W/ LUBE

DESCRIPTION: OIL & FILTER CHANGE W/ LUBE ~ | ~ CUSTOMER STATES OIL & FILTER CHANGE W/ LUBE \$114.00 ~ | ~ CUSTOMER STATES OIL & FILTER CHANGE W/ LUBE ~ | ~ OIL & FILTER CHANGE W/ LUBE

SERVICE: PERFORM EXPRESS VEHICLE INSPECTION

DESCRIPTION: PERFORM EXPRESS VEHICLE INSPECTION ~|~CUSTOMER STATES PERFORM EXPRESS VEHICLE INSPECTION ~|~OCI ~|~PERFORM EXPRESS VEHICLE INSPECTION SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~|~CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~|~LOANER ~|~PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE

SERVICE: REMOVED ALL CORROSION REPLACED POS CLAMP.

DESCRIPTION: REMOVED ALL CORROSION REPLACED POS CLAMP. ~|~CUSTOMER STATES OK TO REPLACE POSITIVE BATTERY CABLE END AND SERVICE BATTERY ~|~CORROSION ON POS. BATTERY TERMINAL ~|~REMOVED ALL CORROSION REPLACED POS CLAMP. SERVICE: REPLACE FRONT BRAKE PADS, CAL BOLTS AND ANTI SQUEAL SHIM KITS. RESURFACED ROTO DESCRIPTION: REPLACE FRONT BRAKE PADS, CAL BOLTS AND ANTI SQUEAL SHIM KITS. RESURFACED ROTO ~ | ~ CUSTOMER STATES REPLACE FRONT BRAKE PADS, CAL BOLTS AND ANTI SOUEAL SHIM KITS - \$422.00 ~ | ~ FRONT BRAKES BELOW MIN SPEC. ~ | ~ REPLACE FRONT BRAKE PADS, CAL BOLTS AND ANTI SOUEAL SHIM KITS. RESURFACED ROTORS 66391 MILES **DATE:** 04/14/2014 REPAIR# 0075834 **REPORTED BY: Lexus of Las Vegas** SERVICE: REMOVED NAIL AND PERFORMED A PLUG PATCH REPAIR. NOTICED FRONT BRAKES AT 3MM DESCRIPTION: REMOVED NAIL AND PERFORMED A PLUG PATCH REPAIR. NOTICED FRONT BRAKES AT 3MM ~ | ~ CUSTOMER STATES ONE TIER HAS A SCREW IN IT (WAITER, PATCH TIRE IF POSS.) ~ | ~ RIGHT FRONT TIRE HAD NAIL ON MIDDLE OF TREAD. ~|~REMOVED NAIL AND PERFORMED A PLUG PATCH REPAIR. NOTICED FRONT BRAKES AT 3MM 61978 MILES **DATE:** 10/22/2013 REPAIR# 0062938 **REPORTED BY: Lexus of Las Vegas** SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~ MI ~ | ~ PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED 5,000 MILE SERVICE. DESCRIPTION: PERFORMED 5,000 MILE SERVICE. ~ | ~ CUSTOMER STATES FACTORY MINIMUM 5,000 MILE SERVICE \$262.00 ~ |~5K MAINT ~ | ~ PERFORMED 5,000 MILE SERVICE. REAR BRAKES DUE NEXT 5K SERVICE SERVICE: REPLACE REAR BRAKE PADS AND ANTI SQUEAL SHIM KITS DESCRIPTION: REPLACE REAR BRAKE PADS AND ANTI SQUEAL SHIM KITS ~ | ~ CUSTOMER STATES REPLACE REAR BRAKE PADS AND ANTI SQUEAL SHIM KITS ~ |~WORN PADS @3MM ~ |~ REPLACE REAR BRAKE PADS AND ANTI SOUEAL SHIM KITS SERVICE: REPLACED THE RIGHT HID BULB. DESCRIPTION: REPLACED THE RIGHT HID BULB. ~ | ~ CUSTOMER STATES RIGHT HEADLIGHT GOES OUT INT, SEEMS TO GO OUT WHEN MAKING LEFT TURNS - ADVISE (OK TO REPLACE HID BULB) ~ | ~ RIGHT HID BULB IS BURNED OUT. ~ | ~ REPLACED THE RIGHT HID BULB. **57025 MILES** DATE: 03/26/2013 REPAIR# 0047308 **REPORTED BY: Lexus of Las Vegas** SERVICE: INSPECTED UNDER BODY SHIELDS, NO FASTENERS ARE MISSING. REPLACED BOTH REAR SHO DESCRIPTION: INSPECTED UNDER BODY SHIELDS, NO FASTENERS ARE MISSING. REPLACED BOTH REAR SHO ~ | ~ CUSTOMER STATES TO SECURE DAMAGED UNDER SHIELD IF POSS., MAKING NOISE WHILE DRIVING (L.E. WARR CONT#9664793) ~ | ~ KNOCKING NOISE FROM LEFT FRONT STRUT MOUNT. MOUNT BROKEN, STRUT IS LEAKING OIL. EXESSIVE BOUNCE FROM REAR SUSPENSION, BOTH REAR SHOCKS ARE LEAKING OIL ~ | ~ INSPECTED

UNDER BODY SHIELDS, NO FASTENERS ARE MISSING. REPLACED BOTH REAR SHOCK ABSORBERS AND LEFT FRONT SHOCK ABSORBER.

SERVICE: MOUNT AND BALANCED THREE TIRES. - (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18)

DESCRIPTION: MOUNT AND BALANCED THREE TIRES. - (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) ~|~CUSTOMER STATES TO REPLACE 3 TIRES (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) \$1200.00 ~|~WORN ~|~MOUNT AND BALANCED THREE TIRES. - (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18)

SERVICE: NO REPAIR MADE

DESCRIPTION: NO REPAIR MADE ~|~CUSTOMER STATES HEADLIGHT KEEPS GOING OUT ~|~CHECKED HEADLIGHTS FOR 4 HOURS, BOTH HEADLIGHTS ARE WORKING AT THIS TIME. ~|~NO REPAIR MADE

SERVICE: PERFORM MAINTENANCE INSPECTION

DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~|~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~|~MI ~|~PERFORM MAINTENANCE INSPECTION SERVICE: PERFORM WHEEL ALIGNMENT

DESCRIPTION: PERFORM WHEEL ALIGNMENT ~|~CUSTOMER STATES WHEEL ALIGNMENT ~|~3 NEW TIRES (1 TIME N/C ALIGNMENT) ~|~PERFORM WHEEL ALIGNMENT

SERVICE: PERFORMED FACTORY MINIMUM - 5,000 MILES 15,000 MILES

DESCRIPTION: PERFORMED FACTORY MINIMUM - 5,000 MILES 15,000 MILES ~|~CUSTOMER STATES FACTORY MINIMUM - 55,000 MILES \$258.00 ~|~55K MAINT. ~|~PERFORMED

FACTORY MINIMUM - 5,000 MILES 15,000 MILES

SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~|~CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~|~LOANER ~|~PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE

51932 MILES

DATE: 07/02/2012

REPAIR# 0028486

REPORTED BY: Lexus of Las Vegas

SERVICE: CHECK & TEST BATTERY. R&R BATTERY, SYSTEM OK.

DESCRIPTION: CHECK & TEST BATTERY. R&R BATTERY, SYSTEM OK. ~|~P/W -- CUSTOMER STATES CAR IS SLOW TO CRANK (BATTERY PREV RPLCD RO#82720, 9/9/10, 35,334 MI) ~|~BATTERY FAILED LOAD TEST, BAD CELL. CODE 603P ~|~CHECK & TEST BATTERY. R&R

BATTERY, SYSTEM OK.

SERVICE: PERFORM MAINTENANCE INSPECTION

DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~| ~MI ~| ~PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED FACTORY MINIMUM - 5,000 MILES 15,000 MILES.

DESCRIPTION: PERFORMED FACTORY MINIMUM - 5,000 MILES 15,000 MILES. ~|~CUSTOMER STATES FACTORY MINIMUM - 50,000 MILES \$258.00 ~|~50K SERVICE ~|~PERFORMED FACTORY MINIMUM - 5,000 MILES 15,000 MILES.

SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~|~CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~|~LOANER ~|~PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE **48764 MILES DATE:** 02/10/2012 REPAIR# 0018537 **REPORTED BY: Lexus of Las Vegas** SERVICE: NEED TO SPECIAL ORDER SHIELD P=\$355.00 / L=\$125.00 + TAX/SUP DESCRIPTION: NEED TO SPECIAL ORDER SHIELD P=\$355.00 / L=\$125.00 + TAX/SUP ~ |~ CUSTOMER STATES RATTLE FROM UNDER DRIVER AREA -- WAITER, INSTALL S.O.P.--~|~SHIELD UNDER DRIVER SIDE OF CAR ~|~NEED TO SPECIAL ORDER SHIELD P=\$355.00 / L=\$125.00 + TAX/SUP 48136 MILES **DATE:** 01/17/2012 REPAIR# 0016796 **REPORTED BY: Lexus of Las Vegas** SERVICE: PERFORM EXPRESS VEHICLE INSPECTION DESCRIPTION: PERFORM EXPRESS VEHICLE INSPECTION ~|~CUSTOMER STATES PERFORM EXPRESS VEHICLE INSPECTION ~|~P/ PERFORM EXPRESS VEHICLE INSPECTION SERVICE: TIGHTENED SHEILD NUTS IF SOUNDS CONTINUE NEED TO REMOVE AND INSULATE SHEILDS WRI DESCRIPTION: TIGHTENED SHEILD NUTS IF SOUNDS CONTINUE NEED TO REMOVE AND INSULATE SHEILDS WRI ~ | ~ CUSTOMER STATES SHIELD IS LOOSE -- WAITER, ADVISE--~|~SHEILDS VIBRATING ~|~TIGHTENED SHEILD NUTS IF SOUNDS CONTINUE NEED TO REMOVE AND INSULATE SHEILDS WRITER HAS EST FOR PARTS AND LABOR P=\$25.00 / L=\$125.00 / TAX/SUP=\$11.00 (PARTS ARE SPECIAL ORDER) **46955 MILES DATE:** 12/05/2011 REPAIR# 0013932 **REPORTED BY: Lexus of Las Vegas** SERVICE: 1 TIME N/C REPAIR DESCRIPTION: 1 TIME N/C REPAIR ~ | ~ CUSTOMER STATES L/REAR DOOR PANEL IS LOOSE @ 1/4 GLASS AREA - ADVISE ~ | ~ DOOR PANEL HAD SOME BROKEN CLIPS. REPLACED CLIPS, R&R DOOR PANEL. ~|~1 TIME N/C REPAIR SERVICE: ALIGN VEHICLE TO MANUFACTURE SPECIFICATIONS DESCRIPTION: ALIGN VEHICLE TO MANUFACTURE SPECIFICATIONS ~ | ~ CUSTOMER STATES ALIGN VEHICLE TO MANUFACTURE SPECIFICATIONS ~ | ~ CUSTOMER STATES ALIGN VEHICLE TO MANUFACTURE SPECIFICATIONS ~ | ~ ALIGN VEHICLE TO MANUFACTURE SPECIFICATIONS SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~ MI ~ | ~ PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED DEALER RECOMMENDED - 50,000 MILES DESCRIPTION: PERFORMED DEALER RECOMMENDED - 50,000 MILES ~ | ~ CUSTOMER STATES DEALER RECOMMENDED - 50,000 MILES \$440.00 ~ | ~50K MAINT. ~ | ~ PERFORMED DEALER **RECOMMENDED - 50,000 MILES** SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE

DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ | ~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ | ~ LOANER ~ | ~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE SERVICE: REPLACE WORN R/F TIRE (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) DESCRIPTION: REPLACE WORN R/F TIRE (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) ~ | ~ CUSTOMER STATES TO REPLACE WORN R/F TIRE (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) ~|~WORN R/F TIRE ~|~REPLACE WORN R/F TIRE (DUNLOP SP SPORT MAXX A1 A/S, 235/50R18) 43433 MILES **DATE:** 07/20/2011 REPAIR# 0004318 **REPORTED BY: Lexus of Las Vegas** SERVICE: SYSTEM OK (MARK LEVINSON RADIO, CODE #P6501) DESCRIPTION: SYSTEM OK (MARK LEVINSON RADIO, CODE #P6501) ~ | ~ CUSTOMER STATES INT RADIO, CD, VOLUME, POWER/CHANNEL CONTROLS WILL GO OUT -- L.E. WARR CONT#9664793, NEED PRT# & OP-- ~ | ~ ALL CONTROLS WORKING WHEN CHECKED ~|~SYSTEM OK (MARK LEVINSON RADIO, CODE #P6501) **42546 MILES** DATE: 06/17/2011 REPAIR# 0001962 **REPORTED BY: Lexus of Las Vegas** SERVICE: HOOD SUPPORT ASEMBLY Z=OP SIDE DESCRIPTION: HOOD SUPPORT ASEMBLY Z=OP SIDE ~|~CUSTOMER STATES HOOD DOES NOT STAY UP WHEN OPENED - (L.E. WARR, INSTALL S.O.P.) ~ |~WEAK HOOD STAYS ~|~HOOD SUPPORT ASEMBLY Z=OP SIDE SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ | ~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ | ~ LOANER ~ | ~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE 42171 MILES **DATE:** 06/06/2011 REPAIR# 0001071 **REPORTED BY: Lexus of Las Vegas** SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~ ARGIS DOWN ~ | ~ PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED COMPLETE 45000 MILE SERVICE DESCRIPTION: PERFORMED COMPLETE 45000 MILE SERVICE ~|~CUSTOMER STATES PERFORMED COMPLETE 45000 MILE SERVICE \$250.00 ~ |~45K MAINT. ~ |~PERFORMED **COMPLETE 45000 MILE SERVICE** SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ |~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ |~ LOANER ~ |~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE SERVICE: REPLACE FRONT BRAKE PADS AND REFINISH ROTORS

DESCRIPTION: REPLACE FRONT BRAKE PADS AND REFINISH ROTORS ~ | ~ CUSTOMER STATES REPLACE FRONT BRAKE PADS AND REFINISH ROTORS ~|~REPLACE FRONT BRAKE PADS AND REFINISH ROTORS ~ | ~ REPLACE FRONT BRAKE PADS AND REFINISH ROTORS SERVICE: SOP STRUTS DESCRIPTION: SOP STRUTS ~ | ~ CUSTOMER STATES HOOD DOES NOT STAY UP - ADVISE ~|~SOP~|~SOP STRUTS **37739 MILES DATE:** 01/24/2011 REPAIR# 0091976 **REPORTED BY: Lexus of Las Vegas** SERVICE: \*\*\*CLEARING WE-OWE\*\*\* DESCRIPTION: \*\*\*CLEARING WE-OWE\*\*\* ~ | ~ CUSTOMER STATES PARTS CREDIT \*\*\*CLEARING WE-OWE\*\*\* ~| ~\*\*\*CLEARING WE-OWE\*\*\* ~| ~\*\*\*CLEARING WE-OWE\*\*\* **37738 MILES DATE:** 12/18/2010 REPAIR# 0089429 **REPORTED BY: Lexus of Las Vegas** SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ | ~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ | ~ MAINT ~ | ~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE SERVICE: REPLACE DRIVE BELT TENSIONER DESCRIPTION: REPLACE DRIVE BELT TENSIONER ~ | ~ CUSTOMER STATES RATTLE TYPE NOISE FROM ENGINE HEARD @ IDLE & REVERSE (MORE APPARENT WHEN EMNGINE IS WARM) ~ | ~ LOSS TENSION ~ | ~ REPLACE DRIVE BELT TENSIONER **37286 MILES DATE:** 11/30/2010 REPAIR# 0087924 **REPORTED BY: Lexus of Las Vegas** SERVICE: ALE REPL COMP SPRINGS & LASH ADJUSTERS FOR GS460, LS600HL DESCRIPTION: ALE REPL COMP SPRINGS & LASH ADJUSTERS FOR GS460, LS600HL ~|~ALE SSC DESCRIPTION NOT AVAILABLE ~ | ~ ALE ~ | ~ ALE REPL COMP SPRINGS & LASH ADJUSTERS FOR GS460, LS600HL SERVICE: INSTALL NEW WIPER BLADE INSERTS ALL DESCRIPTION: INSTALL NEW WIPER BLADE INSERTS ALL ~ | ~ CUSTOMER STATES INSTALL NEW WIPER BLADE INSERTS ALL ~|~WORN, MAINT ~|~INSTALL NEW WIPER BLADE INSERTS ALL SERVICE: PERFORM FACTORY 40000 MILE SERVICE DESCRIPTION: PERFORM FACTORY 40000 MILE SERVICE ~ | ~ CUSTOMER STATES FACTORY 40000 MILE SERVICE \$343.00 ~ | ~40K MAINT ~ | ~PERFORM FACTORY 40000 MILE SERVICE SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~ MAINT ~ | ~ PERFORM MAINTENANCE INSPECTION SERVICE: PERFORM REAR DIFFERENTIAL SERVICE

DESCRIPTION: PERFORM REAR DIFFERENTIAL SERVICE ~ | ~ CUSTOMER STATES REAR DIFFERENTIAL SERVICE ~ | ~ MAINT. DIRTY FLUID ~ | ~ PERFORM REAR DIFFERENTIAL SERVICE SERVICE: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE DESCRIPTION: PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE ~ | ~ CUSTOMER STATES PROVIDED LEXUS LOANER VEHICLE ~ | ~ LOANER ~ | ~ PROVIDED LEXUS LOANER VEHICLE-95.00 DOLLAR PER DAY VALUE SERVICE: R & R OUTER REAR VIEW MIRROR ASSY & BOLTS (RIGHT SIDE ONLY) DESCRIPTION: R & R OUTER REAR VIEW MIRROR ASSY & BOLTS (RIGHT SIDE ONLY) ~ | ~ CUSTOMER STATES R/EXT. MIRROR HOUSING IS LOOSE ~ | ~ LOSS TENSION L-SB- 0033-10 ~ |~R & R OUTER REAR VIEW MIRROR ASSY & BOLTS (RIGHT SIDE ONLY) SERVICE: TIGHTEN DOWN OK DESCRIPTION: TIGHTEN DOWN OK ~ | ~ CUSTOMER STATES BATTERY HOUSING IS NOT TIGHT ~ | ~LOOSE NUT ~ | ~TIGHTEN DOWN OK 35334 MILES **DATE:** 09/09/2010 REPAIR# 0082720 **REPORTED BY: Lexus of Las Vegas** SERVICE: REPLACED BATTERY - (P/W BATTERY PREV RPLCD RO#45570, 7/30/09, 24,339MI.) DESCRIPTION: REPLACED BATTERY - (P/W BATTERY PREV RPLCD RO#45570, 7/30/09, 24,339MI.) ~|~P/W -- CUSTOMER STATES CAR HAS TO BE JUMP STARTED --WAITER, BATTERY PREV RPLCD RO#45570, 7/30/09, 24,339MI.) ~ | ~BATTERY FAILED MIDTRONICS TESTER CODE 91PP ~ | ~ REPLACED BATTERY - (P/W BATTERY PREV RPLCD RO#45570, 7/30/09, 24,339MI.) **32288 MILES DATE:** 04/19/2010 REPAIR# 0069634 **REPORTED BY: Lexus of Las Vegas** SERVICE: CHECKED OP SEVERAL TIMES WORKING AS DESIGNED DESCRIPTION: CHECKED OP SEVERAL TIMES WORKING AS DESIGNED ~ | ~ CUSTOMER STATES R/EXT MIRROR ASSY MAKES NOISE & IS SLOW MOVING IN/OUT FROM AUTO FOLD ~ |~NO PROBLEM WHEN CHECKED ~ |~CHECKED OP SEVERAL TIMES WORKING AS DESIGNED SERVICE: FRONT SUSPENSION UPPER ARM A=OP SIDE DESCRIPTION: FRONT SUSPENSION UPPER ARM A=OP SIDE ~ | ~ CUSTOMER STATES WHEN ALMOST @ A STOP ON FLAT SURFACE, THERE IS A THUMP TYPE NOISE ~ | ~ BUSHINGS CRACKED AND WORN ~|~FRONT SUSPENSION UPPER ARM A=OP SIDE SERVICE: PERFORM 35000 MILE FACTORY SERVICE DESCRIPTION: PERFORM 35000 MILE FACTORY SERVICE ~ | ~ CUSTOMER STATES 35000 MILE FACTORY SERVICE \$252.00 ~ | ~35K MAINT. ~ | ~PERFORM 35000 MILE FACTORY SERVICE SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~|~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~V/I ~ | ~PERFORM MAINTENANCE INSPECTION SERVICE: REPLACE REAR BRAKE PADS AND REFINISH ROTORS TEST DRIVE DESCRIPTION: REPLACE REAR BRAKE PADS AND REFINISH ROTORS TEST DRIVE ~ I~CUSTOMER STATES REAR BRAKES ARE WORN AND REQUIRE REPLACEMENT - PREV

@4.5MM \$295.00 ~|~WORN PADS ~|~REPLACE REAR BRAKE PADS AND REFINISH ROTORS TEST DRIVE

SERVICE: SUSPNSN UPR ARM ASSY 1-SD A= OP SIDE

DESCRIPTION: SUSPNSN UPR ARM ASSY 1-SD A= OP SIDE ~|~CUSTOMER STATES WHEN ALMOST @ A STOP ON FLAT SURFACE, THERE IS A THUMP TYPE NOISE ~|~BUSHING CRAKED AND WORN ~|~SUSPNSN UPR ARM ASSY 1-SD A= OP SIDE

CRAKED AND WORN ~1~SUSPNSN UPR ARM A

27562 MILES **DATE:** 11/17/2009

REPAIR# 0055967

REPORTED BY: Lexus of Las Vegas

SERVICE: ALIGN VEHICLE TO MAUNFACTURER SPECIFICATIONS

DESCRIPTION: ALIGN VEHICLE TO MAUNFACTURER SPECIFICATIONS ~ | ~ CUSTOMER STATES ALIGN VEHICLE TO MAUNFACTURER SPECIFICATIONS - 2 NEW TIRES, 1 NEW SPARE ~ | ~ VEHICLE ALIGNMENT IS OUT OF SPEC. ~ | ~ ALIGN VEHICLE TO MAUNFACTURER SPECIFICATIONS

SERVICE: PERFORM MAINTENANCE INSPECTION

DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~|~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~|~DONE ~|~PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED COMPLETE 30000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRA

DESCRIPTION: PERFORMED COMPLETE 30000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRA ~|~CUSTOMER STATES 30000 MILE FACTORY SERVICE \$541.00 ~|~30000 MILE SERVICE ~|~PERFORMED COMPLETE 30000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRAKES=9MM, REAR=4.5MM

SERVICE: REPLACED KEY FOB BATTERY.

DESCRIPTION: REPLACED KEY FOB BATTERY. ~|~CUSTOMER STATES TO REPLACE KEY FOB BATTERY \$12.00 ~|~SMART KEY INOP. BATTERY VOLTAGE LOW. ~|~REPLACED KEY FOB BATTERY.

SERVICE: REPLACED THREE TIRES. NEW TIRES TO REAR, SPARE.

DESCRIPTION: REPLACED THREE TIRES. NEW TIRES TO REAR, SPARE. ~|~CUSTOMER STATES NEED TO REPLACE BOTH REAR TIRES & SPARE TIRE --NEED EST.-- ~|~THREE TIRES ARE WORN. ~|~REPLACED THREE TIRES. NEW TIRES TO REAR, SPARE.

27425 MILES

**DATE:** 11/11/2009

REPAIR# 0055514

REPORTED BY: Lexus of Las Vegas

SERVICE: LEXUS ROADSIDE ASSISTANCE

DESCRIPTION: LEXUS ROADSIDE ASSISTANCE ~|~ROADSIDE ASSISTANCE CASE#09109546 -LEFT FRONT TIRE IS FLAT ~|~LEFT FRONT TIRE FLAT - REPLACED WITH SPARE ~|~LEXUS

ROADSIDE ASSISTANCE

24339 MILES

**DATE:** 07/30/2009

REPAIR# 0045570

**REPORTED BY: Lexus of Las Vegas** 

SERVICE: LEXUS ROADSIDE ASSISTANCE

DESCRIPTION: LEXUS ROADSIDE ASSISTANCE ~ |~ROADSIDE ASSISTANCE CASE#09072885 ~|~ROADSIDE ~|~LEXUS ROADSIDE ASSISTANCE SERVICE: REPLACED BATTERY DESCRIPTION: REPLACED BATTERY ~ | ~ CUSTOMER STATES VEHICLE WILL NOT START ~|~BATTERY FAILED LOAD TEST ~|~REPLACED BATTERY 23971 MILES DATE: 07/17/2009 REPAIR# 0044204 **REPORTED BY: Lexus of Las Vegas** SERVICE: NO CAR WASH DESCRIPTION: NO CAR WASH ~ | ~ CUSTOMER STATES NO CAR WASH ~ | ~ NO CAR WASH ~|~NO CAR WASH SERVICE: PERFORM MAINTENANCE INSPECTION DESCRIPTION: PERFORM MAINTENANCE INSPECTION ~| ~CUSTOMER STATES PERFORM MAINTENANCE INSPECTION ~ | ~ MAINTENANCE INSPECTION ~ | ~ PERFORM MAINTENANCE INSPECTION SERVICE: PERFORMED COMPLETE 25000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRA DESCRIPTION: PERFORMED COMPLETE 25000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRA ~ | ~ CUSTOMER STATES PERFORMED COMPLETE 25,000 MILE SERVICE EST. 230.55 ~ | ~ 25000 MILE SERVICE ~ | ~ PERFORMED COMPLETE 25000 MILE SERVICE TIRES SET TO 35PSI; TREAD VARIES FRONT BRAKES=10.5MM, REAR=6MM **22184 MILES DATE:** 05/27/2009 REPAIR# 0038987 **REPORTED BY: Lexus of Las Vegas** SERVICE: REPLACE L/FRT TIRE (DUNLOP SP SPORT MAXX : 235/50R18 : 97V : LOAD 1609LBS : @8/3 DESCRIPTION: REPLACE L/FRT TIRE (DUNLOP SP SPORT MAXX : 235/50R18 : 97V : LOAD 1609LBS : @8/3 ~ | ~CUSTOMER STATES L/FRT TIRE HAS SCREW IN INNER SIDEWALL (IAS TIRE WARR) ~|~L/FRT TIRE HAS SCREW IN INNER SIDEWALL ~|~REPLACE L/FRT TIRE (DUNLOP SP SPORT MAXX : 235/50R18 : 97V : LOAD 1609LBS : @8/32"" : DOT# EU5V4M7R2508) 19836 MILES **DATE:** 02/24/2009 REPAIR# 0029757 **REPORTED BY: Lexus of Las Vegas** SERVICE: TEST DROVE, R&R INSTRUMENT PANEL & REPLACED COWL CLIPS DESCRIPTION: TEST DROVE, R&R INSTRUMENT PANEL & REPLACED COWL CLIPS ~ | ~ CUSTOMER STATES RATTLE HEARD FROM GLOVEBOX AREA & TRAVELS TO DRIVER SIDE OF DAHS (MAY BE MORE APPARENT WHEN COLD) HAPPENS WHEN DRIVING ON ROUGH TERRAIN OR GOING THROUGH POTHOLE/LANE DIVIDERS - SEE ADVISOR ~|~INSTRUMENT PANEL EXCESSIVE CLEARANCE ~|~TEST DROVE, R&R INSTRUMENT PANEL & REPLACED COWL CLIPS **19166 MILES** DATE: 01/28/2009 REPAIR# 0026814

REPORTED BY: Lexus of Las Vegas

SERVICE: 9LA REPLACE FUEL DELIVERY PIPES FOR LS460 DESCRIPTION: 9LA REPLACE FUEL DELIVERY PIPES FOR LS460 ~|~9LA 9LA LEXUS FUEL DELIVERY PIPE ~|~SSC ~|~9LA REPLACE FUEL DELIVERY PIPES FOR LS460 SERVICE: PERFORMED COMPLETE 20000 MILE SERVICE

DESCRIPTION: PERFORMED COMPLETE 20000 MILE SERVICE ~|~CUSTOMER STATES 20000 MILE FACTORY SERVICE (W/AC FILTER) \$375.00 ~|~TIRES=6/32 SET AT 36PSI; INNER WEARING FASTER. BRAKES 2MM FRONT & 6MM REAR. BATTERY VOLTS 12.75. REPLACED A/C FILTER ~|~PERFORMED COMPLETE 20000 MILE SERVICE

SERVICE: R&R OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)

DESCRIPTION: R&R OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)

~|~CUSTOMER STATES L/EXT. MIRROR ASSY MAKES BUZZ NOISE WHEN TRYING TO RETRACT ~|~L/EXT. REAR VIEW MIRROR WEAKEND ~|~R&R OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)

SERVICE: REPLACE FRONT BRAKE PADS AND REFINISH ROTORS, & TEST DRIVE. DESCRIPTION: REPLACE FRONT BRAKE PADS AND REFINISH ROTORS, & TEST DRIVE. ~|~FRONT BRAKES WORN AND REQUIRE REPLACEMENT. - @2MM ~|~BRAKES AT 2MM ~|~REPLACE FRONT BRAKE PADS AND REFINISH ROTORS, & TEST DRIVE.

SERVICE: TEST DROVE & VERIFIED WITH TEAM LEADER

DESCRIPTION: TEST DROVE & VERIFIED WITH TEAM LEADER ~|~CUSTOMER STATES RATTLE NOISE HEARD FROM GLOVEBOX AREA, POSSIBLY WOOD TRIM WHEN GOING OVER BUMPS OR LANE DIVIDERS ~|~UNABLE TO DUPLICATE ANY ABNORMAL SOUNDS COMING FROM GLOVEBOX AREA AT THIS TIME ~|~TEST DROVE & VERIFIED WITH TEAM LEADER

SERVICE: TEST DROVE AND VERIFIED WITH TEAM LEADER

DESCRIPTION: TEST DROVE AND VERIFIED WITH TEAM LEADER ~|~CUSTOMER STATES WHEN BACKING UP THROUGH DIP OR BUMP, THERE IS A NOISE L/FRT. ~|~UNABLE TO DUPLICATE ANY ABNORMAL SOUNDS COMING FROM L/FRT. ~|~TEST DROVE AND

VERIFIED WITH TEAM LEADER SERVICE: VEHICLE INSPECTION

DESCRIPTION: VEHICLE INSPECTION ~|~PERFORM MAINTENANCE INSPECTION ~|~DONE ~|~VEHICLE INSPECTION

15238 MILES

DATE: 08/29/2008

REPAIR# 0013407

REPORTED BY: Lexus of Las Vegas

SERVICE: PERFORM MINOR VEHICLE INSPECTION

DESCRIPTION: PERFORM MINOR VEHICLE INSPECTION ~|~PERFORM MINOR VEHICLE INSPECTION ~|~INSPECTION ~|~PERFORM MINOR VEHICLE INSPECTION

SERVICE: PERFORMED TIRE REPAIR W/INSIDE PATCH;MOUNT&BALANCE WHEEL.

DESCRIPTION: PERFORMED TIRE REPAIR W/INSIDE PATCH;MOUNT&BALANCE WHEEL.

~|~(LF) TIRE KEEPS GETTING LOW AND HAS A NAIL IN IT/OR IS LEAKING. ~|~R/F HAS NAIL,REPAIRABLE ~|~PERFORMED TIRE REPAIR W/INSIDE PATCH;MOUNT&BALANCE WHEEL.

14649 MILES

DATE: 08/12/2008

REPAIR# 0011513

REPORTED BY: Lexus of Las Vegas

SERVICE: OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)

DESCRIPTION: OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE) ~|~CUSTOMER STATES R/EXT. MIRROR ASSY IS LOOSE & SHAKES WHILE DRIVING - INSTALL SPO 08219014 MIRROR ASSY ~|~PASSENGER EXTERIOR MIRROR LOOSE AT HINGES. ~|~OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)

14496 MILES

DATE: 08/06/2008

REPAIR# 0010956

REPORTED BY: Lexus of Las Vegas

SERVICE: ADVISE CUSTOMER DURING EXTREME HEATED DAYS EVAPORATIVE SYSTEM TENDS TO VENT EXCE

DESCRIPTION: ADVISE CUSTOMER DURING EXTREME HEATED DAYS EVAPORATIVE SYSTEM TENDS TO VENT EXCE ~!~CUSTOMER STATES INT. THERE IS FUEL ODOR MORE NOTICABLE IN CLOSED AREA ~!~INSPECTED VEHICLE NO SIGNS OF ANY FUEL LEAKS OR FUEL VAPORS. ~!~ADVISE CUSTOMER DURING EXTREME HEATED DAYS EVAPORATIVE SYSTEM TENDS TO VENT EXCESSIVELY.

SERVICE: PERFORMED COMPLETE 15000 MILE SERVICE

DESCRIPTION: PERFORMED COMPLETE 15000 MILE SERVICE ~|~CUSTOMER STATES PERFORMED COMPLETE 15000 MILE SERVICE - \$265.00 ~|~15K MILE SERVICE.

~|~PERFORMED COMPLETE 15000 MILE SERVICE

SERVICE: PURGE AND REFIL TIRES WITH NITROGEN

DESCRIPTION: PURGE AND REFIL TIRES WITH NITROGEN ~|~PURGE AND REFIL TIRES WITH NITROGEN - TIRE PRESSURE LIGHT IS ON : \$40.00 ~|~FILL TIRES WITH NITROGEN ~|~PURGE AND REFIL TIRES WITH NITROGEN

SERVICE: SOP RIGHT EXTERIOR MIRROR - DLR WILL NOTIFY CUST WHEN PART IS IN STOCK TO SET IN

DESCRIPTION: SOP RIGHT EXTERIOR MIRROR - DLR WILL NOTIFY CUST WHEN PART IS IN STOCK TO SET IN ~|~CUSTOMER STATES R/EXT. MIRROR ASSY IS LOOSE & SHAKES WHILE DRIVING ~|~SOP RIGHT EXTERIOR MIRROR. ~|~SOP RIGHT EXTERIOR MIRROR - DLR WILL NOTIFY CUST WHEN PART IS IN STOCK TO SET INSTALL APPT. (WARR-L)

SERVICE: VEHICLE INSPECTION

DESCRIPTION: VEHICLE INSPECTION ~|~PERFORM MAINTENANCE INSPECTION ~|~DONE ~|~VEHICLE INSPECTION

10527 MILES

**DATE:** 04/08/2008

REPAIR# 0099135

REPORTED BY: Lexus of Las Vegas

SERVICE: PERFORM 8LA, FILL WITH GAS

DESCRIPTION: PERFORM 8LA, FILL WITH GAS ~|~PERFORM 8LA IDLER PULLEY CAMPAIGN - INSTALL S.O.P. ~|~SSC 8LA ~|~PERFORM 8LA, FILL WITH GAS 9941 MILES

9941 MILES

DATE: 03/26/2008

REPAIR# 0097637

REPORTED BY: Lexus of Las Vegas

SERVICE: GLOVE BOX RATTLE NOISE/LOOSE COND. 07 LS460 ADJ GLOVE BOX DESCRIPTION: GLOVE BOX RATTLE NOISE/LOOSE COND. 07 LS460 ADJ GLOVE BOX ~ | ~ CUSTOMER STATES THE GLOVEBOX IS SAGGING ON R/SIDE - INSTALL S.O.P. ~ | ~TSIB NV005-07 ~ | ~GLOVE BOX RATTLE NOISE/LOOSE COND. 07 LS460 ADJ GLOVE BOX 9556 MILES **DATE:** 03/13/2008 REPAIR# 0096515 **REPORTED BY: Lexus of Las Vegas** SERVICE: PARTS ON ORDER SEE LINE 51 DESCRIPTION: PARTS ON ORDER SEE LINE 51 ~ | ~ CUSTOMER STATES THE GLOVE BOX IS SAGGING ON THE RIGHT SIDE ~|~TSIB NV005-07 ~|~PARTS ON ORDER SEE LINE 51 SERVICE: PERFORMED 10,000 MILE MANUFACTURE MINIMUM SERVICE -TIRES 10/32"""" TREAD DEPTH -DESCRIPTION: PERFORMED 10,000 MILE MANUFACTURE MINIMUM SERVICE -TIRES 10/32"" TREAD DEPTH -BR ~ | ~ PERFORM 10,000 MILE MANUFACTURE MINIMUM SERVICE \$290 ~ |~10,000 MILE SERVICE ~ |~PERFORMED 10,000 MILE MANUFACTURE MINIMUM SERVICE -TIRES 10/32"" TREAD DEPTH -BRAKES F:9MM R:11MM SERVICE: SPECIAL ORDERED PARTS DESCRIPTION: SPECIAL ORDERED PARTS ~ | ~ CUSTOMER STATES THE WOOD TRIM ABOVE THE GLOVE BOX MAKES A CREAKING/RATTLE SOUND WHEN DRIVING OVER BUMPY ROADS ~ | ~ RATTLE GLOVE BOX ASSEMBLY ~ | ~ SPECIAL ORDERED PARTS SERVICE: VEHICLE INSPECTION DESCRIPTION: VEHICLE INSPECTION ~|~PERFORM MAINTENANCE INSPECTION ~|~INSPECTION ~|~VEHICLE INSPECTION 5203 MILES **DATE:** 10/17/2007 REPAIR# 0081746 **REPORTED BY: Lexus of Las Vegas** SERVICE: PERFORMED 5,000 MILE SERVICE DESCRIPTION: PERFORMED 5,000 MILE SERVICE ~ | ~ CUSTOMER STATES PERFORM 5,000 MILE SERVICE ~ | ~ MAINT ~ | ~ PERFORMED 5,000 MILE SERVICE 3541 MILES DATE: 08/13/2007 REPAIR# 0075060 **REPORTED BY: Lexus of Las Vegas** SERVICE: REPL L/R DOOR SHADE TRIM T1-62,T2-12 DESCRIPTION: REPL L/R DOOR SHADE TRIM T1-62, T2-12 ~ | ~ C/S DRIVERS REAR DOOR SHADE FRAME IS COMING OFF - INSTALL SOP USE SPO 07211031 ~| ~L/R DOOR SHADE TRIM BROKEN ~|~REPL L/R DOOR SHADE TRIM T1-62, T2-12 **3365 MILES** DATE: 07/31/2007 REPAIR# 0073511 **REPORTED BY: Lexus of Las Vegas** SERVICE: RE-SOP PART DESCRIPTION: RE-SOP PART ~ | ~ C/S DRIVERS REAR DOOR SHADE FRAME IS COMING OFF USE SPO 07204009 GARNISH ~ | ~WRONG PART CAME IN ~ | ~RE-SOP PART **2898 MILES** 

DATE: 07/12/2007 REPAIR# 0071611 **REPORTED BY: Lexus of Las Vegas** SERVICE: A/C SEAT IS WORKING PROPERLY AT THIS TIME DESCRIPTION: A/C SEAT IS WORKING PROPERLY AT THIS TIME ~| ~CUSTOMER STATES THE A/C SEATS NOT COOLING ~ | ~ NO PROBLEM FOUND ~ | ~ A/C SEAT IS WORKING PROPERLY AT THIS TIME SERVICE: CHECK L/R SIDE SHADE-NO LOOSENESS FOUND AT THIS TIME CHECK L/R SIDE SHADE-NO LOO DESCRIPTION: CHECK L/R SIDE SHADE-NO LOOSENESS FOUND AT THIS TIME CHECK L/R SIDE SHADE-NO LOO ~ | ~ CUSTOMER STATES DRIVERS REAR SIDE SHADES PANEL IS LOOSE ~ |~NO PROBLEM FOUND ~ |~CHECK L/R SIDE SHADE-NO LOOSENESS FOUND AT THIS TIME CHECK L/R SIDE SHADE-NO LOOSENESS FOUND AT THIS TIME SERVICE: PAINT OR BODY SPECIALIST NEED TO TAKE CARE OF THIS DESCRIPTION: PAINT OR BODY SPECIALIST NEED TO TAKE CARE OF THIS ~ | ~ CUSTOMER STATES THERE IS A SMALL CHIP ON FRONT OF CAR \*\*PL CK & ADV\*\*\* ~|~SUBLET OUT ~ | ~ PAINT OR BODY SPECIALIST NEED TO TAKE CARE OF THIS 430 MILES DATE: 04/25/2007 REPAIR# 0062798 **REPORTED BY: Lexus of Las Vegas** SERVICE: INSTALLED SOP B-PILLAR ASSY. DESCRIPTION: INSTALLED SOP B-PILLAR ASSY. ~ | ~C/S ON THE DRIVERS SIDE MOULDING WHERE THE SEAT BELT MEETS, PART IS DEFORMED ~ | ~ DEFORMED INNER B-PILLAR ~ |~ INSTALLED SOP B-PILLAR ASSY. 136 MILES **DATE:** 04/14/2007 REPAIR# 0062044 **REPORTED BY: Lexus of Las Vegas** SERVICE: REMOVE CHROMES DESCRIPTION: REMOVE CHROMES ~ | ~ CUSTOMER STATES REMOVE CHROMES AND INSTALL FACTORY WHEELS FROM L72086 ~ | ~ REMOVE CHROMES AND INSTALL FACTORY WHEELS FROM L72086 ~ | ~ REMOVE CHROMES 77 MILES DATE: 04/12/2007 REPAIR# 0061522 **REPORTED BY: Lexus of Las Vegas** SERVICE: SOP. PARTS ON BACK ORDER ETA: 5/04/07 DESCRIPTION: SOP. PARTS ON BACK ORDER ETA: 5/04/07 ~ | ~CUSTOMER STATES INSIDE A-PILLAR IS DEFORMED ~ | ~ SOP ~ | ~ SOP. PARTS ON BACK ORDER ETA: 5/04/07 77 MILES DATE: 04/10/2007 REPAIR# 0061355 **REPORTED BY: Lexus of Las Vegas** SERVICE: ENVIROSHLD DESCRIPTION: ENVIROSHLD ~ | ~ CUSTOMER STATES ENVIROSHLD ~ | ~ SUBLET: TEPH SEAL ~|~ENVIROSHLD

17 MILES DATE: 04/06/2007 REPAIR# 0061057 **REPORTED BY: Lexus of Las Vegas** SERVICE: INSTALL FACTORY CHROME WHEELS FOR A LS460 18"""" DESCRIPTION: INSTALL FACTORY CHROME WHEELS FOR A LS460 18"" ~ | ~ CHROME WHEELS PER JR ~ | ~ INSTALL CHROME WHEELS FOR SHOWROOM FLOOR ~ | ~ INSTALL FACTORY CHROME WHEELS FOR A LS460 18"" 16 MILES DATE: 03/23/2007 REPAIR# 0059733 **REPORTED BY: Lexus of Las Vegas** SERVICE: INSTALL MATS AND PLACE LICENSE PLATE BRACKET IN TRUNK DESCRIPTION: INSTALL MATS AND PLACE LICENSE PLATE BRACKET IN TRUNK ~ | ~ CUSTOMER STATES INSTALL MATS AND PLACE LICENSE PLATE BRACKET IN TRUNK ~|~PDS ~|~INSTALL MATS AND PLACE LICENSE PLATE BRACKET IN TRUNK SERVICE: PERFORM PDI OPERATION DESCRIPTION: PERFORM PDI OPERATION ~ | ~ CUSTOMER STATES PERFORM PRE-DELIVERY SERVICE & INSPECTION. ~ | ~ PDI ~ | ~ PERFORM PDI OPERATION **TERMS AND CONDITIONS**