
2004 Lexus LS430

Submodel: | Engine Type: V8 | Liters: 4.3 Fuel Delivery: FI | Fuel: GAS

2001 – 2004 Model Year LS 430 Lexus Link System Removal

TECHNICAL INSTRUCTIONS

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

A. AFFECTED VIN RANGE

Model Year		VIN Range VDS Ranges		
LS 430	2001 - 2003	BN30F	0001027 - 0123767 3523589 - 3523600	
20 100	2004 BN36	F 0123793 - 0127482		

NOTE: Not all vehicles in the VIN range are affected by this LSC. Verify that the vehicle does have a Lexus Link system. Always consult Dealer Daily or TIS to confirm VIN eligibility and to assure the LSC is applicable. This will verify the vehicle is involved and has not already been completed by another dealer. TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected. In addition, the customer must request that the repair be performed and the "Lexus Link Removal Customer Acknowledgement Consent" form must be completed and signed.

III. PREPARATION

A. PARTS


Parts Name	Q'ty/ Vehicle
Roof Console Box Assembly (Ecru)	1*
Roof Console Box Assembly (lvory)	1*
Roof Console Box Assembly (Grav)	1*
Protector. Wire Harness	1
Lexus Link Removal Customer	
Acknowledgement Consent Form and Envelope $(OUP = 25)$	1
	Roof Console Box Assembly (Ecru) Roof Console Box Assembly (Ivory) Roof Console Box Assembly (Gray) Protector, Wire Harness Lexus Link Removal Customer

*NOTE: Only one part is necessary per vehicle. Confirm the interior color of the vehicle prior to ordering the part.

B. TOOLS

Standard Hand Tools

Nylon Pry Tool Kit (P/N 00002-06000-01)



Negative cable

IV. WORK PROCEDURE

A. CONTROL SWITCH ASSEMBLY REPLACEMENT 1. DETERMINE THE SUBSCRIPTION STATUS OF THE VEHICLE



If the subscription is still active, check with the Service Consultant for the signed "Lexus Link Removal Customer Acknowledgement Consent"form. Do

not remove the Lexus Link system without this customer permission form.

2. RECORD THE RADIO STATION PRESETS 3. SET THE SEAT TO MEMORY POSITION 1 4. DISCONNECT THE NEGATIVE BATTERY CABLE


NOTE:



Wait at least 20 seconds before proceeding to the next step to fully discharge the back-up battery. If the back-up battery is not discharged, the Lexus Link System may place a call to the Lexus Link Call Center.

5. REMOVE THE CONTROL SWITCH ASSEMBLY


- (a) Remove the map light assembly. (1) Open the sunglass holder with the Lexus Link buttons.
 - (2) Using a nylon pry tool, remove the lens.



9

23

2001 - 2004 Model Year LS 430 Lexus Link System Removal





24

Q


(3) Remove the 4 screws and map light assembly, and then disconnect the connector.


NOTE: Two of the screws may be covered by access panels.

- (b) Replace the sunglass holder.
 (1) Remove the tape and discard.
 (2) Disconnect the connector for the sunglass holder and the grommet.
 - (3) Remove the spring from the old sunglass holder and discard.


If the spring is not replaced, it will affect the open-rate of the holder.

- (4) Using a screwdriver, remove the gear and discard.
- (5) Remove the old sunglass holder and discard.





Lexus Limited Service Campaign 4LA





B. LSC COMPLETION LABEL INSTALLATION After completing the repair and before returning the vehicle to the owner, an LSC completion label, which is enclosed in the owner's notification, must be affixed to the left front door hinge post, near the check strap.

(a) The label is to be filled out as follows:

- . Write in LSC 4LA.
- .
 - Write in date of repair. Write in your dealer code.



(b) Additional LSC completion labels, in sheets of 50 (P/N 00410-01918), may be ordered through the non-parts system on the DMS system.