

LEXUS FORUM CAR A

SERVICE HISTORY

SERVICE HISTORY FOR: LEXUS FORUM CAR A

VIN: JTHBN36F755016356

91481 MILES

DATE: 10/15/2014

REPAIR# 0060567

REPORTED BY: Lexus of Rockville Centre

SERVICE: 25 POINT CHECK

DESCRIPTION: 25 POINT CHECK

~|~PERFORM A LEXUS OF ROCKVILLE
CENTRE WORLD CLASS INSPECTION
~|~25 POINT CHECK ~|~25 POINT
CHECK

SERVICE: FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY

~|~C/S CD PLAYER INOP, SYSTEM SAYS
CD ERROR ~|~ ~|~UPON INSPECTION
FOUND AFTERMARKED (BURNED CD)
STUCK IN PLAYER. PERFORMED CD
RETRACTION PROCESS UPON
COMPLETION FOUND SYSTEM
OEPRATING AS DESIGNED ADVISED
CUSTOMER RE: NON USE OF BURNED
CD'S

SERVICE: TENTATIVE APPT.

DESCRIPTION: TENTATIVE APPT.

~|~WE HAVE MADE A TENTATIVE
APPOINTMENT FOR YOU 6 MONTHS
FROM TODAY. OUR APPOINTMENT
DESK WILL CONTACT YOU ONE
WEEK PRIOR TO YOUR DATE TO
SCHEDULE AN APPOINTMENT AT
YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

68922 MILES

DATE: 01/26/2012

REPAIR# 0691950

REPORTED BY: Lexus of Rockville Centre

SERVICE: 25 POINT CHECK

DESCRIPTION: 25 POINT CHECK

~|~PERFORM A LEXUS OF ROCKVILLE CENTRE WORLD CLASS INSPECTION
~|~25 POINT CHECK ~|~25 POINT CHECK

SERVICE: INSPECT ENGINE OIL LEVEL

DESCRIPTION: INSPECT ENGINE OIL LEVEL ~|~REPLACE ENGINE OIL AND OIL FILTER PER FACTORY SPECIFICATIONS UP TO 6 QUARTS OF OIL, AN ADDITIONAL CHARGE FOR VEHICLES THAT REQUIRE MORE THAN (6) QUARTS OF OIL. - SYNTHETIC OIL IF REQUIRED OR REQUESTED IS ADDITIONAL ~|~
~|~PERFORM LUBE, OIL & FILTER CHANGE

SERVICE: CHECK TIRE LIGHT

DESCRIPTION: CHECK TIRE LIGHT

~|~CHECK TIRE LIGHT - DIAGNOSIS/REPAIR TIRE PRESSURE WARNING LIGHT ON DASH. PLEASE ADVISE. ~|~. ~|~FOUND NAIL R/R RESET TIRE SENSORS

SERVICE: TENTATIVE APPT.

DESCRIPTION: TENTATIVE APPT.

~|~WE HAVE MADE A TENTATIVE APPOINTMENT FOR YOU 6 MONTHS FROM TODAY. OUR APPOINTMENT DESK WILL CONTACT YOU ONE WEEK PRIOR TO YOUR DATE TO SCHEDULE AN APPOINTMENT AT YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

51975 MILES

DATE: 03/31/2010

REPAIR# 0643558

REPORTED BY: Lexus of Rockville Centre

SERVICE: 25 POINT CHECK

DESCRIPTION: 25 POINT CHECK

~|~CUSTOMER AUTHORIZES COMPLIMENTARY 25 POINT SAFETY INSPECTION ~|~25 POINT CHECK
~|~25 POINT CHECK

SERVICE: FRONT/REAR BODY

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY ~|~CUST

STATES : THE TRUNK DOES NOT OPEN FROM THE INSIDE ,, PLEASE CHECK ~|~ ~|~TRUNK CYL. IN THE LOCK POST. TURNED IT TO THE OPEN POST. ACCESSORY ~|~CUST REQUEST : PLEASE PERFORM DIFF SERVICE ~|~
~|~PERFORMED REAR DIFF.SERVICE.

SERVICE: INSPECT AIR FILTER

DESCRIPTION: FRONT/REAR BODY
~|~CUST STATES : THE TIRE PRESSURE
LIGHT IS ON ,,,"PLEASE CHECK
~|~CUST. INSTALLED NEW SET OF
TIRES,NO TIRE PRES. INITIALIZATIO
~|~INITIALIZED TIRE PRESSURE.

SERVICE: INSPECT ENGINE OIL
LEVEL
DESCRIPTION: INSPECT ENGINE OIL
LEVEL ~|~CUSTOMER REQUESTED
LUBE, OIL & FILTER CHANGE ~|~
~|~LOF IS DONE.

SERVICE: TENTATIVE APPT.
DESCRIPTION: TENTATIVE APPT.
~|~WE HAVE MADE A TENTATIVE
APPOINTMENT FOR YOU 6 MONTHS
FROM TODAY. OUR APPOINTMENT
DESK WILL CONTACT YOU ONE
WEEK PRIOR TO YOUR DATE TO
SCHEDULE AN APPOINTMENT AT
YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

DESCRIPTION: INSPECT AIR FILTER
~|~. ~|~DIRTY A/C FILTER.
~|~REPLACED A/C FILTER. E

SERVICE: NON WARRANTABLE
OPERATION CODE
DESCRIPTION: NON WARRANTABLE
OPERATION CODE ~|~ ~|~
~|~INSTALLED ENGINE AIR FILTER.

46121 MILES

DATE: 10/30/2009

REPAIR# 0631829
REPORTED BY: Lexus of Rockville Centre

SERVICE: 25 POINT CHECK
DESCRIPTION: 25 POINT CHECK
~|~CUSTOMER AUTHORIZES
COMPLIMENTARY 25 POINT SAFETY
INSPECTION ~|~25 POINT CHECK
~|~25 POINT CHECK

SERVICE: DISTRIBUTOR/HDLIGHT/T.
SGNL
DESCRIPTION:
DISTRIBUTOR/HDLIGHT/T. SGNL
~|~CUSTOMER STS CK AFS LIGHT IS
ON CK AND REPORT ~|~FOUND AFS
LIGHT BLINKING. CODE B2416
CHECKED DATA LIST AND FOUND
REAR SENSOR DEFECTIVE.
~|~REPLACED REAR HIGHT
CONTROL SENSOR 857021 .40 T1 72 T2
99

SERVICE: FRONT AXLE

DESCRIPTION: FRONT AXLE ~|~C/S

THERE IS A CLICKING SOUND OVER
BUMPS FROM REAR AND AFS LIGHT
IS ON... ~|~ROAD TESTED CAR.
FOUND NOISE IN L/R AREA OF CAR.
LIFT CHECKE CAR AND FOUND
BADLY LEAKING STRUT. . .
~|~REPLACED DRIVERS SIDE REAR
STRUT. OPCODE 482091 0.8 T-1 65 T-2 14
..

SERVICE: TENTATIVE APPT.

DESCRIPTION: TENTATIVE APPT.

~|~WE HAVE MADE A TENTATIVE
APPOINTMENT FOR YOU 6 MONTHS
FROM TODAY. OUR APPOINTMENT
DESK WILL CONTACT YOU ONE
WEEK PRIOR TO YOUR DATE TO
SCHEDULE AN APPOINTMENT AT
YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

42420 MILES

DATE: 03/02/2009

REPAIR# 0615123

REPORTED BY: Lexus of Rockville Centre

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY ~|~C/S
DRIVERS MIRROR IS INOP. ~|~CHECK
D/S MIRROR. MIRROR ASSEMBLY IS
FAULTY..INTERNAL ELECTRICAL
FAILURE.. ~|~ORDRED PARTS.. WILL
CALL CUSTOMER WHEN PART IS
IN....THANKS MIKE

SERVICE: INSPECT BATTERY

CHARGE LEVEL INSPECT BATTERY
CHARGE LEVEL
DESCRIPTION: INSPECT BATTERY
CHARGE LEVEL ~|~C/S PLEASE
CHECK BATTERY AND CHARGING
SYST...MUSTJUMP START VEHICLE
ALL THE TIME.... ~|~CHECK BATTERY.
PERFORMED BATTERY TEST FAILED.
CODE A03P ~|~REPLACED BATTERY
UNIT OPCODE 190011 .3 COMBO
BATTERY TEST 190011A .3 T171 T271

SERVICE: LUBE OIL AND FILTER

DESCRIPTION: LUBE OIL AND
FILTER ~|~CUSTOMER STATES PLEASE
PERFORM LUBE OIL AND FILTER
CHANGE ~|~PERFORMED LUBE OIL
AND FILTER ~|~PERFORMED LUBE
OIL AND FILTER

SERVICE: TENTATIVE APPT.

DESCRIPTION: TENTATIVE APPT.

~|~WE HAVE MADE A TENTATIVE
APPOINTMENT FOR YOU 6 MONTHS
FROM TODAY. OUR APPOINTMENT
DESK WILL CONTACT YOU ONE
WEEK PRIOR TO YOUR DATE TO
SCHEDULE AN APPOINTMENT AT
YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

42607 MILES

DATE: 02/26/2009

REPAIR# 0615490

REPORTED BY: Lexus of Rockville Centre

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY ~|~C/S
DRIVERS MIRROR IS INOP.,INSTALL
SOP MIRROR ~|~MIRROR ADJUSTED
WAS NOT WORKING ~|~REPLACED
D/S FRONT MIRROR ASSEMBLY 752051
.40 T172 T299

SERVICE: TENTATIVE APPT.

DESCRIPTION: TENTATIVE APPT.
~|~WE HAVE MADE A TENTATIVE
APPOINTMENT FOR YOU 6 MONTHS
FROM TODAY. OUR APPOINTMENT
DESK WILL CONTACT YOU ONE
WEEK PRIOR TO YOUR DATE TO
SCHEDULE AN APPOINTMENT AT
YOUR CONVENIENCE. ~|~TENT APPT
~|~TENT APPT

42372 MILES

DATE: 02/23/2009

REPAIR# 0615038

REPORTED BY: Lexus of Rockville Centre

SERVICE: INSPECT BATTERY

CHARGE LEVEL

DESCRIPTION: INSPECT BATTERY
CHARGE LEVEL ~|~JUMP START
9018507 120 GOLD PLACE/WOODS AVE
MALVERNE CALL CST UPON
ARRIVAL ~|~ ~|~ROASIDE
ASSISTANCE 42,372 MILES

29624 MILES

DATE: 05/13/2008

REPAIR# 0295339

REPORTED BY: Lexus of Rockville Centre

SERVICE: WHEELS & TIRES

DESCRIPTION: WHEELS & TIRES

~|~CUSTOMER STATES TIRE PRESSURE
LIGHT ON ~|~ ~|~RESET LIGHT

28796 MILES

DATE: 04/23/2008

REPAIR# 0293914

REPORTED BY: Lexus of Rockville Centre

SERVICE: 30,000 MILE SERVICE

DESCRIPTION: 30,000 MILE SERVICE

~|~REPLACE ENGINE OIL AND OIL
FILTER REPLACE A/C FILTER REPLACE
BRAKE FLUID REPLACE ENGINE AIR
FILTER RE-TORQUE AXLE SHAFT
FLANGE BOLTS ROAD TEST ROTATE
TIRES INSPECT FUEL LINE AND
VAPOR SYSTEM INSPECT FUEL TANK
CAP GASKET INSPECTION 1: BALL
JOINTS AND DUST ~|~
~|~PERFORMED 30K SERVICE

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY

~|~CRUISE CONTROL DOES NOT
WORK ~|~ ~|~TESTED CRUISE
CONTROL SYSTEM AND IS
OPERATING PROPERLY. ACCESSORY
~|~CUSTOMER STATES CHECK
GARAGE DOOR OPENER ITS ON
VISOR ~|~DO NOT KNOW IF
CUSTOMERS GARAGE DOOR REMOTE
IS WORKING. PERFORMED
PROGRAMMING PROCEDURE WITH
VEHICLE BUT DO NOT KNOW IF
REMOTE IS WORKING GARAGE
MOTOR HAS ROLLING CODE.

SERVICE: WHEELS & TIRES

DESCRIPTION: WHEELS & TIRES

~|~CUST HEARS A NOISE-NOT SURE IF
IT IS TIRES OR SOMETHING ELSE AT
ABOUT 20 MPH ~|~HEARD A
CLICKING NOISE ON INITIAL ROAD
TEST. ~|~FOUND LARGE NAIL IN
PASSENGER SIDE FRONT TIRE.
CUSTOMER DECLINED REPAIR

24706 MILES

DATE: 01/31/2008

REPAIR# 0287773

REPORTED BY: Lexus of Rockville Centre

SERVICE: FRONT/REAR BODY

FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY

~|~CK FOR ALL LIGHTS AND SYSTEMS
WORKING OK ... ~|~BATTERY IS
WEAK. ALL OTHER SYSTEMS CHECK
OK. ~|~PERFORMED BATTERY TEST,
NO GOOD, CODE C0PP. R&R BATTERY.
CHECKED FOR PARASITIC DRAW, OK
@ 49MA. 190011A .6

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CUST

STATES BATTERY WENT DEAD HAD
TO JUMP START NOW HEATER INOP
AND PASS SIDE LIGHTS DASH INOP
AND NAV INOP ?? ~|~WIRE FOR
RADIO FUSE BACKED OUT OF
TERMINAL IN PASSENGER SIDE
JUNCTION BLOCK, BLOWN 7.5A
RADIO FUSE. ~|~R&R JB TO SECURE
TERMINAL. R&R FUSE, RECHECKED
RADIO/CLIMATE CONTROL
OPERATION, OK.

10303 MILES

DATE: 10/10/2006

REPAIR# 0252582

REPORTED BY: Lexus of Rockville Centre

SERVICE: 10,000 MILE SERVICE

DESCRIPTION: 10,000 MILE SERVICE

~|~REPLACE ENGINE OIL AND OIL
FILTERS ROAD TEST ROTATE TIRES
REPLACE A/C FILTER VISUALLY
INSPECT BRAKE PADS AND ROTORS
~|~ ~|~DONE.

SERVICE: NYSI SAFETY ONLY

DESCRIPTION: NYSI SAFETY ONLY

~|~CUSTOMER REQUESTS NEW YORK
STATE SAFETY INSPECTION.
~|~INSPECTION DUE ~|~INSPECTION
COMPLETED.

5215 MILES

DATE: 01/31/2006

REPAIR# 0235750

REPORTED BY: Lexus of Rockville Centre

SERVICE: 25000 MILE SERVICE NON
WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE

NON WARRANTY-NON OEM
~|~REPLACE ENGINE OIL & FILTER,
ROTATE TIRES, INSPECT WIPER

SERVICE: WINDSHIELD

WIPER/WASHER

DESCRIPTION: WINDSHIELD

WIPER/WASHER ~|~CHK FRNT
WIPERS LEAVING STREAKS ~|~WIPER

BLADES, INSPECT BATTERY &
CONNECTIONS, LUBE HINGES.
CHECK & REPLENISH ALL FLUID
LEVELS. INSPECT AIR FILTER. CHECK
ALL INSTRUMENTS, ACCESSORIES &
LIGHTS. CHECK TIRE WEAR & RESET
TIRE PRESSURE. ROAD T

~|~=====

=====

~|~PERFORMED 5K MILE SERVICE

INSERTS WARPED ~|~REMOVED AND
REPLACED WIPER INSERTS

10 MILES

DATE: 11/07/2005

REPAIR# 0228896

REPORTED BY: Lexus of Rockville Centre

SERVICE: NON-OEM THEFT

DETERRENT SYSTEM INSTALL/R&R

DESCRIPTION: NON-OEM THEFT

DETERRENT SYSTEM INSTALL/R&R

~|~SUPPLY WALET KEY ~|~ ~|~DONE.

SERVICE: NYSI SAFETY ONLY

DESCRIPTION: NYSI SAFETY ONLY

~|~CUSTOMER REQUESTS NEW YORK
STATE SAFETY INSPECTION.

~|~INSPECTION DUE ~|~INSPECTION
COMPLETED.

11 MILES

DATE: 07/08/2005

REPAIR# 0221164

REPORTED BY: Lexus of Rockville Centre

SERVICE: NON WARRANTABLE

OPERATION CODE

DESCRIPTION: NON WARRANTABLE

OPERATION CODE ~|~CLEAN/WAX

SERVICE: NYS SAFETY INSPECT

DESCRIPTION: NYS SAFETY INSPECT

~|~#11182358 ~|~REQUIRED

~|~COMPLETED

5 MILES

DATE: 04/20/2005

REPAIR# 0215721

REPORTED BY: Lexus of Rockville Centre

SERVICE: PRE-DELIVERY SERVICE

FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY

SERVICE FOR USA ALL ALTITUDES

~|~PERFORM PRE-DELIVERY

INSPECTION PRE-DELIVERY SERVICE

FOR USA ALL ALTITUDES

~|~PERFORM PRE-DELIVERY

INSPECTION

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus dealership that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) ([//www.lexus.com/privacy/online-statement](http://www.lexus.com/privacy/online-statement)).