

SERVICE HISTORY

SERVICE HISTORY FOR: SANTAANAWHITE07L

VIN: JTHGL46F975017562

118084 MILES

DATE: 01/17/2017

REPAIR# 0427602

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: SAFETY INSPECTION

DESCRIPTION: SAFETY INSPECTION ~|-PERFORM SAFETY INSPECTION ~|~ ~|-COMPLETE

SERVICE: WHOLESALE INSPECTION

DESCRIPTION: WHOLESALE INSPECTION ~|-BELL LEXUS NORTH SCOTTSDALE WHOLESALE PREP. INCLUDES FULL MINI DETAIL, VACUUM, SHINE TIRES, WALKAROUND INSPECTION, AND PLATE FRAME ~|~

118007 MILES

DATE: 01/13/2017

REPAIR# 0427131

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: LOANER CAR BLNS

DESCRIPTION: LOANER CAR BLNS ~|-BELL LEXUS NORTH SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS TAKEN. A \$7.45 FUEL CONVENIENCE FEE HAS BEEN ADDED. PLEASE RETURN THE LOANER VEHICLE 4-6 BUSINESS HOURS AFTER YOUR VEHICLE HAS BEEN ~|~ ~|-LOANER#..... RETURN DATE..... CUST.....

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|-REPLACE A/C AIR FILTER. ~|~ ~|-REPLACED A/C FILTER(S)

SERVICE: SEE SECTION

DESCRIPTION: SEE SECTION ~|-CLIENT STATES GETS BURNING SMELL WHEN CAR IS RUNNING, CK AND ADVISE ~|-CUASED BY OIL LEAKAGE FROM FRONT ENGINE COVER. OIL GETTING ON EXHAUST AND BURNING CAUSING SMELL. ~|-NEEDS FRONT TIMING COVER RESEAL, CLIENT DECLINED CHARGES ARE FOR DIAGNOSIS

110946 MILES

DATE: 06/28/2016

REPAIR# 0406162

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: LOANER CAR BLNS

DESCRIPTION: LOANER CAR BLNS ~|-BELL LEXUS NORTH SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS TAKEN. A \$7.45 FUEL CONVENIENCE FEE HAS BEEN ADDED. PLEASE RETURN THE LOANER VEHICLE 4-6 BUSINESS HOURS AFTER YOUR VEHICLE HAS BEEN ~|~ ~|-LOANER#..... RETURN DATE..... CUST.....

SERVICE: SKID CONTROL COMPUTER ASSY

DESCRIPTION: SKID CONTROL COMPUTER ASSY ~|-CLIENT STATES BRAKE PAD WARNING LIGHT IS ON, CK AND ADVISE ~|-REPLACED WORN FRONT BRAKE PADS, REPLACED WEAR INDICATOR, RESURFACED DISCS

103512 MILES

DATE: 11/30/2015

REPAIR# 0383660

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 100,000 MILE CLUB

DESCRIPTION: 100,000 MILE CLUB ~|~100,000 MILE CLUB MEMBER DISCOUNT ~|~ ~|~THANKS FOR YOUR BUSINESS!

SERVICE: LOANER CAR BLNS

DESCRIPTION: LOANER CAR BLNS ~|~BELL LEXUS NORTH SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS TAKEN. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$65.00 RENTAL FEE, PER DAY WILL BE ADDED TO YOUR INVOICE LOANER#.... ~|~ ~|~E

SERVICE: ENGINE NOISE

DESCRIPTION: ENGINE NOISE ~|~CUSTOMER STATES ENGINE MAKES NOISE DESCRIBED AS:CHIRPING SOUND FROM FRONT OF ENGINE WHEN RUNNING ~|~UPON INSPECTION FOUND SERP BELT TENSIONER BEARING WORN ~|~REPLACED TENSIONER PULLEY AND SERP BELT

98725 MILES

DATE: 07/08/2015

REPAIR# 0368840

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: LOANER CAR BLNS

DESCRIPTION: LOANER CAR BLNS ~|~BELL LEXUS NORTH SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS TAKEN. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$65.00 RENTAL FEE, PER DAY WILL BE ADDED TO YOUR INVOICE LOANER#.... ~|~

SERVICE: SAFETY RECALL ELF

DESCRIPTION: SAFETY RECALL ELF ~|~INSPECT FOR FUEL PRESSURE SENSOR LEAK, CAMPAIGN ELF ~|~VEHICLE QUALIFIES FOR ELF CAMPAIGN ~|~COMPLETE

SERVICE: WATER PUMP

DESCRIPTION: WATER PUMP ~|~REPLACE LEAKING WATER PUMP ~|~WATER PUMP LEAKING FROM FAILED SEAL ~|~REPLACED WATER PUMP

SERVICE: OIL LEAKS

DESCRIPTION: OIL LEAKS ~|~DIAGNOSE OIL LEAKS CLIENT STATES SEES FLUID LEAK UNDER FRONT OF CAR, CK AND ADVISE ~|~FOUND GASKETS BETWEEN VALVE COVERS AND FUEL PUMPS LEAKING, BOTH SIDES ~|~RESEALED FUEL PUMPS, BOTH SIDES

SERVICE: SHOCKS/STRUTS

DESCRIPTION: SHOCKS/STRUTS ~|~R/F SHOCK IS LEAKING ~|~SEAL FAILED ~|~REPLACED BOTH FRONT SHOCKS

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~|~PERFORM FOUR WHEEL ALIGNMENT ~|~ ~|~ADJUST CASTER, CAMBER AND TOE TO FACTORY SPECIFICATION ROAD TEST & COMPLETE.

91422 MILES

DATE: 10/21/2014

REPAIR# 0342038

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: *ROTATE&ROAD FORCE

DESCRIPTION: *ROTATE&ROAD FORCE ~|~PERFORM ROAD FORCE BALANCE OF ALL FOUR TIRES ~|~. ~|~COMPLETED

SERVICE: 90000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 90000 MILE SERVICE NON WARRANTY-NON OEM ~|~PERFORM 90,000 MILE SERVICE CHANGE ENGINE OIL & FILTER. LUBRICATE ALL VEHICLE HINGES CHANGE ENGINE COOLANT & INSPECT COOLING SYSTEM. REPLACE FUEL TANK CAP GASKET & TEST EVAP/EMISSIONS SYSTEM. CLEAN THROTTLE BODY & ADD FUEL SYSTEM CONDITIONER ROTATE TIRES ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~90,000 MILE SERVICE PERFORMED BRAKES FRONT 6MM REAR 9MM TIRES FRONT AND REAR 5/32

SERVICE: DETAIL
DESCRIPTION: DETAIL ~!~EXECUTIVE HAND WAX & DETAIL
169.95 ~!~ ~!~COMPLETED

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
~!~REPLACE A/C AIR FILTER. ~!~ ~!~REPLACED A/C FILTER(S)

SERVICE: LOANER CAR BLNS
DESCRIPTION: LOANER CAR BLNS ~!~BELL LEXUS NORTH
SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE
ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS
TAKEN. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS
FINISHED OR A \$65.00 RENTAL FEE, PER DAY WILL BE ADDED TO
YOUR INVOICE LOANER#..... ~!~

SERVICE: WHEEL ALIGNMENT
DESCRIPTION: WHEEL ALIGNMENT ~!~PERFORM FOUR WHEEL
ALIGNMENT ~!~ ~!~PERFORMED FOUR WHEEL ALIGNMENT

86647 MILES

DATE: 05/22/2014

REPAIR# 0327233
REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 85000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 85000 MILE SERVICE NON WARRANTY-NON OEM
~!~PERFORM 85,000 MILE SERVICIE. CHANGE ENGINE OIL AND
FILTER. ROTATE TIRES, SET TIRE PRESSURE INCLUDING SPARE.
CHECK CONDITION OF TIRES MEASURE TREAD DEPTH. CHECK ALL
FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION.
SERVICE BATTERY. LOAD TEST, CLEAN ~!~SCHEDULED
MAINTENANCE DUE TO TIME OR MILEAGE ~!~CLIENT JUST HAD
CAR SERVICED AT AFTERMARKET SHOP NO SERVICING DONE
TODAY

SERVICE: SKID CONTROL COMPUTER ASSY
DESCRIPTION: SKID CONTROL COMPUTER ASSY ~!~CLIENT
STATES FEELS VIB IN STEERING WHEEL WHEN BRAKING FROM
FWY SPEED ~!~FOUND FRONT ROTORS WARPED ~!~RESURFACED
FRONT ROTORS, SCUFFED PADS AND LUBED CALIPER PINS

SERVICE: LOANER CAR BLNS
DESCRIPTION: LOANER CAR BLNS ~!~BELL LEXUS NORTH
SCOTTSDALE IS PROVIDING THIS LOANER AS A COURTESY. WE
ASK ONLY THAT IT BE RETURNED IN THE CONDITION IT WAS
TAKEN. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS
FINISHED OR A \$65.00 RENTAL FEE, PER DAY WILL BE ADDED TO
YOUR INVOICE LOANER#..... ~!~

80884 MILES

DATE: 11/18/2013

REPAIR# 0542258
REPORTED BY: Earnhardt Lexus

SERVICE: BALANCE TIRES (ROTATE WHEN APPLICABLE)
DESCRIPTION:

SERVICE: MAILER DISCOUNT APPLIED
DESCRIPTION: MAILER DISCOUNT APPLIED ~!~MAILER
DISCOUNT APPLIED ~!~

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: INSPECT BRAKE PADS AND/OR LININGS, ROTORS
AND/OR DRUMS
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: SERVICE - 80,000 MILES
DESCRIPTION: SERVICE - 80,000 MILES ~!~SERVICE - 80,000 MILES
~!~ ~!~80884 190 80 K PERFORMED REMAINING TIRE TREAD AND
BRAKE MEASUREMENT LEFT FRONT EDGE :4RIGHT FRONT EDGE :4
LEFT FRONT CENTER :7RIGHT FRONT CENTER :7 LEFT REAR EDGE
:4RIGHT REAR EDGE :4 LEFT REAR CENTER :6RIGHT REAR CENTER
:6 BRAKE PADS REMAINING IN MILLIME

REPAIR# 0535020**REPORTED BY:** Earnhardt Lexus**SERVICE:** APPLICABLE)**DESCRIPTION:****SERVICE:** BRAKE GROUP**DESCRIPTION:** BRAKE GROUP ~|~CLIENT STATES HEARS WHINE OR SQUEAK FROM BRAKE PEDAL WHEN APPLIED ~|~ ~|~75901 COULD NOT DUPLICATE CLIENTS COMPLAINT. OK AT THIS TIME.**SERVICE:** INSERTS (FRONT)**DESCRIPTION:****SERVICE:** INSPECT BRAKE LINES, HOSES AND CONNECTIONS**DESCRIPTION:****SERVICE:** INSPECT DRIVE AXLE BOOTS**DESCRIPTION:****SERVICE:** INSPECT ENGINE COOLANT LEVEL**DESCRIPTION:****SERVICE:** INSPECT RACK AND PINION ASSEMBLY**DESCRIPTION:****SERVICE:** INSPECT STEERING OPERATION AND LINKAGE**DESCRIPTION:****SERVICE:** MAILER DISCOUNT APPLIED**DESCRIPTION:** MAILER DISCOUNT APPLIED ~|~MAILER DISCOUNT APPLIED ~|~ ~|~75901 MAILER MAILER**SERVICE:** REPLACE AIR FILTER**DESCRIPTION:****SERVICE:** REPLACE ENGINE OIL FILTER**DESCRIPTION:****SERVICE:** RESET SERVICE INDICATOR**DESCRIPTION:****SERVICE:** SERVICE - 75,000 MILES**DESCRIPTION:** SERVICE - 75,000 MILES ~|~SERVICE - 75,000 MILES ~|~ ~|~75901 75K SERVICE. LABOR TIME=2.8 280 PERFORMED 75K SERVICE. LABOR TIME=2.8REMAINING TIRE TREAD AND BRAKE MEASUREMENTLEFT FRONT EDG5RIGHT FRONT EDG5LEFT FRONT CTR7 RIGHT FRONT CTR7LEFT REAR EDG6 RIGHT REAR EDG5LEFT REAR CTR7 RIGHT REAR CTR7 BRAKE PADS REM**SERVICE:** BALANCE TIRES (ROTATE WHEN**DESCRIPTION:****SERVICE:** CABIN FILTER**DESCRIPTION:****SERVICE:** INSPECT BODY PAINT AND CORROSION**DESCRIPTION:****SERVICE:** INSPECT BRAKE PADS AND/OR LININGS, ROTORS AND/OR DRUMS**DESCRIPTION:****SERVICE:** INSPECT DRIVE BELT(S)**DESCRIPTION:****SERVICE:** INSPECT EXHAUST SYSTEM AND HEAT SHIELDS**DESCRIPTION:****SERVICE:** INSPECT REAR DIFFERENTIAL FLUID LEVEL**DESCRIPTION:****SERVICE:** INSPECT SUSPENSION BALL JOINTS**DESCRIPTION:****SERVICE:** REPLACE AIR CONDITIONER**DESCRIPTION:****SERVICE:** REPLACE ENGINE OIL**DESCRIPTION:****SERVICE:** REPLACE WINDSHEILD WIPER**DESCRIPTION:****SERVICE:** ROAD TEST**DESCRIPTION:****REPAIR#** 0525108**REPORTED BY:** Earnhardt Lexus

SERVICE: APPLICABLE)

DESCRIPTION:

SERVICE: CHASSIS ELECTRICAL

DESCRIPTION: CHASSIS ELECTRICAL ~|~REPLACE BATT'S IN BOTH KEYS ~|~ ~|~70490 KEY BATTERIES REPLACED BOTH KEY BATTERIES

SERVICE: INSPECT BRAKE PADS AND/OR LININGS, ROTORS AND/OR DRUMS

DESCRIPTION:

SERVICE: PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE I/S 2.20

DESCRIPTION: PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE I/S 2.20 ~|~PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE I/S 2.20 ~|~ ~|~70490 REAR BRAKE PADS ARE AT 2MM REMAINING 220 REPLACED REAR BRAKE PADS AND RE-SURFACED REAR ROTORS 2.20

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: BALANCE TIRES (ROTATE WHEN

DESCRIPTION:

SERVICE: DEFAULT

DESCRIPTION: DEFAULT ~|~CUSTOMER REQUESTED A LOANER ~|~ ~|~70490 LOANER CAR

SERVICE: MAILER DISCOUNT APPLIED

DESCRIPTION: MAILER DISCOUNT APPLIED ~|~MAILER DISCOUNT APPLIED ~|~ ~|~70490 MAILER DISCOUNT

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: SERVICE - 70,000 MILES

DESCRIPTION: SERVICE - 70,000 MILES ~|~SERVICE - 70,000 MILES ~|~ ~|~70490 SERVICE DUE BY TIME OR MILEAGE 190 PERFORMED 70,000 MILE SERVICE 1.90 TIRE TREAD REMAINING IN MILLIMETERS LEFT FRONT EDGE=5 RIGHT FRONT EDGE=5 LEFT FRONT CENTER=8 RIGHT FRONT CENTER=8 LEFT REAR EDGE=4 RIGHT REAR EDGE=4 LEFT REAR CENTER=8 RIGHT REAR

66879 MILES

DATE: 09/14/2012

REPAIR# 0516358

REPORTED BY: Earnhardt Lexus

SERVICE: TIRES & WHEELS GROUP

DESCRIPTION: TIRES & WHEELS GROUP ~|~CLIENT STATES R/R TIRE LOSES AIR, INSTALLED HERE 8 7 12 AT 65312 MI ~|~ ~|~66879 50 MOUNTED AND BALANCED RIGHT REAR TIRE UNDER ROAD HAZARD WARRENTY

65312 MILES

DATE: 08/07/2012

REPAIR# 0514039

REPORTED BY: Earnhardt Lexus

SERVICE: APPLICABLE)

DESCRIPTION:

SERVICE: BODY (WINDOW/DOOR)

DESCRIPTION: BODY (WINDOW/DOOR) ~|~REPLACE WORN FLOOR MATS WITH DARK FLOOR MATS

SERVICE: INSPECT BRAKE PADS AND/OR LININGS, ROTORS AND/OR DRUMS

DESCRIPTION:

SERVICE: BALANCE TIRES (ROTATE WHEN

DESCRIPTION:

SERVICE: DETAIL CAR

DESCRIPTION: DETAIL CAR ~|~DETAIL CAR

SERVICE: MAILER DISCOUNT APPLIED

DESCRIPTION: MAILER DISCOUNT APPLIED ~|~MAILER DISCOUNT APPLIED

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: SERVICE - 65,000 MILES

DESCRIPTION: SERVICE - 65,000 MILES ~|~SERVICE - 65,000 MILES ~|~ ~|~65308 70 PERFORMED 65,000 MILE SERVICE LESS ROTATE AND BALANCE DUE TO TIRE CONDITION TIRE TREAD REMAINING IN MILLIMETERSLEFT FRONT EDG8RIGHT FRONT EDG8LEFT FRONT CTR8RIGHT FRONT CTR8LEFT REAR EDG8RIGHT REAR EDG8LEFT REAR CTR8RIGHT REAR CTR8 BRAKE PADS REM

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: TIRES & WHEELS GROUP

DESCRIPTION: TIRES & WHEELS GROUP ~|~MOUNT AND BALANCE 4 TIRES, B STONE ~|~ ~|~65312 TIRE WEAR 240 MOUNTED AND BALANCED 4 BRIDGESTONE TIRES TIRES & WHEELS GROUP ~|~PERFORM 4 WHEEL ALIGNMENT ~|~ ~|~65312 NEW TIRES INSTALLED 200 PERFORMED FOUR WHEEL ALIGNMENT

60090 MILES

DATE: 04/27/2012

REPAIR# 0508235

REPORTED BY: Earnhardt Lexus

SERVICE: APPLICABLE)

DESCRIPTION:

SERVICE: BRAKE GROUP

DESCRIPTION: BRAKE GROUP ~|~REPLACE WORN FRONT BRAKES AND RESURFACE ROTORS ~|~ ~|~60090 FRONT PADS LOW WHILE DOING SERVICE FOUND FRONT PADS AT 3MM. REPLACED FRONT PADS AND TURNED ROTORS 2.2 HRS.

SERVICE: INSPECT BRAKE LINES, HOSES AND CONNECTIONS

DESCRIPTION:

SERVICE: INSPECT DRIVE BELT(S)

DESCRIPTION:

SERVICE: INSPECT ENGINE VALVES (AUDIBLE)

DESCRIPTION:

SERVICE: INSPECT FUEL TANK, CAP, LINE AND HOSES

DESCRIPTION:

SERVICE: INSPECT REAR DIFFERENTIAL FLUID LEVEL

DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS

DESCRIPTION:

SERVICE: INSTALL FUEL INJECTION ADDITIVE

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: REPLACE WINDSHEILD WIPER

DESCRIPTION:

SERVICE: SERVICE - 60,000 MILES

DESCRIPTION: SERVICE - 60,000 MILES ~|~SERVICE - 60,000 MILES

SERVICE: BALANCE TIRES (ROTATE WHEN

DESCRIPTION:

SERVICE: INSERTS (FRONT)

DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS

DESCRIPTION:

SERVICE: INSPECT ENGINE COOLANT LEVEL

DESCRIPTION:

SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS

DESCRIPTION:

SERVICE: INSPECT RACK AND PINION ASSEMBLY

DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE

DESCRIPTION:

SERVICE: INSPECT TRANSMISSION FOR LEAKS

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE GAS CAP GASKET,

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

~|~60090 60K COMPLETED 60K SERVICE 9QTS. 5W-20 4.5
HRS.REMAINING TIRE TREAD AND BRAKE MEASUREMENT LEFT
FRONT EDG4RIGHT FRONT EDG4 LEFT FRONT CTR3 RIGHT FRONT
CTR3 LEFT REAR EDG4 RIGHT REAR EDG4 LEFT REAR CTR4 RIGHT
REAR CTR4 BRAKE PADS REMAIN IN MILLIMETERS

50075 MILES

DATE: 06/29/2011

REPAIR# 0241748

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~LUBE
OIL AND FILTER ~|~LUBE OIL AND FILTER 2417751236 NON
WARRANTABLE OPERATION CODE ~|~REPLACE A/C AIR FILTER. ~|~
~|~REPLACED A/C FILTER(S) NON WARRANTABLE OPERATION
CODE ~|~CUSTOMER HAS DECLINED FACTORY RECOMMENDED
SERVICE ~|~NOTED NON WARRANTABLE OPERATION CODE
~|~INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER
FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL
AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR
VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL
BE ADDED TO YOUR INVOICE LOANER# ~|~ ~|~LOANER

42484 MILES

DATE: 11/16/2010

REPAIR# 0222532

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: VALVE SPRINGS

DESCRIPTION: VALVE SPRINGS ~|~PERFORM ALE CAMPAIGN ~|~
~|~PERFORMED ALE CAMPAIGN

35903 MILES

DATE: 05/19/2010

REPAIR# 0207694

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 35000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 35000 MILE SERVICE NON WARRANTY-NON OEM
~|~PERFORM 35,000 MILE SERVICE CHANGE OIL AND OIL FILTER
ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS
ALIGNMENT WEAR. CHECK ALL FLUID LEVELS AND TOP OFF AS
NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVELS
AND CABLE ENDS. CHECK POWER STEERING FLUID
~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
~|~35,000 MILE SERVICE PERFORMED TIRES 9/32 BRAKES FR 6+MM
REARS 6+MM

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER
FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL
AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR
VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL
BE ADDED TO YOUR INVOICE LOANER# ~|~ ~|~LOANER

30779 MILES

DATE: 12/23/2009

REPAIR# 0194698

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 04 30,000 MILE SVC

SERVICE: ACCESSORY

DESCRIPTION: 04 30,000 MILE SVC ~!-PERFORM 30,000 MILE SERVICE. CHANGE OIL & FILTER. LUBE ALL HINGES. INSPECT COOLING SYSTEM & TRANSMISSION FLUID. INSPECT EVAPORATIVE EMISSION SYSTEM & FUEL TANK CAP GASKET. CLEAN THROTTLE BODY AND ADD FUEL SYSTEM CLEANER. ROTATE TIRES & CHECK TIRE PRESSURE ~!-SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~!-30,000 MILE SERVICE PERFORMED TIRES 10/32 BRAKES FR 7MM REARS 8MM

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~!-REPLACE A/C AIR FILTER. ~!- ~!-REPLACED A/C FILTER(S) NON WARRANTABLE OPERATION CODE ~!-INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# ~!- ~!-LOANER

DESCRIPTION: ACCESSORY ~!-INSTALL SOP FLOOR MATS ~!- ~!-INSTALLED

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~!-PERFORM FOUR WHEEL ALIGNMENT MAINTENANCE ~!- ~!-PERFORMED FOUR WHEEL ALIGNMENT

25620 MILES

DATE: 07/29/2009

REPAIR# 0753414

REPORTED BY:

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~!-CUSTOMER REQUESTS 25000 MILE SERVICE ~!-SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~!-TIRES F=5MM R=6MM FRONT TIRES WEARING ON INSIDE EDGE.

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~!-GUEST STATES THAT THE A/C FILTER LIGHT IS ON, PLEASE INSPECT AND REPLACE IF NEEDED ~!-CHECKED A/C FILTER AT 6 SUGGEST REPLACE NEXT SERVICE. ~!-FILTER AT 6

SERVICE: INSPECTION SHEET

DESCRIPTION: INSPECTION SHEET ~!-PLEASE PERFORM LEXUS OF COLORADO SPRINGS MULTI POINT INSPECTION ~!-LOCS INSPECTION ~!-LOCS MULTI POINT INSPECTION COMPLETED. SERVICE CONSULTANT TO REVIEW FINDINGS WITH GUEST AND PROVIDE COPY.

20365 MILES

DATE: 03/09/2009

REPAIR# 0169808

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 20000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 20000 MILE SERVICE NON WARRANTY-NON OEM ~!-PERFORM 20,000 MILE SERVICE, CHANGE OIL AND OIL FILTER ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS ALIGNMENT WEAR. CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVEL AND CABLE ENDS. CHECK POWER STEERING FLUID ~!-SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~!-20,000 MILE SERVICE PERFORMED TIRES FR 7/32 REARS 6/32 BRAKES 10MM

SERVICE: FUEL DELIVERY PIPES

DESCRIPTION: FUEL DELIVERY PIPES ~!-PERFORM SERVICE CAMPAIGN 9LA ~!- ~!-PERFORMED 9LA CAMPAIGN

15297 MILES

DATE: 09/24/2008

REPAIR# 0155907

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 15000 MILE SERVICE NON WARRANTY

DESCRIPTION: 15000 MILE SERVICE NON WARRANTY

~|~PERFORM 15,000 MILE SERVICE CHANGE OIL AND OIL FILTER ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS ALIGNMENT WEAR. REPLACE AIR FILTER CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVEL AND CABLE ENDS INSPECT EX ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~15,000 MILE SERVICE PERFORMED TIRES FR 8/32 REARS 9/32 BRAKES 10MM

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~|~PERFORM FOUR WHEEL ALIGNMENT MAINTENANCE ~|~PERFORMED FOUR WHEEL ALIGNMENT

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE

~|~REPLACE A/C AIR FILTER. ~|~REPLACED A/C FILTER(S) NON WARRANTABLE OPERATION CODE ~|~PERFORM 4 WHEEL SPIN BALANCE MAINTENANCE ~|~BALANCED ALL FOUR TIRES NON WARRANTABLE OPERATION CODE ~|~INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER# ~|~LOANER

316 MILES

DATE: 05/16/2008

REPAIR# 0307237

REPORTED BY: Kuni Lexus of Portland

SERVICE: 1,000 MILE SERVICE

DESCRIPTION: 1,000 MILE SERVICE ~|~CUSTOMER REQUESTS 30 DAY INSPECTION. ~|~INSPECT ALL FLUID LEVELS. INSPECT STEERING SYSTEM, BODY, CHASSIS, AND NUTS AND BOLTS. INSPECT BATTERY, BELTS, HOSES, AND TIRE PRESSURES. ~|~COMPLETED

SERVICE: MISC

DESCRIPTION: MISC ~|~GUEST WOULD LIKE US TO PAIR HIS BLUETOOTH TO HIS VEHICLE. ~|~PAIRED PHONE. LOADED LIST OF NUMBERS IN PHONEBOOK, AND SET EACH NUMBER TO A SPEED DIAL. PER GUEST REQUEST.

10221 MILES

DATE: 04/17/2008

REPAIR# 0141838

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 10000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 10000 MILE SERVICE NON WARRANTY-NON OEM ~|~PERFORM 10,000 MILE SERVICE CHANGE OIL AND OIL FILTER ROTATE TIRES AND CHECK TIRE PRESSURE AS WELL AS ALIGNMENT WEAR. CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED. ADVISE ON CONDITION. CHECK BATTERY WATER LEVELS AND CABLE ENDS CHECK POWER STEERING FLUID A ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~10,000 MILE SERVICE PERFORMED TIRES FR 8/32 REARS 7/32 BRAKES 8-9MM

SERVICE: ELECT/MODULATED AIR SUSPNSN AIRBAG SYSTEM

DESCRIPTION: ELECT/MODULATED AIR SUSPNSN AIRBAG SYSTEM ~|~SEAT BELT WILL NOT RELEASE AT TIMES CUSTOMER HAS TO OPEN THE DOOR FOR SEAT BELT TO RELEASE CUSTOMER STATES THIS HAPPENS WHEN PULLING OUT THE SEAT BELT ~|~INTERNAL FAILURE ~|~REPLACE LEFT FRONT SEAT BELT

SERVICE: FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~|~THERE IS A WIND NOISE FROM THE WINDOWS CUSTOMER STATES ~|~INSULATED MULTIPLE LOCATIONS TO REDUCE WIND NOISE WIND TURBULANCE NOISE, ESPECIALLY IN CROSS WIND CONDITIONS, IS PRESENT IN ALL VEHICLES. THE LS460, WHICH IS A VERY QUIET VEHICLE, MAY TEND TO DRAW ATTENTION TO NORMAL WIND TURBULANCE OR RUSHING SOUNDS BECA ~|~TEST DROVE AFTER REPAIR NO ABNORMAL NOISE HEARD AFTER REPAIR

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$5.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$25.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LOANER#. ~|~LOANER

9360 MILES

DATE: 03/20/2008

REPAIR# 0139143

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 8LA CAMPAIGN

DESCRIPTION: 8LA CAMPAIGN ~~-PERFORM 8LA CAMPAIGN
~~-CAMPAIGN ~~-REPLACED #1 & #2 IDLER PULLEYS

SERVICE: FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~~-CUSTOMER STATES THAT
THERE IS A WIND NOISE FROM THE RIGHT FRONT WINDOW
~~-ORDERED PARTS ~~-WILL NOTIFY CUSTOMER WHEN PARTS
ARRIVE

5109 MILES

DATE: 11/12/2007

REPAIR# 0126739

REPORTED BY: Bell Lexus North Scottsdale

SERVICE: 5,000 MILE SERVICE

DESCRIPTION: 5,000 MILE SERVICE ~~-PERFORM 5,000 MILE
SERVICE CHANGE OIL AND OIL FILTER AND ROTATE TIRES CHECK
TIRE PRESSURE AS WELL AS CONDITION OF TIRE. INSPECT AIR
FILTER CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED.
ADVISE ON CONDITION. CHECK BATTERY WATER LEVELS AND
CABLE ENDS. INSPC ~~-SCHEDULED MAINTENANCE DUE TO TIME
OR MILEAGE ~~-5000 MILE SERVICE PERFORMED TIRES 9/32
BRAKES 12MM

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
~~-INSTRUCTION/NOTES BELL LEXUS HAS PROVIDED A LOANER
FOR YOU. WE ONLY ASK A \$5.00 PARTICIPATION TO OFFSET FUEL
AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR
VEHICLE IS FINISHED OR A \$25.00 RENTAL CHARGE PER DAY WILL
BE ADDED TO YOUR INVOICE LOANER#. ~~- ~~-LOANER

1485 MILES

DATE: 07/30/2007

REPAIR# 0280882

REPORTED BY: Kuni Lexus of Portland

SERVICE: 1,000 MILE SERVICE

DESCRIPTION: 1,000 MILE SERVICE ~~-CUSTOMER REQUESTS 30
DAY INSPECTION. . ~~-INSPECT ALL FLUID LEVELS. INSPECT
STEERING SYSTEM, BODY, CHASSIS, AND NUTS AND BOLTS.
INSPECT BATTERY, BELTS, HOSES, AND TIRE PRESSURES. .
~~-PERFORMED 30 DAY INSPECTION AS REQUESTED

SERVICE: LEXUS PERSONALIZED SETTINGS

DESCRIPTION: LEXUS PERSONALIZED SETTINGS ~~-CUSTOMER
WOULD LIKE THE C-BEST ADJUSTED /NO ADJUSTMENTS/ ~~-
~~-ADJUSTED C-BEST

10 MILES

DATE: 06/04/2007

REPAIR# 0275108

REPORTED BY: Kuni Lexus of Portland

SERVICE: NEW CAR DETAIL

DESCRIPTION: NEW CAR DETAIL ~~-PLEASE PERFORM
COMPLETE NEW CAR DETAIL AS REQUIRED. ~~- ~~-DONE.

SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES
~~-PLEASE PERFORM PDI AS REQUIRED BY FACTORY ~~- ~~-PDI
DONE

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contain in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) ([//www.lexus.com/privacy/online-statement](http://www.lexus.com/privacy/online-statement)).