

SERVICE HISTORY**SERVICE HISTORY FOR:** 2013SWBNEBULAGRAY**VIN:** JTHBL1EF4D5116652**67478 MILES****DATE:** 12/09/2016**REPAIR#** 0529933**REPORTED BY:** Lexus of Sacramento**SERVICE:** 65K MILE SVC

DESCRIPTION: 65K MILE SVC ~!~CUSTOMER REQUESTS A 65K MILE SERVICE ~!~CUSTOMER REQUESTS A 65K MILE SERVICE ~!~PERFORMED 65K SERVICE, PERFORMED LOF, ROTATED TIRES AND BALANCED FRONT TIRES, L/F 7/32, R/F 7/32, L/R 7/32, R/R 7/32 BRAKES F@7MM...R@8MM, ADDED FUEL ADDITIVE, BATTERY TESTED GOOD AT 667 CCA T=1.0

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
~!~PERFORM OIL AND FILTER CHANGE USING MOBIL 1 OIL ~!~.
~!~PERFORMED OIL AND FILTER CHANGE T=.5

SERVICE: INSPECT TIRE PRESSURE

DESCRIPTION: INSPECT TIRE PRESSURE ~!~CHECK TIRE PRESSURES AND RECORD ON INVOICE ~!~TIRE PRESSURE WAS INSPECTED AND ADJUSTED ~!~TIRE PRESSURE SET AND ADJUSTED BASED ON TIRE TEMPERATURE F@33...R@33

SERVICE: OTHERS

DESCRIPTION: OTHERS ~!~PLEASE CEHCK ENGINE TEMP WHEN RUNNING. CUSTOMER IS QUESTIONI NG IF ITS RUNNING HOT ~!~PERFORMED HEALTH CHECK, ENGINE COOLANT TEMP 192 DEGREES, GUAGE IS AT HALF WAY. NORMAL COOLANT TEMPERATURE AT THIS TIME.

66557 MILES**DATE:** 11/17/2016**REPAIR#** 0528198**REPORTED BY:** Lexus of Sacramento**SERVICE:** FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~!~C/S: CHECK CLOCK /CHECK TSIB CLOCK DOES NOT KEEP TIME CERT ~!~THERE IS A TSIB TO REPLACE THE CLOCK LEXUS EXTRA CARE TO AUTHORIZE REPLACEMENT ~!~REPLACED CLOCK AND UPDATES AS DESIGNED T=.6

SERVICE: INSPECT TIRE PRESSURE

DESCRIPTION: INSPECT TIRE PRESSURE ~!~CHECK TIRE PRESSURES AND RECORD ON INVOICE ~!~TIRE PRESSURE WAS INSPECTED AND ADJUSTED ~!~TIRE PRESSURE SET AND ADJUSTED BASED ON TIRE TEMPERATURE SET ALL TO 35PSI.

62715 MILES**DATE:** 08/03/2016**REPAIR#** 0520099**REPORTED BY:** Lexus of Sacramento**SERVICE:** 60K MILE SVC

DESCRIPTION: 60K MILE SVC ~!~CUSTOMER REQUESTS A 60K MILE SERVICE ~!~CUSTOMER REQUESTS A 60K MILE SERVICE ~!~PERFORM 60K SERVICE. CHANGED OIL AND FILTER W/LUBE STICKER. RESET MAINT.LIGHT. PERFORM INSPECTIONS. TOP OFF FLUIDS. INSP.BRAKES FRONT 6MM REAR 8MM. INSP.TIRES LF 9/8/9 RF 9/8/9 LR 9/9/9 RR 9/9/9. ROTATED TIRES AND BALANCE 4 TIRES. ADD FUEL INJECTOR ADDITI

SERVICE: FRONT AXLE

DESCRIPTION: FRONT AXLE ~!~POPPING NOISE INTERMITTENTLY OCCURS WHEN TURNING FROM UNDER VEHICLE ~!~ROAD TEST VEHICLE AND COULD NOT DUPLICATE POPPING SOUND WHEN TURNING. INSPECTED UNDERNEATH VEHICLE AND FOUND NO DAMAGE AT THIS TIME. CONTROL ARMS IN FRONT HAVE BEEN REPLACED . ~!~NO REPAIRS AT THIS TIME.

SERVICE: INNER REAR VIEW MIRROR ASSY**SERVICE:** INSPECT TIRE PRESSURE

DESCRIPTION: INNER REAR VIEW MIRROR ASSY ~|~LEFT FRONT VISOR IS BROKEN. PLEASE ADVISE ~|~P&A DRIVER SIDE SUN VISOR. PRICE LISTED \$144.65 LABOR 0.5 ~|~ESTIMATE ARRIVAL 4-5DAYS. TRIM NOT COVERED BY LEXUS EXTRA CARE CONTRACT. TOTAL TO REPLACE \$231.22. PART WOULD TAKE 4-5 BUSINESS DAYS WHEN ORDERED

SERVICE: RECHECK FRNT SUSPEN

DESCRIPTION: RECHECK FRNT SUSPEN ~|~PLEASE REMOVE TIRE FROM SPARE TO USE SPARE RIM ON VEHICLE IN PLACE OF RIGHT FRONT RIM THAT IS DAMAGED. 1.0 ~|~DEMOUNT SPARE AND RIGHT FRONT TIRES AND SWAP TIRES. INSTALL TIRE FROM BAD RIM ONTO SPARE RIM. SPARE TIRE ON BAD RIM. BALANCE TIRES. NEW RIM IS ON RIGHT REAR AFTER TIRE ROTATION.

DESCRIPTION: INSPECT TIRE PRESSURE ~|~CHECK TIRE PRESSURES AND RECORD ON INVOICE ~|~TIRE PRESSURE WAS INSPECTED AND ADJUSTED ~|~TIRE PRESSURE SET AND ADJUSTED BASED ON TIRE TEMPERATURE 36PSI SPARE 40PSI

SERVICE: WINDSHIELD WIPER/WASHER

DESCRIPTION: WINDSHIELD WIPER/WASHER ~|~FRONT GLASS RAIN REPELLENT ~|~CAR IS NOT EQUIPPED WITH SPECIAL GLASS. CAR HAS AUTO SENSING WIPERS FOR RAIN AND THEY ARE OPERATING ~|~NO REPAIRS PERFORMED

57169 MILES

DATE: 05/13/2016

REPAIR# 0514281

REPORTED BY: Lexus of Sacramento

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~CUSTOMER REQUEST OIL & FILTER CHANGE ONLY PLEASE USE FULL SYNTHETIC OIL 0W-20 ~|~NO CHARGE TO CUSTOMER FOR SERVICE PO# WILL BE PROVIDED LEXUS OF CONCORD PO# 116081 CONTACT : SERVICE DIRECTOR MARK RUFFNER (925)687-7274
~|~TECH 368, RESET MAINT, CHECKED FLUIDS, LOF NON WARRANTABLE OPERATION CODE ~|~PLEASE SET ALL WINDOWS TO OPEN WHEN PRESS AND HOLDING KEY ~|~TECH 368 SET ALL WINDOWS TO UPEN WHEN PRESSING AND HOLDING UNLOCK BUTTON

52120 MILES

DATE: 09/23/2015

REPAIR# 0249480

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION. CAN ONLY BE COMBINED WITH A SERVICE.
~|~GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION. CAN ONLY BE COMBINED WITH A SERVICE. ~|~ ~|~52119 TECH PERFORMED COURTESY VISUAL MULTI-POINT INSPECTION... AND COMPLETED YOUR COMPLIMENTARY INSPECTION SHEET THANK YOU FOR YOUR BUSINESS!!! GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION. CAN ONLY BE COMBINED WITH A SERVICE. GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT ~|~GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~|~ ~|~52119 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT__10__MM --- FT RIGHT__10__MM --- RR RIGHT__10__MM --- RR LEFT__10__MM TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT____MM --- FT RIGHT GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT THE DRIVERS FLOOR MAT.

DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~|~INSPECT THE DRIVERS FLOOR MAT. ~|~ ~|~52119 TECHNICIAN INSPECTED

SERVICE: PERFORM STATE MANDATED TIRE PRESSURE CHECK.
DESCRIPTION: PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~52119 FRONT LEFT ___34___PSI --- FRONT RIGHT ___34___PSI --- REAR RIGHT ___34___PSI --- REAR LEFT ___34___PSI

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: SERVICE - 55,000 MILES
DESCRIPTION: SERVICE - 55,000 MILES ~|~SERVICE - 55,000 MILES ~|~52119 110 MAINTENANCE SERVICE COMPLETED

FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT FOR VEHICLE. THANK YOU!

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: ROTATE TIRES
DESCRIPTION:

49340 MILES

DATE: 07/22/2015

REPAIR# 0237870
REPORTED BY: Longo Lexus

SERVICE:
DESCRIPTION: GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT ~|~GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~|~ ~|~49340 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT ___10___MM --- FT RIGHT ___10___MM --- RR RIGHT ___10___MM --- RR LEFT ___10___MM TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT ___MM --- FT RIGHT GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT

SERVICE: PADS, BRAKE (FRONT) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE
DESCRIPTION: PADS, BRAKE (FRONT) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~PADS, BRAKE (FRONT) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~FRONT PADS AT 3MM. ~|~49340 220 REPLACED FRONT BRAKE PADS AND MACHINED ROTORS AND REPLACED BOTH FRONT BRAKE WEAR SENSORS.

SERVICE: PERFORM STATE MANDATED TIRE PRESSURE CHECK.
DESCRIPTION: PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~49340 FRONT LEFT ___36___PSI --- FRONT RIGHT ___36___PSI --- REAR RIGHT ___36___PSI --- REAR LEFT ___36___PSI

SERVICE: INSPECT THE DRIVERS FLOOR MAT.
DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~|~INSPECT THE DRIVERS FLOOR MAT. ~|~ ~|~49340 TECHNICIAN INSPECTED FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT FOR VEHICLE. THANK YOU!

SERVICE: PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE
DESCRIPTION: PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~PADS, BRAKE (REAR) - REPLACE AND RESURFACE ROTORS OFF-VEHICLE ~|~REAR PADS AT 3MM. ~|~49340 220 REPLACED REAR BRAKE PADS AND MACHINED ROTORS.

46912 MILES

DATE: 06/03/2015

REPAIR# 0228378
REPORTED BY: Longo Lexus

SERVICE:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS

DESCRIPTION: GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC ~-GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~- ~-46912 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT___7__MM --- FT RIGHT___7__MM --- RR RIGHT___5__MM --- RR LEFT___5__MM TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT_____MM -- - FT RIGHT___ GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: MISC

DESCRIPTION: MISC ~-SERVICE - 50,000 MILES ~- ~-46912 150 MAINTENANCE SERVICE COMPLETED

SERVICE: REPLACE 2 FRONT WINDSHIELD WIPER INSERTS

DESCRIPTION: REPLACE 2 FRONT WINDSHIELD WIPER INSERTS ~-REPLACE 2 FRONT WINDSHIELD WIPER INSERTS ~-TORN ~-46912 30 REPLACED WIPER INSERTS

SERVICE: REPLACE CABIN AIR FILTER

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

AND ROTORS

DESCRIPTION:

SERVICE: INSPECT THE DRIVERS FLOOR MAT.

DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~-INSPECT THE DRIVERS FLOOR MAT. ~- ~-46912 TECHNICIAN INSPECTED FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT FOR VEHICLE. THANK YOU!

SERVICE: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE.

DESCRIPTION: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE. ~-PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE. ~- ~-46912 FRONT LEFT___34_PSI --- FRONT RIGHT___34_PSI --- REAR RIGHT___34_PSI --- REAR LEFT___34_PSI

SERVICE: REPLACE BATTERY(S) IN MASTER KEY

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

44263 MILES

DATE: 04/06/2015

REPAIR# 0217442

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST STATES THAT CLICKING SOUND HEARD FROM UNDERSIDE AFTER IMPACT DAMAGE / RAN OVER TIRE ON FREEWAY ~-GUEST STATES THAT CLICKING SOUND HEARD FROM UNDERSIDE AFTER IMPACT DAMAGE / RAN OVER TIRE ON FREEWAY. INSPECT AND ADVISE. LOOSE UNDERSIDE COVER MAY HAVE COME OFF. ~- ~-44263 100 INSPECT VEHICLE UNDER BODY, FOUND LEFT REAR SUSPENSION/AXLE COVER LOOSE AND RUBBING ON LEFT REAR AXLE. ADJUST COVER BRACKET AND COVER. RESECURE BEST AS POSSIBLE. COSMETIC (MINOR) DAMAGE TO SEVERAL BODY COVERS. ALL COVER ARE SECURED AT THIS TIME. GUEST STATES THAT CLICKING SOUND HEARD FROM UNDERSIDE AFTER IMPACT DAMAGE / RAN OVER TIRE ON FREEWAY LEXUS LOAN CAR. LEXUS LOAN CAR IS PROVIDED WITH THE UNDERSTANDING THAT I WILL RESPOND TO COMMUNICA ~-LEXUS LOAN CAR. LEXUS LOAN CAR IS PROVIDED WITH THE

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~-GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~- ~-44263 TECH PERFORMED COURTESY VISUAL MULTI-POINT INSPECTION... AND COMPLETED YOUR COMPLIMENTARY INSPECTION SHEET THANK YOU FOR YOUR BUSINESS!!!

UNDERSTANDING THAT I WILL RESPOND TO COMMUNICATIONS WITHIN 24 HOURS OF THE FIRST NOTIFICATION, AND I WILL BRING THIS LOANER BACK WITHIN 24 HOURS OF FIRST BEING NOTIFIED MY VEHICLE IS COMPLETE OR A \$90 P ~|~ LEXUS LOAN CAR. LEXUS LOAN CAR IS PROVIDED WITH THE UNDERSTANDING THAT I WILL RESPOND TO COMMUNICA

SERVICE: INSPECT THE DRIVERS FLOOR MAT.

DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~|~INSPECT THE DRIVERS FLOOR MAT. ~|~ ~|~44263 TECHNICIAN INSPECTED FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT FOR VEHICLE. THANK YOU!

SERVICE: PERFORM STATE MANDATED TIRE PRESSURE CHECK.

DESCRIPTION: PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~ ~|~44263 FRONT LEFT ___34___PSI --- FRONT RIGHT ___34___PSI --- REAR RIGHT ___34___PSI --- REAR LEFT ___34___PSI

42135 MILES

DATE: 02/25/2015

REPAIR# 0210003

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT ~|~GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~|~ ~|~42135 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT ___6___MM --- FT RIGHT ___6___MM --- RR RIGHT ___5___MM --- RR LEFT ___5___MM TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT ___MM -- - FT RIGHT ___ GUEST REQUEST BRAKE MEASUREMENTS: CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUT

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~|~GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~|~

SERVICE: INSPECT BODY PAINT AND CORROSION

DESCRIPTION:

SERVICE: INSPECT BRAKE LINES, HOSES AND CONNECTIONS

DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS

DESCRIPTION:

SERVICE: INSPECT ENGINE COOLANT LEVEL

DESCRIPTION:

SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT RACK AND PINION ASSEMBLY

DESCRIPTION:

SERVICE: INSPECT REAR DIFFERENTIAL FLUID LEVEL

DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE

DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS

DESCRIPTION:

SERVICE: INSPECT THE DRIVERS FLOOR MAT.

DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~|~INSPECT THE DRIVERS FLOOR MAT. ~|~ ~|~42135 TECHNICIAN INSPECTED FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT FOR VEHICLE. THANK YOU!

SERVICE: PERFORM STATE MANDATED TIRE PRESSURE CHECK.

DESCRIPTION: PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~PERFORM STATE MANDATED TIRE PRESSURE CHECK. ~|~ ~|~42135 FRONT LEFT ___32___PSI --- FRONT RIGHT ___32___PSI --- REAR RIGHT ___32___PSI --- REAR LEFT ___32___PSI

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: SERVICE - 45,000 MILES

DESCRIPTION: SERVICE - 45,000 MILES ~~-SERVICE - 45,000 MILES

~~-42135 110 MAINTENANCE SERVICE COMPLETED

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

37172 MILES

DATE: 11/12/2014

REPAIR# 0192290

REPORTED BY: Longo Lexus

SERVICE: BATTERY

DESCRIPTION: BATTERY ~~-CHECK BATTERY ~~-BATTERY FAIL LOAD TEST DUE TO A OPEN CIRCUIT IN THE BATTERY. ~~-37172 BATTERY FAIL LOAD TEST DUE TO A OPEN CIRCUIT IN THE BATTERY. 190011A 72 71 60 REPLACED BATTERY

SERVICE: BATTERY COMB: BATTERY

DESCRIPTION:

37172 MILES

DATE: 11/11/2014

REPAIR# 192290C

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC ~~-GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~~-37172 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT__8__MM --- FT RIGHT__8__MM --- RR RIGHT__6__MM --- RR LEFT__6__MM TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT____MM --- FT RIGHT____ GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC

SERVICE: GUEST REQUEST COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: GUEST REQUEST COMPLIMENTARY MULTI-POINT INSPECTION ~~-GUEST REQUEST COMPLIMENTARY MULTI-POINT INSPECTION ~~-

SERVICE: GUEST REQUESTS FOUR WHEEL ALIGNMENT

DESCRIPTION: GUEST REQUESTS FOUR WHEEL ALIGNMENT ~~-GUEST REQUESTS FOUR WHEEL ALIGNMENT ~~-37172 200 PERFORM FOUR WHEEL ALIGNMENT

SERVICE: GUEST REQUESTS REPLACE FOUR TIRES - PROVIDE INSTALLED LOCATIONS AND DOT NUMBERS

DESCRIPTION: GUEST REQUESTS REPLACE FOUR TIRES - PROVIDE INSTALLED LOCATIONS AND DOT NUMBERS ~~-GUEST REQUESTS REPLACE FOUR TIRES - PROVIDE INSTALLED LOCATIONS AND DOT NUMBERS ~~-37172 200 TECHNICIAN MOUNTED AND BALANCED 4 TIRES. TIRE LOCATIONS AND DOT NUMBERS: #1____U2LN EM 7R2613 ALL THE SAME_____#2_____ #3_____#4_____ REPLACED FOUR TIRES

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE.

DESCRIPTION: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE. ~~-PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE

SERVICE: REPLACE BATTERY(S) IN MASTER KEY

DESCRIPTION:

PRESSURE. ~|~ ~|~37172 LF 5/1 RF 5/1 RR 6/2 LR 6/1 FRONT
LEFT ___34___PSI --- FRONT RIGHT ___34___PSI --- REAR
RIGHT ___34___PSI --- REAR LEFT ___34___PSI

SERVICE: REPLACE CABIN AIR FILTER
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: SERVICE - 40,000 MILES
DESCRIPTION: SERVICE - 40,000 MILES ~|~SERVICE - 40,000 MILES
~|~ ~|~37172 150 MAINTENANCE SERVICE COMPLETED

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: ROTATE TIRES
DESCRIPTION:

31858 MILES

DATE: 08/11/2014

REPAIR# 0176670
REPORTED BY: Longo Lexus

SERVICE:
DESCRIPTION: AAA MEMBER 10% UP TO \$75.00 DISCOUNT,
INCLUDES 2 YR/ 24,000 MILE WARRANTY ON LEXUS ORIGINAL
REPAIR ~|~AAA MEMBER 10% UP TO \$75.00 DISCOUNT, INCLUDES 2
YR/ 24,000 MILE WARRANTY ON LEXUS ORIGINAL REPAIRS
(FILTERS, TIRES AND WEAR ITEMS NOT INCLUDED) ~|~ AAA
MEMBER 10% UP TO \$75.00 DISCOUNT, INCLUDES 2 YR/ 24,000 MILE
WARRANTY ON LEXUS ORIGINAL REPAIR

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT
DESCRIPTION:

SERVICE: PERFORM STATE MANDATED TIRE TREAD DEPTH
CHECK, CONDITION AND TIRE PRESSURE.
DESCRIPTION: PERFORM STATE MANDATED TIRE TREAD DEPTH
CHECK, CONDITION AND TIRE PRESSURE. ~|~PERFORM STATE
MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE
PRESSURE. ~|~ ~|~31857 FRONT LEFT CENTER WEAR ___8___/32 &
EDGE WEAR ___7___/32 - FRONT RIGHT CENTER WEAR ___8___/32 &
EDGE WEAR ___7___/32 REAR RIGHT CENTER WEAR ___9___/32 & EDGE
WEAR ___7___/32 - REAR LEFT CENTER WEAR ___9___/32 & EDGE
WEAR ___7___/32 FRONT LEFT ___36___PSI --- FRONT RIGH

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: SERVICE - 35,000 MILES
DESCRIPTION: SERVICE - 35,000 MILES ~|~OIL AND FILTER -
CHANGE ~|~ ~|~31857 50 MAINTENANCE SERVICE COMPLETED

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS
AND ROTORS
DESCRIPTION:

SERVICE: INSPECT THE DRIVERS FLOOR MAT.
DESCRIPTION: INSPECT THE DRIVERS FLOOR MAT. ~|~INSPECT
THE DRIVERS FLOOR MAT. ~|~ ~|~31857 TECHNICIAN INSPECTED
FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT FITMENT
FOR VEHICLE. THANK YOU!

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: ROTATE TIRES
DESCRIPTION:

30568 MILES

DATE: 07/12/2014

REPAIR# 0172409

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC ~~-GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDICATION OF FUTURE WEAR ~~-~30564 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT__3__MM --- FT RIGHT__3__MM --- RR RIGHT__7__MM --- RR LEFT__7__MM GUEST REQUEST BRAKE MEASUREMENTS: LF RF LR RR CURRENT BRAKE MEASUREMENTS ARE APPROX - NOT AN INDIC

SERVICE: PADS, BRAKE (FRONT) - REPLACE AND RESURFACE ROTORS ON-VEHICLE

DESCRIPTION: PADS, BRAKE (FRONT) - REPLACE AND RESURFACE ROTORS ON-VEHICLE ~~-BRAKE WEAR LIGHT ON ~~-~30564 220 REPLACE FRONT BRAKE PADS AND RESURFACE ROTORS AND REPLACE R/F BRAKE WEAR SENSOR

SERVICE: REVISED ESTIMATE

DESCRIPTION: REVISED ESTIMATE ~~-REVISED FOR FRONT BRAKES AND SENSORS ~~-~30568 0

SERVICE: GUEST REQUESTS LONGO LEXUS COURTESY VEHICLE

DESCRIPTION: GUEST REQUESTS LONGO LEXUS COURTESY VEHICLE ~~-GUEST REQUESTS LONGO LEXUS COURTESY VEHICLE ~~-

SERVICE: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE.

DESCRIPTION: PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE. ~~-PERFORM STATE MANDATED TIRE TREAD DEPTH CHECK, CONDITION AND TIRE PRESSURE. ~~-~30564 FRONT LEFT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 - FRONT RIGHT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 REAR RIGHT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 - REAR LEFT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 FRONT LEFT__36__PSI --- FRONT RIGH

26501 MILES

DATE: 04/13/2014

REPAIR# 0157248

REPORTED BY: Longo Lexus

SERVICE:

DESCRIPTION: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~-GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~-~26401 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT__6__MM -- - FT RIGHT__6__MM --- RR RIGHT__9__MM --- RR LEFT__9__MM GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN REMO ~~-GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN REMOVED HAVE WHEEL LUG NUTS TIGHTENED TO FACTORY SPECIFICATIONS UPON RE-INSTALLATION. ~~-~26401 FRONT LEFT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 - FRONT RIGHT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 REAR RIGHT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 - REAR LEFT CENTER WEAR__6__/32 & EDGE WEAR__6__/32 (ALL 4) TIRE PRESSURE... FRONT TIRES_ GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN REMO INSPECT THE DRIVERS FLOOR MAT. () FLOOR MAT WAS PROPERLY INSTALLED () FLOOR MAT WAS SECURED FOR ~~-INSPECT THE DRIVERS FLOOR MAT. () FLOOR MAT WAS PROPERLY INSTALLED () FLOOR MAT WAS SECURED FOR YOUR SAFETY () NON-COMPATIBLE FLOOR MAT HAS BEEN PLACED IN THE TRUNK FOR YOUR SAFETY. ~~-~26401 TECHNICIAN INSPECTED FLOOR MAT INSTALLATION. FLOOR MAT WAS CORRECT

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~~-GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~~-~26401 TECH PERFORMED COURTESY VISUAL MULTI-POINT INSPECTION... AND COMPLETED YOUR COMPLIMENTARY INSPECTION SHEET THANK YOU FOR YOUR BUSINESS!!!

FITMENT FOR VEHICLE. THANK YOU! INSPECT THE DRIVERS FLOOR MAT. () FLOOR MAT WAS PROPERLY INSTALLED () FLOOR MAT WAS SECURED FOR

SERVICE: INSPECT BODY PAINT AND CORROSION
DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS
DESCRIPTION:

SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS
DESCRIPTION:

SERVICE: INSPECT FUEL TANK, CAP, LINE AND HOSES
DESCRIPTION:

SERVICE: INSPECT RACK AND PINION ASSEMBLY
DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE
DESCRIPTION:

SERVICE: INSPECT TRANSMISSION FOR LEAKS
DESCRIPTION:

SERVICE: MEASURE BRAKE PAD THICKNESS AND ROTOR RUNOUT
DESCRIPTION:

SERVICE: REPLACE BATTERY(S) IN MASTER KEY
DESCRIPTION:

SERVICE: REPLACE CABIN AIR FILTER
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: SERVICE - 30,000 MILES
DESCRIPTION: SERVICE - 30,000 MILES ~~-SERVICE - 30,000 MILES ~~- ~~-26401 270 MAINTENANCE SERVICE COMPLETED

SERVICE: INSPECT BRAKE LINES, HOSES AND CONNECTIONS
DESCRIPTION:

SERVICE: INSPECT ENGINE COOLANT LEVEL
DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS
DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT
DESCRIPTION:

SERVICE: INSPECT REAR DIFFERENTIAL FLUID LEVEL
DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS
DESCRIPTION:

SERVICE: LONGO LEXUS COURTESY VEHICLE
DESCRIPTION: LONGO LEXUS COURTESY VEHICLE ~~-LONGO LEXUS COURTESY VEHICLE ~~-

SERVICE: REPLACE AIR CLEANER FILTER
DESCRIPTION:

SERVICE: REPLACE BRAKE FLUID
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: ROTATE TIRES
DESCRIPTION:

21143 MILES

DATE: 12/21/2013

REPAIR# 0139146
REPORTED BY: Longo Lexus

SERVICE:
DESCRIPTION: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~-GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~- ~~-21142 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT __9__MM ---

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION
DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~~-GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~~- ~~-21142 TECH PERFORMED COURTESY VISUAL MULTI-POINT INSPECTION... AND COMPLETED YOUR COMPLIMENTARY INSPECTION SHEET THANK YOU FOR YOUR

FT RIGHT_9___MM --- RR RIGHT__10___MM --- RR
LEFT__10___MM GUEST REQUESTS CURRENT BRAKE
MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE
FUTURE WEAR GUEST REQUESTS CHECK TIRE TREAD DEPTH,
CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN
REMO ~|~GUEST REQUESTS CHECK TIRE TREAD DEPTH,
CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN
REMOVED HAVE WHEEL LUG NUTS TIGHTENED TO FACTORY
SPECIFICATIONS UPON RE-INSTALLATION. ~|~ ~|~21142 FRONT LEFT
CENTER WEAR__8___/32 & EDGE WEAR__7___/32 - FRONT RIGHT
CENTER WEAR__7___/32 & EDGE WEAR__7___/32 REAR RIGHT
CENTER WEAR__8___/32 & EDGE WEAR__8___/32 - REAR LEFT CENTER
WEAR__8___/32 & EDGE WEAR__8___/32 (ALL 4) TIRE PRESSURE...
FRONT TIRES__ GUEST REQUESTS CHECK TIRE TREAD DEPTH,
CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN
REMO INSPECT THE DRIVERS FLOOR MAT. () FLOOR MAT WAS
PROPERLY INSTALLED () FLOOR MAT WAS SECURED FOR
~|~INSPECT THE DRIVERS FLOOR MAT. () FLOOR MAT WAS
PROPERLY INSTALLED () FLOOR MAT WAS SECURED FOR YOUR
SAFETY () NON-COMPATIBLE FLOOR MAT HAS BEEN PLACED IN
THE TRUNK FOR YOUR SAFETY. ~|~ INSPECT THE DRIVERS FLOOR
MAT. () FLOOR MAT WAS PROPERLY INSTALLED () FLOOR MAT
WAS SECURED FOR

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS
AND ROTORS
DESCRIPTION:

SERVICE: REPLACE BATTERY(S) IN MASTER KEY
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL
DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR
DESCRIPTION:

SERVICE: ROTATE TIRES
DESCRIPTION:

BUSINESS!!!

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT
DESCRIPTION:

SERVICE: REPLACE CABIN AIR FILTER
DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER
DESCRIPTION:

SERVICE: ROAD TEST
DESCRIPTION:

SERVICE: TAC2WE1526
DESCRIPTION: TAC2WE1526 ~|~SERVICE - 20,000 MILES ~|~
~|~21142 150 20K MAINTENANCE SERVICE COMPLETED

16128 MILES

DATE: 09/21/2013

REPAIR# 0123368
REPORTED BY: Longo Lexus

SERVICE: DEALER RECOMMENDED
DESCRIPTION:

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT
INSPECTION
DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-
POINT INSPECTION ~|~GUEST REQUESTS COMPLIMENTARY MULTI-
POINT INSPECTION ~|~ ~|~16127 TECH PERFORMED COURTESY

SERVICE: GUEST REQUESTS CHECK TIRE TREAD DEPTH,
CONDITION AND TIRE PRESSURE. ALL WHEELS T
DESCRIPTION: GUEST REQUESTS CHECK TIRE TREAD DEPTH,
CONDITION AND TIRE PRESSURE. ALL WHEELS T ~|~GUEST
REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE
PRESSURE. ALL WHEELS THAT HAVE BEEN REMOVED HAVE
WHEEL LUG NUTS TIGHTENED TO FACTORY SPECIFICATIONS UPON
RE-INSTALLATION. ~|~ ~|~16127 FRONT LEFT CENTER WEAR__8___
/32 & EDGE WEAR__8___/32 - FRONT RIGHT CENTER WEAR__8___/32 &
EDGE WEAR__8___/32 REAR RIGHT CENTER WEAR__8___/32 & EDGE
WEAR__8___/32 - REAR LEFT CENTER WEAR__8___/32 & EDGE
WEAR__8___/32 (ALL 4) TIRE PRESSURE... FRONT TIRES__

SERVICE: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS
ARE APPROXIMATE AND DO NOT INDICATE FU
DESCRIPTION: GUEST REQUESTS CURRENT BRAKE
MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FU
~|~GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE

VISUAL MULTI-POINT INSPECTION... AND COMPLETED YOUR COMPLIMENTARY INSPECTION SHEET THANK YOU FOR YOUR BUSINESS!!!

APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~-16127 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASURMENT FT LEFT__10__MM --- FT RIGHT__10__MM --- RR RIGHT__11__MM --- RR LEFT__11__MM

SERVICE: INSPECT BODY PAINT AND CORROSION

DESCRIPTION:

SERVICE: INSPECT BRAKE LINES, HOSES AND CONNECTIONS

DESCRIPTION:

SERVICE: INSPECT DRIVE AXLE BOOTS

DESCRIPTION:

SERVICE: INSPECT ENGINE COOLANT LEVEL

DESCRIPTION:

SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS

DESCRIPTION:

SERVICE: INSPECT FRONT AND REAR BRAKE PADS, CALIPERS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: INSPECT RACK AND PINION ASSEMBLY

DESCRIPTION:

SERVICE: INSPECT REAR DIFFERENTIAL FLUID LEVEL

DESCRIPTION:

SERVICE: INSPECT STEERING OPERATION AND LINKAGE

DESCRIPTION:

SERVICE: INSPECT SUSPENSION BALL JOINTS

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 15,000 MILES

DESCRIPTION: SERVICE - 15,000 MILES ~~-SERVICE - 15,000 MILES

SERVICE: WINDSHIELD WASHER FLUID

DESCRIPTION:

~-~-16127 110 15K MAINTENANCE SERVICE COMPLETED

11338 MILES

DATE: 06/29/2013

REPAIR# 0110132

REPORTED BY: Longo Lexus

SERVICE: 10,000 MILE FULL SERVICE

DESCRIPTION: 10,000 MILE FULL SERVICE ~~-10,000 MILE FULL SERVICE ~~-11336 MAINTENANCE SERVICE COMPLETED

SERVICE: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS T

DESCRIPTION: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS T ~~-GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN REMOVED HAVE WHEEL LUG NUTS TIGHTENED TO FACTORY SPECIFICATIONS UPON RE-INSTALLATION. INITIALS _____ ~~-11336 FRONT LEFT CENTER WEAR__8_/32 & EDGE WEAR__8_/32 - FRONT RIGHT CENTER WEAR__8_/32 & EDGE WEAR__8_/32 REAR RIGHT CENTER WEAR__8.5_/32 & EDGE WEAR__8_/32 - REAR LEFT CENTER WEAR__8.5_/32 & EDGE WEAR__8_/32 (ALL 4) TIRE PRESSURE... FRONT TIR

SERVICE: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION ~~-GUEST REQUESTS COMPLIMENTARY MULTI-POINT INSPECTION

SERVICE: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FU

DESCRIPTION: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FU ~~-GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~-11336 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASURMENT FT LEFT__10__MM --- FT RIGHT__10__MM ---

RR RIGHT ___9___MM --- RR LEFT ___9___MM

SERVICE: INSPECT BRAKE PADS AND ROTORS

DESCRIPTION:

SERVICE: INSPECT INSTALLATION OF DRIVER'S FLOOR MAT

DESCRIPTION:

SERVICE: REPLACE BATTERY(S) IN MASTER KEY

DESCRIPTION:

SERVICE: REPLACE CABIN AIR FILTER

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL AND GASKET

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 10,000 MILES

DESCRIPTION: SERVICE - 10,000 MILES ~~-SERVICE - 10,000 MILES (\$180, OP-CODE: LP9N10, AUTH#: TAC2UD2874) ~~-TAC 2UD2874 \$180.00 ~~-11336 MAINTENANCE SERVICE COMPLETED

6670 MILES

DATE: 04/13/2013

REPAIR# 0098113

REPORTED BY: Longo Lexus

SERVICE: SERVICE - 5,000 MILE COMPLIMENTARY SERVICE - CONVENTIONAL OIL VEHICLES

DESCRIPTION: SERVICE - 5,000 MILE COMPLIMENTARY SERVICE - CONVENTIONAL OIL VEHICLES ~~-SERVICE - 5,000 MILE COMPLIMENTARY SERVICE - CONVENTIONAL OIL VEHICLES ~~-5K ~~-6689 MAINTENANCE SERVICE COMPLETED

6670 MILES

DATE: 04/12/2013

REPAIR# 098113C

REPORTED BY: Longo Lexus

SERVICE: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS T

DESCRIPTION: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS T ~~-GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE. ALL WHEELS THAT HAVE BEEN REMOVED HAVE WHEEL LUG NUTS TIGHTENED TO FACTORY SPECIFICATIONS UPON RE-INSTALLATION. INITIALS _____ ~~- ~~-6689 FRONT LEFT CENTER WEAR_10_/32 & EDGE WEAR_7_/32 - FRONT RIGHT CENTER WEAR_10_/32 & EDGE WEAR_7_/32 REAR RIGHT CENTER WEAR_11_/32 & EDGE WEAR_7_/32 - REAR LEFT CENTER WEAR_11_/32 & EDGE WEAR_7_/32 (ALL 4) TIRE PRESSURE... FRONT TIRE

SERVICE: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FU

DESCRIPTION: GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FU ~~-GUEST REQUESTS CURRENT BRAKE MEASUREMENTS ARE APPROXIMATE AND DO NOT INDICATE FUTURE WEAR ~~- ~~-6689 TECH PERFORMED VISUAL BRAKE INSPECTION PAD THICKNESS MEASUREMENT FT LEFT___10___MM --- FT RIGHT___10___MM --- RR RIGHT___10___MM --- RR LEFT___10___MM

1773 MILES

DATE: 01/28/2013

REPAIR# 0086811

REPORTED BY: Longo Lexus

SERVICE: 1,000 MILE SERVICE

DESCRIPTION: 1,000 MILE SERVICE ~|~PERFORM 1,000 MILE SERVICE AND INSTALL LIC PLATES ~|~1K ~|~1773 MAINTENANCE SERVICE COMPLETED AND INSTALLED LICENSE PLATES.

1773 MILES

DATE: 01/26/2013

REPAIR# 086811C

REPORTED BY: Longo Lexus

SERVICE: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE

DESCRIPTION: GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE ~|~GUEST REQUESTS CHECK TIRE TREAD DEPTH, CONDITION AND TIRE PRESSURE ~|~ ~|~1772 FRONT LEFT CENTER WEAR__10__/32 & EDGE WEAR__8__/32 - FRONT RIGHT CENTER WEAR__10__/32 & EDGE WEAR__8__/32 REAR RIGHT CENTER WEAR__10__/32 & EDGE WEAR__8__/32 - REAR LEFT CENTER WEAR__10__/32 & EDGE WEAR__8__/32 (ALL 4) TIRE PRESSURE... FRONT TIRES

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) (//www.lexus.com/privacy/online-statement).