

LX470

SERVICE HISTORY**SERVICE HISTORY FOR:** LX470**VIN:****90693 MILES****DATE:** 12/19/2011**REPAIR#** 0501529**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** 90,000 MILE SERVICE WITH TIMING BELT & WHEEL BEARING REPACK**DESCRIPTION:** 90,000 MILE SERVICE WITH TIMING BELT & WHEEL BEARING REPACK ~|~90,000 MILE SERVICE WITH TIMING BELT & WHEEL BEARING REPACK ~|~ ~|~90693 1170 FRONT PADS 4MM, REAR PADS 7MM, FRONT TIRES 8/32, REAR TIRES 13/32 * TEST BATTERY AND CLEAN TERMINALS* REPLACE AIR FILTER* REPLACE ENGINE COOLANT* REPLACE AIR FILTER* REPLACE ENGINE TIMING BELT* INSPECT A/C FILTER (WHERE APPLIES)* FLUSH BRAKE SY**SERVICE:** BALANCE TIRES**DESCRIPTION:** BALANCE TIRES ~|~BALANCE TIRES ~|~ ~|~90693 040 BALANCED**SERVICE:** DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS**DESCRIPTION:** DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS ~|~DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS ~|~ ~|~90693 100 SERVICED**SERVICE:** LC**DESCRIPTION:** LC ~|~INORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOU LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$120 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.**SERVICE:** NO PROBLEM FOUND, COULD NOT DUPLICATE CONCERN.**DESCRIPTION:** NO PROBLEM FOUND, COULD NOT DUPLICATE CONCERN. ~|~C/S THE DASH LIGHTS ""D"" IS FLASHING --- PLEASE ADVISE (WATER CAME THROUGH THE SUN ROOF LAST NIGHT) ~|~ ~|~90693 WORKING AS DESIGNED AT THIS TIME NONE**SERVICE:** REPLACE TRANSFER CASE FLUID**DESCRIPTION:** REPLACE TRANSFER CASE FLUID ~|~REPLACE**SERVICE:** ALF INSTALL STEERING FITTING KIT & SUPPORT KIT - LX 470**DESCRIPTION:** ALF INSTALL STEERING FITTING KIT & SUPPORT KIT - LX 470 ~|~ALF LX 470 STEERING KIT INSTALL ~|~ALF ~|~90693 0523G1 190 COMPLETED SERVICE CAMPAIGN ALF. GAS \$55.22**SERVICE:** DEAR GUEST, AS A COMMON COURTESY, WE WOULD LIKE TO PERFORM A COURTESY INSPECTION**DESCRIPTION:** DEAR GUEST, AS A COMMON COURTESY, WE WOULD LIKE TO PERFORM A COURTESY INSPECTION ~|~DEAR GUEST, AS A COMMON COURTESY, WE WOULD LIKE TO PERFORM A COURTESY INSPECTION OF YOUR VEHICLE. IF YOU WOULD LIKE TO DECLINE THIS SERVICE, PLEASE INITIAL HERE _____**SERVICE:** FOUR WHEEL ALIGNMENT**DESCRIPTION:** FOUR WHEEL ALIGNMENT ~|~C/S THE STEERING WHEEL IS OFF CENTER, IT IS ALSO HARD TO KEEP STRAIGHT IN THE LANE. VERY MUCH MOVEMENT FROM THE STEERING WHEEL - - PLEASE ADVISE ~|~ ~|~90693 ALIGNMENT, VGRS OUT OF SPECS, TIRES WORN 180 ALIGNED, WITHIN SPECS, HAS SLIGHT TIRE PULL TO RIGHT.O.K. TO RELEASE TO CUSTOMER.**SERVICE:** MOUNT AND BALANCE 2 TIRES**DESCRIPTION:** MOUNT AND BALANCE 2 TIRES ~|~MOUNT AND BALANCE 2 TIRES ~|~ ~|~90693 080 VWD5DMDR1511**SERVICE:** REPLACE ALL FRONT AXLE BOOTS**DESCRIPTION:** REPLACE ALL FRONT AXLE BOOTS ~|~UPON INSPECTION, FOUND AXLE BOOTS LEAKING ~|~ ~|~90693 400 REPLACED ALL FRONT AXLE BOOTS**SERVICE:** REPLACE WATER PUMP AND FRONT CRANK SEAL**DESCRIPTION:** REPLACE WATER PUMP AND FRONT CRANK SEAL

TRANSFER CASE FLUID ~ ~ 90693 050 SERVICED

~ ~ REPLACE WATER PUMP AND SEALS ~ ~ 90693 200 REPLACED
WATER PUMP (CRUSTY) AND FRONT CRANK SEAL**73720 MILES****DATE: 07/28/2009****REPAIR#** 0408662**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** 10,000 MILE MAINTENANCE, RESET MAINTENANCE LIGHT IF APPLICABLE.**DESCRIPTION:** 10,000 MILE MAINTENANCE, RESET MAINTENANCE LIGHT IF APPLICABLE. ~ ~ 70,000 MILE SERVICE ~ ~ 73720 70K SERVICE 100 FRONT BRAKES=7MM. REAR BRAKES=9MM. ALL TIRES=8/32" ---CHECK ALL FLUIDS* CHECK TIRE PRESSURES* INSPECT WIPER INSERTS* CHECK TAIL LIGHTS/HEADLIGHTS* RE-TORQUE DRIVE SHAFT FLANGE BOLTS* INSPECT BALL JOINTS AND DUST COVERS* INSPECT BRAKE**SERVICE:** FOUR WHEEL ALIGNMENT**DESCRIPTION:** FOUR WHEEL ALIGNMENT ~ ~ C/S CAR IS PULLING RIGHT --- MAKE SURE STEERING WHEEL IS CENTERED AFTER ALIGNMENT ~ ~ 73720 ALIGNMENT 180**SERVICE:** RESURFACE FRONT BRAKE ROTORS**DESCRIPTION:** RESURFACE FRONT BRAKE ROTORS ~ ~ C/S SEVERE VIBRATION WHEN BRAKING ~ ~ 73720 FRONT ROTORS WARPED 300 MACHINE BOTH FRONT ROTORS WITH ON-CAR BRAKE LATHE**SERVICE:** COURTESY VEHICLE INSPECTION.**DESCRIPTION:** COURTESY VEHICLE INSPECTION. ~ ~ COURTESY VEHICLE INSPECTION.**SERVICE:** LOAN CAR**DESCRIPTION:** LOAN CAR ~ ~ IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.**SERVICE:** STATE INSPECTION-1 YEAR *PLEASE PROVIDE CURRENT PROOF OF INSURANCE.**DESCRIPTION:** STATE INSPECTION-1 YEAR *PLEASE PROVIDE CURRENT PROOF OF INSURANCE. ~ ~ STATE INSPECTION-1 YEAR *PLEASE PROVIDE CURRENT PROOF OF INSURANCE. ~ ~ 73715 STATE INSPECTION 050**61856 MILES****DATE: 06/19/2008****REPAIR#** 0369123**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** 60,000 MILE SERVICE LX470**DESCRIPTION:** 60,000 MILE SERVICE LX470 ~ ~ 60,000 MILE SERVICE LX470 ~ ~ 61846 770 60K SERVICE TIRES ARE ALL 9/32 BRAKES ARE ALL 9MM STATE EXP.2/09 TEST BATTERY AND CLEAN TERMINALS* REPLACE AIR FILTER* REPLACE ENGINE COOLANT* INSPECT A/C FILTER (WHERE APPLIES)* FLUSH BRAKE SYSTEM* REPACK FRONT WHEEL BEARINGS LX450,LX470 (ONLY)**SERVICE:** COURTESY VEHICLE INSPECTION.**DESCRIPTION:** COURTESY VEHICLE INSPECTION. ~ ~ COURTESY VEHICLE INSPECTION.**SERVICE:** FOUR WHEEL ALIGNMENT**DESCRIPTION:** FOUR WHEEL ALIGNMENT ~ ~ FOUR WHEEL ALIGNMENT ~ ~ 61856 180 FOUR WHEEL ALIGNMENT**SERVICE:** CHECK OUT CAR**DESCRIPTION:** CHECK OUT CAR ~ ~ C.S BE SURE THE STEERING WHEEL IS STRAIGHT**SERVICE:** DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS**DESCRIPTION:** DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS ~ ~ DIFFERENTIAL FLUID REPLACEMENT FRONT AND REAR UNITS ~ ~ 61856 100 REPLACED FRONT AND REAR DIFF FLUIDS**SERVICE:** FUEL AND AIR INDUCTION SERVICE**DESCRIPTION:** FUEL AND AIR INDUCTION SERVICE ~ ~ FUEL AND AIR INDUCTION SERVICE ~ ~ 61856 100 FUEL INDUCTION SERVICE

SERVICE: LOANER

DESCRIPTION: LOANER ~|~IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.

SERVICE: REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID

DESCRIPTION: REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID ~|~REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID ~|~ ~|~61856 50 REPLACED TRANS FLUID

SERVICE: SUV BALANCE

DESCRIPTION: SUV BALANCE ~|~C/S SOUNDS LIKE THERE IS A LOT OF ROAD NOISE...PLEASE CHECK ~|~ ~|~61856 80 BALANCED ALL FOUR WHEELS. ALSO NOTICED CRACKS IN REAR WINDOW PANELING ON BOTH SIDE OF THE VEHICLE ALLOWING ROAD NOISE TO BE HEARD LOUDER THAN NORMAL. CUSTOMER DECLINED REPLACING THE WINDOWS AND PANELING AT THIS TIME.

SERVICE: POWER STEERING SYSTEM FLUSH

DESCRIPTION: POWER STEERING SYSTEM FLUSH ~|~POWER STEERING SYSTEM FLUSH ~|~ ~|~61856 100 P/S FLUSH SERVICE

SERVICE: REPLACE TRANSFER CASE FLUID

DESCRIPTION: REPLACE TRANSFER CASE FLUID ~|~REPLACE TRANSFER CASE FLUID ~|~ ~|~61856 50 REPLACED TRANSFER CASE FLUID

57027 MILES

DATE: 12/19/2007

REPAIR# 0351069

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: REMOVE TIRE FROM WHEEL AND APPLY PATCH.

DESCRIPTION: REMOVE TIRE FROM WHEEL AND APPLY PATCH. ~|~REMOVE TIRE FROM WHEEL AND APPLY PATCH. PASSENGER REAR TIRE HAS A NAIL IN IT ~|~ ~|~57027 050 FOUND NAIL IN TIRE PATCHED TIRE

46363 MILES

DATE: 03/16/2007

REPAIR# 0321315

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: 45,000 MILE MAINTENANCE. REPEAT OF 15K. RESET MAINTENANCE LIGHT IF APPLICABLE.

DESCRIPTION: 45,000 MILE MAINTENANCE. REPEAT OF 15K. RESET MAINTENANCE LIGHT IF APPLICABLE. ~|~45,000 MILE MAINTENANCE = *** DO NOT CHANGE OIL ***** ~|~ ~|~46359 1.7 45,000 MILE SERVICE COMPLETE BRAKES: FT, 10MM TO SENSOR REAR 10MM TO SENSOR TIRES:LF11/32 RF11/32 LR11/32 RR11/32 TEST BATTERY AND CLEAN TERMINALS* REPLACE AIR FILTER* INSPECT A/C FILTER (WHERE APPLIES)* INSPECT BRAKE PADS, ROTORS, LINES AND HOS

SERVICE: ADJUST STEERING ANGLE SENSOR = RECALIBRATED SENSOR

DESCRIPTION: ADJUST STEERING ANGLE SENSOR = RECALIBRATED SENSOR ~|~STEERING WHEEL OFF CENTER ~|~INOP ~|~46359 STEERING ANGLE SENSOR OUT OF CALIBRATION 441991 .70 CALIBRATE STEERING ANGLE SENSOR TO CORRECT CUSTOMER

SERVICE: 5LB INSTALL DRL KIT MY03-05 LX470 (SSC)

DESCRIPTION: 5LB INSTALL DRL KIT MY03-05 LX470 (SSC) ~|~CUSTOMER STATES THAT THE LOW BEAM HEADLIGHTS SEEM TO BE TOO BRIGHT WHILE DRIVING INTO ONCOMING TRAFFIC ~|~PERFORM CAMPAIGN ~|~46363 CUSTOMER REQUEST SSC #5LB 5520E2 1.1 PERFORMED SSC #5LB TO CORRECT CUSTOMER CONCERN.

SERVICE: DELIVER VEHICLE

DESCRIPTION: DELIVER VEHICLE ~|~PICK UP AT HOME CALL CELL 817.559.0290 = KEN ~|~ ~|~46359

CONCERN. STEERING ANGLE SENSOR ACCUATOR OUT OF CALIBRATI

SERVICE: DIFFERENTIAL FLUID REPLACEMENT-ONE ONLY
DESCRIPTION: DIFFERENTIAL FLUID REPLACEMENT-ONE ONLY
 ~~-DIFFERENTIAL FLUID REPLACEMENT-ONE ONLY ~~-~46363 .50
 DIFFERENTIAL SERVICE COMPLETE

SERVICE: IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN
DESCRIPTION: IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN ~~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE. ~~-~46363

SERVICE: OIL PAN GASKET (NO2 OIL PAN)
DESCRIPTION: OIL PAN GASKET (NO2 OIL PAN) ~~-VEHICLE HAS AN OIL LEAK ~~-LEAK ~~-46359 LOSS OF RESILENCE OIL PAN ADHESIVE 112121 9.3 RESEAL #2 OIL PAN TO CORRECT CUSTOMER CONCERN

SERVICE: REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID
DESCRIPTION: REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID ~~-REPLACE AUTOMATIC OR MANUAL TRANSMISSION FLUID ~~-~46363 .50 TRANS SERVICE COMPLETE

SERVICE: REPLACE REAR BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PAD
DESCRIPTION: REPLACE REAR BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PAD ~~-REPLACE REAR BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PADS AND SHIMS. RESURFACE REAR ROTORS. ~~-~46359 2.2 REAR BRAKE SERVICE COMPLETE

SERVICE: FOUR WHEEL ALIGNMENT
DESCRIPTION: FOUR WHEEL ALIGNMENT ~~-FOUR WHEEL ALIGNMENT = STEERING WHEEL OFF CENTER ~~-~46359 1.8 ALIGNMENT COMPLETE

SERVICE: NO EXHAUST FOUND AT THIS TIME
DESCRIPTION: NO EXHAUST FOUND AT THIS TIME ~~-CUSTOMER STATES EXHAUST SMELL INSIDE VEHICLE ~~-~46363 0.0 NO EXHAUST LEAKS FOUND

SERVICE: REMOVED FRONT BEARING SEALS AND FRONT WHEEL BEARINGS. CLEANED FRONT BEARINGS AND
DESCRIPTION:

SERVICE: REPLACE FRONT BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PA
DESCRIPTION: REPLACE FRONT BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PA ~~-REPLACE FRONT BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PADS AND SHIMS. RESURFACE FRONT ROTORS. ~~-~46359 5.0 FT, BRAKE SERVICE WITH WHEEL BEARING PACK

SERVICE: REPLACED ANTENNA
DESCRIPTION: REPLACED ANTENNA ~~-REPLACED BROKEN ANTENNA ~~-~46363 1.5 REMOVE ANTENNA TO REPLACE BROKEN MAST

21420 MILES

DATE: 07/08/2005

REPAIR# 0262145

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: 30,000 MILE MAINTENANCE,2000-2003 LX470. RESET LIGHT IF APPLICABLE.
DESCRIPTION: 30,000 MILE MAINTENANCE,2000-2003 LX470. RESET LIGHT IF APPLICABLE. ~~-30,000 MILE MAINTENANCE,2000-2003 LX470. RESET LIGHT IF APPLICABLE. ~~-~21420 6.3 TIRES FRT. 9/9 REAR 9/9 FRT. BRAKE 8 1/2 & REAR 8 1/2 10396

SERVICE: FOUR WHEEL ALIGNMENT
DESCRIPTION: FOUR WHEEL ALIGNMENT ~~-FOUR WHEEL ALIGNMENT ~~-~21420 1.8 ALIGN. 10396

SERVICE: CHANGE OIL AND OIL FILTER
DESCRIPTION: CHANGE OIL AND OIL FILTER ~~-CHANGE OIL AND OIL FILTER ~~-~21420 0.4 O/F 10396

SERVICE: IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN
DESCRIPTION: IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN ~~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE. ~~-~21420

SERVICE: SUV BALANCE**DESCRIPTION:** SUV BALANCE ~|~SUV BALANCE ~|~ ~|~21420 0.8
TIRE BAL. 10396**SERVICE:** TRANSMISSION AND DIFFERENTIAL SERVICE.**DESCRIPTION:** TRANSMISSION AND DIFFERENTIAL SERVICE.
~|~TRANSMISSION AND DIFFERENTIAL SERVICE. ~|~ ~|~21420 1.0
TRANS. & DIFF. SVC. 10396**17590 MILES****DATE:** 01/06/2005**REPAIR#** 0246706**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** CHANGE OIL AND OIL FILTER**DESCRIPTION:** CHANGE OIL AND OIL FILTER ~|~CHANGE OIL
AND OIL FILTER ~|~ ~|~17590 LOF 0.4 HR 13204 DONE**SERVICE:** FOUR WHEEL ALIGNMENT**DESCRIPTION:** FOUR WHEEL ALIGNMENT ~|~WHEN DRIVING AT
HWY SPEEDS VEHICLE CONSTANTLY PULLING AND STEERING
WHEEL OFF CENTER ~|~ ~|~17590 ALIGNMENT 1.8 HR 13204 DONE**11884 MILES****DATE:** 06/30/2004**REPAIR#** 0231582**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** CHANGE OIL AND OIL FILTER**DESCRIPTION:** CHANGE OIL AND OIL FILTER ~|~CHANGE OIL
AND OIL FILTER ~|~ ~|~11881 .4 DONE-10691**SERVICE:** CHECK OUT CAR**DESCRIPTION:** CHECK OUT CAR ~|~CHECK OVER FOR TRIP ~|~
~|~11881 DONE-10691**SERVICE:** FOUR WHEEL ALIGNMENT**DESCRIPTION:** FOUR WHEEL ALIGNMENT ~|~FOUR WHEEL
ALIGNMENT ~|~ ~|~11884 1.8 DONE-10691**8352 MILES****DATE:** 01/31/2004**REPAIR#** 0221146**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** 5,000 MILE SERVICE**DESCRIPTION:** 5,000 MILE SERVICE ~|~5,000 MILE SERVICE ~|~5K
~|~8352 001050 ***0.6*** (10101) 5000 SVC.ROTATE TIRES.**SERVICE:** CHECK OUT CAR**DESCRIPTION:** CHECK OUT CAR ~|~MAINT REQ LIGHT ON ~|~
~|~8352 DONE**216 MILES****DATE:** 07/16/2003**REPAIR#** 0207181**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** BLEND LEFT REAR BUMPER**DESCRIPTION:** BLEND LEFT REAR BUMPER ~|~BLEND SPOT ON
LEFT REAR BUMPER ~|~ ~|~216 2.0 DONE 216 2.0 DONE**SERVICE:** NEW CAR DETAIL WASH EXTERIOR OF CAR, CLEAN
WHEELS WITH WHEEL CLEANER AND DRESS T**DESCRIPTION:** NEW CAR DETAIL WASH EXTERIOR OF CAR,
CLEAN WHEELS WITH WHEEL CLEANER AND DRESS T ~|~NEW CAR
DETAIL WASH EXTERIOR OF CAR, CLEAN WHEELS WITH WHEEL
CLEANER AND DRESS TIRES. VACUUM INTERIOR, CLEAN

WINDOWS-POLISH AND WAX EXTERIOR. ~-~ -216 2.5 DONE 216 2.5 DONE

SERVICE: NON-OEM PIN STRIPE

DESCRIPTION: NON-OEM PIN STRIPE ~-~NON-OEM PIN STRIPE ~-~
~-~216 1.5 DONE 216 1.5 DONE

SERVICE: NON-OEM WINDOW TINTING MATCH TINT

DESCRIPTION: NON-OEM WINDOW TINTING MATCH TINT
~-~NON-OEM WINDOW TINTING MATCH TINT ~-~ ~-~216 1.0 DONE
216 1.0 DONE

SERVICE: TEST DROVE VEHICLE, NO PROBLEM FOUND. STEERING
WHEEL STRAIGHT

DESCRIPTION: TEST DROVE VEHICLE, NO PROBLEM FOUND.
STEERING WHEEL STRAIGHT ~-~STEERING WHEEL OFF CENTER ~-~
~-~216 0.0 VEHICLES STEERING WHEEL STRAIGHT 216 0.0 VEHICLES
STEERING WHEEL STRAIGHT

9 MILES

DATE: 07/05/2003

REPAIR# 0206389

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: NEW CAR DETAIL WASH EXTERIOR OF CAR, CLEAN
WHEELS WITH WHEEL CLEANER AND DRESS T

DESCRIPTION: NEW CAR DETAIL WASH EXTERIOR OF CAR,
CLEAN WHEELS WITH WHEEL CLEANER AND DRESS T ~-~NEW CAR
DETAIL WASH EXTERIOR OF CAR, CLEAN WHEELS WITH WHEEL
CLEANER AND DRESS TIRES. VACUUM INTERIOR, CLEAN
WINDOWS-POLISH AND WAX EXTERIOR. ~-~ ~-~9 2.5 NCD DONE 9 2.5
NCD DONE

5 MILES

DATE: 04/29/2003

REPAIR# 0201831

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: 2 YEAR STATE INSPECTION ON NEW CARS ONLY

DESCRIPTION: 2 YEAR STATE INSPECTION ON NEW CARS ONLY
~-~2 YEAR STATE INSPECTION ON NEW CARS ONLY ~-~ ~-~5 STATE
INSP 0.3 HRS. STATE INSP# W04072919. 5 STATE INSP 0.3 HRS. STATE
INSP# W04072919.

SERVICE: DONE

DESCRIPTION: DONE ~-~REMOVE RAIL DUST ~-~RAIL DUST ~-~5 .5
DONE 5 .5 DONE

SERVICE: CAR WASH OTHREMOVE STICKERS AND DRESS TIRES
PUT ON READY LINE

DESCRIPTION: CAR WASH OTHREMOVE STICKERS AND DRESS
TIRES PUT ON READY LINE ~-~CAR WASH OTHREMOVE STICKERS
AND DRESS TIRES PUT ON READY LINE ~-~ ~-~5 .5 DONE 5 .5 DONE

SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES
~-~PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES ~-~PDI ~-~5
PERFORMED PDI 001013 2.0 HRS. LEXUS LINK# STID 0013305584. 5
PERFORMED PDI 001013 2.0 HRS. LEXUS LINK# STID 0013305584.

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contain in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) ([//www.lexus.com/privacy/online-statement](http://www.lexus.com/privacy/online-statement)).