

SERVICE (/LEXUSDRIERS/SERVICE) | SERVICE HISTORY

02 SOROLA 160 KMILES

SERVICE HISTORY FOR YOUR 02 SOROLA 160KMILES

Get the most out of your Lexus Drivers account by keeping track of your vehicle service history. Work performed at an authorized Lexus Dealer will be added automatically. Any work done outside of a Lexus Dealer, can be updated or added yourself.

PRINT

ADD SERVICE

SERVICE HISTORY

SERVICE HISTORY FOR: 02 SOROLA 160KMILES

VIN: JTJGF10U420129431

Filter History By Year

ALL

155251 MILES

DATE: 09/14/2015

REPAIR# 2103177

REPORTED BY: Sewell Lexus

SERVICE: 30,000 MILE SERVICE RX300

DESCRIPTION: 30,000 MILE SERVICE RX300 ~30,000 MILE SERVICE RX300*PLEASE CHECK PLACEMENT OF TIRES AND PUT BEST TIRES WHERE THEY ARE RECOMMENDED. ~155249 450 30K SVC COMPLETED.

SERVICE: NO REPAIRS COMPLETED

DESCRIPTION: NO REPAIRS COMPLETED ~CAM SEALS AND VALVE COVER GASKETS ~155251 00 DID NOT PERFORM.

SERVICE: REPLACED DRIVERS DOOR LOCK ACTUATOR

DESCRIPTION: REPLACED DRIVERS DOOR LOCK ACTUATOR ~PLEASE CHECK DRIVERS SIDE DOOR. C/S THAT IT WILL NOT AUTOMATICALLY LOCK WITH KEY FOB ~155251 150 REPLACED DRIVER'S DOOR LOCK ACTUATOR.

SERVICE: LOAN CAR PROVIDED.

DESCRIPTION: LOAN CAR PROVIDED. ~IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE. ~

SERVICE: REPLACE KEY SHELL

DESCRIPTION: REPLACE KEY SHELL ~REPLACE KEY SHELL ~155251 00 REPLACED KEY WITH AFTERMARKET KEY SHELL.

SERVICE: REPLACEMENT OF BULB

DESCRIPTION: REPLACEMENT OF BULB ~REPLACEMENT OF BULB ~155249 50 REPLACED RIGHT FRONT SIDEMARKER BULB.

138462 MILES

DATE: 10/05/2013

REPAIR# 1908859**REPORTED BY:** Sewell Lexus**SERVICE:** 15,000 MILE SERVICE RX300

DESCRIPTION: 15,000 MILE SERVICE RX300 ~-135,000 MILE SCHEDULED SERVICE ~- ~-138462 DONE 140 RF TIRE 6/32, LF TIRE 9/32, REAR TIRES 4/32, FRONT AND REAR BRAKE PADS 9MM. ONLY ROTATED PASSENGER SIDE TIRES TO KEEP BEST TIRES ON FRONT. CLIENT DECLINED REPLACING TIRES THAT ARE NOW ON THE REAR. *REPLACE ENGINE OIL AND FILTER* REPLACE CA

SERVICE: LOAN CAR PROVIDED.

DESCRIPTION: LOAN CAR PROVIDED. ~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.

SERVICE: REPLACE KEY SHELL

DESCRIPTION: REPLACE KEY SHELL ~-CUSTOMER WOULD LIKE TO REPLACE BROKEN KEY SHELL WITH NON LEXUS KEY SHELL. OLD KEY IS IN THE CENTER CUP HOLDER ~- ~-138461 REPLACED KEY SHELL

SERVICE: REPLACED ANTENNA MAST

DESCRIPTION: REPLACED ANTENNA MAST ~-CUSTOMER STATES THE ANTENNA IS BROKEN, PLEASE CHECK AND ADVISE ~- ~-138462 DONE 150 REPLACED BROKEN ANTENNA MAST

SERVICE: REPLACED REAR WIPER BLADE

DESCRIPTION: REPLACED REAR WIPER BLADE ~-UPON INSPECTION TECHNICIAN FOUND THE REAR WIPER BLADE IS IN NEED OF REPLACING ~- ~-138462 DONE 10 REPLACED REAR WIPER BLADE

SERVICE: DECLINED DIAGNOSIS

DESCRIPTION: DECLINED DIAGNOSIS ~-CUSTOMER STATES SHE RAN OUT OF GAS, BUT THE GAS GAUGE STILL READ THAT SHE HAD A HALF TANK OF GAS. NO DIAGNOSIS QUOTED YET ~- ~-138461 CLIENT DECLINED DIAGNOSIS TIME FOR THIS CONCERN. ALSO NEED MORE DETAILS. HOW MUCH GAS IS ADDED WHEN CONCERN HAPPENS? HOW LONG DOES THE CAR SIT BEFORE IT STARTS RUNNING AGAIN?

SERVICE: REINSTALLED CUPHOLDER

DESCRIPTION: REINSTALLED CUPHOLDER ~-CUSTOMER STATES SHE TOOK OUT A PIECE THAT IS PART OF THE CUP HOLDER AND CAN NOT RESECURE IT, CAN THIS BE RESECURED OR DOES THIS HAVE TO BE REPLACE? ~- ~-138461 REINSTALLED CUPHOLDER CENTER SECTION

SERVICE: REPLACED AIR MIX SERVO MOTOR

DESCRIPTION: REPLACED AIR MIX SERVO MOTOR ~-CUSTOMER STATES WHEN SHE TURNS THE AIR TO BLOW ON JUST THE FACE THE VEHICLE IS MAKING A CLICKING NOISE, THE NOISE GOES AWAY WHEN THE AIR IS BLOWING ON BOTH THE FACE AND THE FEET ~- ~-138462 200 REPLACED NOISY INOPERTIVE AIR MIX SERVO

SERVICE: REPLACED FUEL TANK PROTECTOR

DESCRIPTION: REPLACED FUEL TANK PROTECTOR ~-UPON INSPECTION TECHNICIAN FOUND GAS TANK PROTECTOR DAMAGED ~- ~-138462 DONE 100 REPLACED GAS TANK PROTECTOR

How is your visit? **SERVICE:** REPLACED THIRD BRAKE LIGHT BULB AND RIGHT FRONT DAYTIME RUNNING LIGHT BULB

DESCRIPTION: REPLACED THIRD BRAKE LIGHT BULB AND RIGHT FRONT DAYTIME RUNNING LIGHT BULB ~-CUSTOMER STATES THE TAIL LIGHT INDICATOR CAME ON, PLEASE CHECK AND ADVISE ~- ~-138462 DONE 80 REPLACED THIRD BRAKE LIGHT BULB AND RIGHT FRONT DAYTIME RUNNING LIGHT BULB

123955 MILES

DATE: 03/13/2012

REPAIR# 1759684**REPORTED BY:** Sewell Lexus**SERVICE:** 120,000 MILE SERVICE WITH SPARK PLUGS

DESCRIPTION: 120,000 MILE SERVICE WITH SPARK PLUGS ~-120,000 MILE SERVICE WITH SPARK PLUGS ~- ~-123955 600 120K SERVICE WITH SPARK PLUGS BRAKES ALL NEW TIRES 6/32, 1 NEW ONE REPLACE ENGINE OIL & OIL FILTER REPLACE A/C FILTER REPLACE ENGINE AIR FILTER INSPECT NUTS & BOLTS ON CHASSIS REPLACE BRAKE FLUID REPLACE ENGINE COOLANT ROTATE TIRES RE-TORQUE DR

SERVICE: LOAN CAR PROVIDED.**SERVICE:** COURTESY VISUAL INSPECTION

DESCRIPTION: COURTESY VISUAL INSPECTION ~-COURTESY VISUAL INSPECTION

SERVICE: REPLACE FRONT BRAKE PADS. RESURFACE FRONT BRAKE ROTORS AND INSTALLED ANTI-SQUEAL

DESCRIPTION: LOAN CAR PROVIDED. ~~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.

SERVICE: REPLACE REAR BRAKE PADS, SHIM KIT AND HARDWARE KIT. RESURFACEREAR BRAKE ROTORS A
DESCRIPTION: REPLACE REAR BRAKE PADS, SHIM KIT AND HARDWARE KIT. RESURFACEREAR BRAKE ROTORS A ~~-REPLACE REAR BRAKE PADS, SHIM KIT AND HARDWARE KIT. RESURFACEREAR BRAKE ROTORS AND INSTALL ANTI-SQUEAL COMPOUND ~~-123955 200 REPLACE REAR BRAKE PADS AND RESURFACE ROTORS

SERVICE: TIRES HAVE 6/32NDS OR MORE OF TREAD AND LOOK GOOD AT THIS TIME
DESCRIPTION: TIRES HAVE 6/32NDS OR MORE OF TREAD AND LOOK GOOD AT THIS TIME ~~-INSPECT AND REPORT TIRE CONDITION INCLUDING TREAD DEPTH MEASUREMENTS

DESCRIPTION: REPLACE FRONT BRAKE PADS. RESURFACE FRONT BRAKE ROTORS AND INSTALLED ANTI-SQUEAL ~~-REPLACE FRONT BRAKE PADS. RESURFACE FRONT BRAKE ROTORS AND INSTALLED ANTI-SQUEAL COMPOUND. ~~- ~~-123955 200 REPLACE FRONT BRAKE PADS AND RESURFACE ROTORS

SERVICE: REPLACED R/F TIRE
DESCRIPTION: REPLACED R/F TIRE ~~-VINTECH SHOWS THE R/F TIRE IS LOW- REPORT ~~-123955 050 NAIL IN EDGE OF TIRE, REPLACE TIRE BF GOODRICH LONG TRAIL DOT BF5L L211 2611

SERVICE: VEHICLE IS OPERATING AS DESIGNED
DESCRIPTION: VEHICLE IS OPERATING AS DESIGNED ~~-YOU CAN FEEL THE ENGINE WHEN IN GEAR, CAN FEEL IN THE CAR MORE SO THAN BEFORE, LESSENS WHEN IN PARK ~~-123955 ENGINE AND MOUNTS ALL OK AT THIS TIME

113992 MILES**DATE:** 06/22/2011

REPAIR# 1692123
REPORTED BY: Sewell Lexus

SERVICE: 105.000 MILE SERVICE
DESCRIPTION: 105.000 MILE SERVICE ~~-105.000 MILE SERVICE ~~-113992 140 105K SERVICE, BRAKES AT 6MM FRONT 5MM REAR, TIRES AT 7-8/32 IN GOOD CONDITION. REPLACE ENGINE OIL AND FILTER* TEST BATTERY AND CLEAN TERMINALS* REPLACE AIR FILTER* INSPECT A/C FILTER (WHERE APPLIES)* INSPECT BRAKE PADS, ROTORS, LINES AND HOSES*

SERVICE: LOAN CAR PROVIDED.
DESCRIPTION: LOAN CAR PROVIDED. ~~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 DAY FEE WILL BE ADDED TO YOUR INVOICE.

How is your visit? **102705 MILES****DATE:** 06/12/2010

REPAIR# 1596191
REPORTED BY: Sewell Lexus

SERVICE: 4 WHEEL ALIGNMENT
DESCRIPTION: 4 WHEEL ALIGNMENT ~~-4 WHEEL ALIGNMENT ~~-102705 WITH SUSPENSION REPAIRS 180 CHECKED AND CORRECTED FRONT TOE - MACHINE C.

SERVICE: FLAT REPAIR
DESCRIPTION: FLAT REPAIR ~~-FLAT REPAIR ~~-102705 LEFT REAR TIRE HAD PUNCTURE 50 PATCHED AND BALANCED LEFT REAR TIRE. MOVED TO LEFT FRONT WITH SERVICE.

SERVICE: LOAN CAR PROVIDED.
DESCRIPTION: LOAN CAR PROVIDED. ~~-IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE.

SERVICE: ONE YEAR STATE INSPECTION. INS EXP DATE_____. **ATTENTION** YOU ARE REQUIRE
DESCRIPTION: ONE YEAR STATE INSPECTION. INS EXP DATE_____. **ATTENTION** YOU ARE REQUIRE ~~-ONE YEAR STATE INSPECTION. INS EXP DATE_____. **ATTENTION** YOU ARE REQUIRED BY LAW TO PAY THE STATUTORY FEE FOR THE INSPECTION WHETHER YOUR VEHICLE PASSES OR FAILS ~~-102705 DUE 50 INSPECTION COMPLETED.

SERVICE: PERFORMED BASIC 100,000 MILE SCHEDULED SERVICE

SERVICE: REPLACED CV BOOT
DESCRIPTION: REPLACED CV BOOT ~~-CV AXLE BOOT LEAKING ~~-102705 INNER CV BOOT LEAKING 250 REMOVED

DESCRIPTION: PERFORMED BASIC 100,000 MILE SCHEDULED SERVICE ~1~90,000 MILE SERVICE WITH TIMING BELT ~1~ ~1~102705 MAINT 100 PERFORMED BASIC 10K SVC - TIMING BELT AND WATER PUMP RECENTLY DONE AT PARK PLACE. FT BRAKES AT 6MM, RR BRAKES AT 5MM. TIRES ALL BETWEEN 6-8/32.

SERVICE: RESEALED UPPER OIL PAN

DESCRIPTION: RESEALED UPPER OIL PAN ~1~UPPER OIL PAN GASKET LEAKING ~1~ ~1~102705 OIL PAN GASKET LEAKING 460 REMOVED AND RESEALED UPPER OIL PAN.

AXLE SHAFT FROM VEHICLE, REPLACED BOOTS, AND INSTALLED IN VEHICLE.

91591 MILES

DATE: 09/03/2009

REPAIR# 0779685

REPORTED BY: Park Place Lexus Plano

SERVICE: BATTERY

DESCRIPTION: BATTERY ~1~FREE REPLACEMENT 9-05-2007, RO #0339830, MILES 63456 ~1~FAILED LOAD TEST ~1~91591 190011 T1/72 T2/71 FP#00544-MF24F-575 INTERST. GR24F BATT. 60 BATTERY DROPPED TO 6.97 VOLTS ,REPLACED BATTERY

SERVICE: CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA

DESCRIPTION: CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA ~1~CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.

SERVICE: COMB: BATTERY

DESCRIPTION:

SERVICE: NO PRIOR BLEMISHES NOTED

DESCRIPTION: NO PRIOR BLEMISHES NOTED ~1~NO PRIOR BLEMISHES NOTED

SERVICE: REPLACE TIMING BELT-V-6 ENGINE

DESCRIPTION: REPLACE TIMING BELT-V-6 ENGINE ~1~REPLACE TIMING BELT-V-6 ENGINE ~1~ ~1~91591 600 REPLACED TIMING BELT AND WATER PUMP

SERVICE: CLIENT STATES: C/S THAT THE CAR HAS TO BE JUMPED STARTED

DESCRIPTION: CLIENT STATES: C/S THAT THE CAR HAS TO BE JUMPED STARTED ~1~CLIENT STATES: C/S THAT THE CAR HAS TO BE JUMPED STARTED ~1~.. ~1~91591 SEE LINE D FOR REPAIRS

SERVICE: CLIENT STATES: CUSTOMER STATED AT TIME OF APPT THEY WILL BE WAITING IN THE LOUNG

DESCRIPTION: CLIENT STATES: CUSTOMER STATED AT TIME OF APPT THEY WILL BE WAITING IN THE LOUNG ~1~CLIENT STATES: CUSTOMER STATED AT TIME OF APPT THEY WILL BE WAITING IN THE LOUNGE EACH DAY AFTER.

SERVICE: CRNKSHFT REAR OIL SEAL (ATM)

DESCRIPTION: CRNKSHFT REAR OIL SEAL (ATM) ~1~CLIENT STATES: THE CAR IS LEAKING OIL ~1~ ~1~91591 111161 730 REPLACED REAR MAIN SEAL

SERVICE: RENTAL

DESCRIPTION:

SERVICE: REPLACE WATER PUMP WITH TIMING BELT.

DESCRIPTION:

How is your visit?

86303 MILES

DATE: 04/07/2009

REPAIR# 1487163

REPORTED BY: Sewell Lexus

SERVICE: 85,000 MILE SERVICE

DESCRIPTION: 85,000 MILE SERVICE ~1~85,000 MILE SCHEDULED SERVICE ~1~ ~1~86303 85K SERVICE 100 REPLACED OIL, ADDED CF5, ROTATED TIRES, CHECKED OVER COMPONENTS AND TEST DROVE. TIRES HAVE 9/32NDS OF TREAD LEFT. BRAKES HAVE 8MM OF PAD LEFT. PLEASE NOTE TIMING BELT IS DUE FOR REPLACEMENT ON NEXT OIL CHANGE.REPLACE ENGINE OIL AND F

SERVICE: LOAN CAR PROVIDED.

DESCRIPTION: LOAN CAR PROVIDED. ~1~IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE. ~1~ ~1~86303 DONE

SERVICE: REPLACED TORN VACUUM HOSE

DESCRIPTION: REPLACED TORN VACUUM HOSE ~|~CHECK ENGINE LIGHT ~|~ ~|~86303 VACUUM HOSE FOUND TORN FROM AIR BOX TO EVAP CONNECTION. 100 REMOVED LINE AND CUT A NEW PIECE OF LINE. REATTACHED AND CLEARED SYSTEM. P0440,P0441,P0446 FOUND IN SYSTEM.

79384 MILES

DATE: 12/16/2008

REPAIR# 0858306

REPORTED BY: Park Place Lexus Grapevine

SERVICE: 80,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE
DESCRIPTION: 80,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE ~|~80,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSPECT STEERING LINKAGES; INSPECT BALL JOINTS AND DUST ~|~ ~|~79384 100 PERF 80K SVC - STATE INSP 5/09 BRAKES F-8MM R-7MM TIRES 10/32

SERVICE: NO PRIOR BLEMISHES NOTED
DESCRIPTION: NO PRIOR BLEMISHES NOTED ~|~NO PRIOR BLEMISHES NOTED ~|~ ~|~79384

SERVICE: REPLACE BULB
DESCRIPTION: REPLACE BULB ~|~REPLACE TAIL LIGHT BULB / LIGHT INDICATOR ON / DONT KNOW WHICH IS OUT ~|~ ~|~79384 30 REPLACED THIRD BRAKE LIGHT BULB

72405 MILES

DATE: 09/03/2008
How is your visit?

REPAIR# 0844162

REPORTED BY: Park Place Lexus Grapevine

SERVICE: AUTH NUMBER IS VSA 1PP9836
DESCRIPTION:

SERVICE: CERTIFIED PREOWNED 1ST OIL CHANGE
DESCRIPTION: CERTIFIED PREOWNED 1ST OIL CHANGE ~|~CERTIFIED PREOWNED 1ST OIL CHANGE ~|~ ~|~72405 50 CHANGE OI LAND FILTER

SERVICE: RENTCAR
DESCRIPTION:

SERVICE: REPLACED THE AIR MIX SERVO
DESCRIPTION: REPLACED THE AIR MIX SERVO ~|~PLEASE CEHCK THERE IS A CLICKING NOISE BEHIND DASH ~|~ ~|~72405 410 REPLACE AIR MIX SERVO MOTOR

SERVICE: ROTATE TIRES
DESCRIPTION: ROTATE TIRES ~|~ROTATE TIRES ~|~ ~|~72405 50 ROTATE TIRES

67937 MILES

DATE: 05/09/2008

REPAIR# 0827517

REPORTED BY: Park Place Lexus Grapevine

SERVICE: INTERNAL COMPLETE TOUCH UP
DESCRIPTION: INTERNAL COMPLETE TOUCH UP ~|~INTERNAL COMPLETE TOUCH UP ~|~ ~|~67937 CHIPS TO

VEHICLE. IPAINTTU. 50 COMPLETED TO TOUCH UP.

67937 MILES

DATE: 05/07/2008

REPAIR# 0827213

REPORTED BY: Park Place Lexus Grapevine

SERVICE: METRO INV.# 19086 P.O.#70395

DESCRIPTION: METRO INV.# 19086 P.O.#70395 ~-METRO INTERIOR SYSTEMS INV.# 19086

67937 MILES

DATE: 05/06/2008

REPAIR# 0826536

REPORTED BY: Park Place Lexus Grapevine

SERVICE: 60,000 MILE SERVICE

DESCRIPTION: 60,000 MILE SERVICE ~-60,000 MILE SERVICE ~- ~-67937 400 TIRES ALL 11/32 BKS FT. 10MM RR 6MM STATE 05/09

SERVICE: CERTIFIED PRE-OWNED PDI

DESCRIPTION: CERTIFIED PRE-OWNED PDI ~-CERTIFIED PRE-OWNED PDI ~- ~-67937 200

SERVICE: OBD II (1996-2002) STATE INSPECT

DESCRIPTION: OBD II (1996-2002) STATE INSPECT ~-OBD II (1996-2002) STATE INSPECT ~- ~-67937 050

SERVICE: REPLACE FRONT BRAKE PADS AND TURN ROTORS

DESCRIPTION: REPLACE FRONT BRAKE PADS AND TURN ROTORS ~-REPLACE FRONT BRAKE PADS AND TURN ROTORS ~- ~-67937 200

SERVICE: CERTIFICATION ALIGNMENT AND TIRE BALANCE

DESCRIPTION: CERTIFICATION ALIGNMENT AND TIRE BALANCE ~-CERTIFICATION ALIGNMENT AND TIRE BALANCE ~- ~-67937 200

SERVICE: DETAIL PREOWNED SUV


DESCRIPTION: DETAIL PREOWNED SUV ~-DETAIL PREOWNED SUV ~- ~-67937 DETAIL PREOWNED 400

SERVICE: PREOWNED DENT REMOVAL

DESCRIPTION: PREOWNED DENT REMOVAL ~-PREOWNED DENT REMOVAL ~- ~-67937 200

SERVICE: REPLACE WINDSHIELD WIPER INSERTS

DESCRIPTION: REPLACE WINDSHIELD WIPER INSERTS ~-REPLACE WINDSHIELD WIPER INSERTS ~- ~-67937 030



63456 MILES

DATE: 09/05/2007

REPAIR# 0339830

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: BATTERY

DESCRIPTION: BATTERY ~-C/S ALL LIGHTS WILL FLASH AT TIMES/ THEN VEHICLE WILL DIE/**** 49982 MILES/ 11.28.05/ RO 274603/ ILEX# 7840429 ~-BATTERY FAIL LOAD TEST ~-63456 BATTERY FAIL LOAD TEST 190011A 60 REPLACED BATTERY AND CHECK ELECTRICAL 10691

SERVICE: COMB: BATTERY

DESCRIPTION:

SERVICE: EXHAUST MANIFLD ASSY (RT SD) AUTH# VSA1LL8384

DESCRIPTION: EXHAUST MANIFLD ASSY (RT SD) AUTH# VSA1LL8384 ~-UPON INSPECTION FOUND CHECK ENGINE LIGHT ON ~-P1135 A/F SENSOR MALFUNCTION B1 S1 ~-63456

SERVICE: CHECK OUT CAR

DESCRIPTION: CHECK OUT CAR ~-VEHICLE TOWED IN ~- ~-63456

SERVICE: COURTESY VEHICLE INSPECTION.

DESCRIPTION: COURTESY VEHICLE INSPECTION. ~-COURTESY VEHICLE INSPECTION. ~- ~-63456

SERVICE: HANDLING FEE FOR EXCHANGE PART

DESCRIPTION:

P1135 A/F SENSOR MALFUNCTION B1 S1 170021Z 630 WHEN REMOVING A/F SENSOR THREADS ON EHXAUST MANIFOLD GOT DAMAGED REMOVED MANIFOLD TO RETAP THREADS AND REPLACED A/F SENSOR 10691

SERVICE: LOAN CAR

DESCRIPTION: LOAN CAR ~|~IN ORDER TO PROVIDE EXCELLENT SERVICE TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12 BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO YOUR INVOICE. ~|~ ~|~63456

SERVICE: RE-TAP MANIFOLD

DESCRIPTION:

SERVICE: Z TIME

DESCRIPTION:

61083 MILES

DATE: 06/08/2007

REPAIR# 0330440

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: STATE INSPECTION-1 YEAR

DESCRIPTION: STATE INSPECTION-1 YEAR ~|~STATE INSPECTION-1 YEAR ~|~ ~|~61083 50 1 YR STATE INSPECTION

54983 MILES

DATE: 07/07/2006

REPAIR# 0295979


REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CHANGE OIL AND OIL FILTER

DESCRIPTION: CHANGE OIL AND OIL FILTER ~|~CHANGE OIL AND OIL FILTER ~|~ ~|~54983 0.4 LOF""

SERVICE: COURTESY VEHICLE INSPECTION.

DESCRIPTION: COURTESY VEHICLE INSPECTION. ~|~ ~|~54983 ~|~COURTESY VEHICLE INSPECTION. ~|~ ~|~54983



50516 MILES

DATE: 01/13/2006

REPAIR# 0279153

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: REPLACED LEFT OUTER MIRROR VSA1FW8269

DESCRIPTION: REPLACED LEFT OUTER MIRROR VSA1FW8269 ~|~CUSTOMER STATES THAT THE LEFT EXTERNAL MIRROR IS LOOSE WHILE DRIVING == SOP HERE >>>> TECH 12741 ~|~ ~|~50516 752051 0.4 REPLACED OUTER LEFT MIRROR

50400 MILES

DATE: 01/11/2006

REPAIR# 0278525

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CHECK OUT CAR

DESCRIPTION: CHECK OUT CAR ~|~DRIVER MIRROR ASSY. IS LOOSE & BLOWS AROUND WHILE DRIVING ~|~ ~|~50400 SOP LEFT OUTSIDE MIRROR.

SERVICE: TRUNK SHOCKS /AUTH#VSA-1FW5392

DESCRIPTION: TRUNK SHOCKS /AUTH#VSA-1FW5392 ~|~REAR HATCH LID SLOW TO RISE WHEN OPENING / ~|~ ~|~50400 T1-

97.T2-14 642241 A 0.3 REPLACED BOTH REAR HATCH STRUT
STAY

50157 MILES**DATE: 12/26/2005****REPAIR#** 0277376**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** COURTESY VEHICLE INSPECTION.**DESCRIPTION:** COURTESY VEHICLE INSPECTION.

~|~COURTESY VEHICLE INSPECTION. ~|~ ~|~50157 .

SERVICE: IN ORDER TO PROVIDE EXCELLENT SERVICE TO
OUR CUSTOMERS, PLEASE RETURN YOUR LOAN**DESCRIPTION:** IN ORDER TO PROVIDE EXCELLENT SERVICE
TO OUR CUSTOMERS, PLEASE RETURN YOUR LOAN ~|~IN
ORDER TO PROVIDE EXCELLENT SERVICE TO OUR
CUSTOMERS, PLEASE RETURN YOUR LOAN CAR WITHIN 12
BUSINESS HOURS UPON NOTIFICATION OF YOUR VEHICLE
BEING READY OR A \$95 PER DAY FEE WILL BE ADDED TO
YOUR INVOICE. ~|~ ~|~50157**SERVICE:** PWR WNDW MASTER SWITCH ASSY**DESCRIPTION:** PWR WNDW MASTER SWITCH ASSY ~|~RIGHT
REAR WINDOW ROLLS UP AND DOWN ON ITS OWN ~|~MASTER
SWITCH ~|~50157 675161 0.2 REPLACED MASTER SWITCH**50038 MILES****DATE: 12/26/2005****REPAIR#** 0277242**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** CHECK OUT CAR**DESCRIPTION:** CHECK OUT CAR ~|~CUT AND PROGRAM 2
REMOTE MASTER KEYS ~|~ ~|~50038 KEYS REG 1.0 REG CHECK
OUT CAR ~|~REPLACE REAR BUMPER PROTECTOR ~|~ ~|~50038
REAR BUMPER TRIM REPLACED 1.0 REPLACED CHECK OUT
CAR ~|~BUFF CAR ~|~ ~|~50038 2.0 TECH 12988 DONE**SERVICE:** PINSTRIPE W/ LOGO**DESCRIPTION:** PINSTRIPE W/ LOGO ~|~PINSTRIPE W/ LOG
~|~50038 1.5 13316How is your visit? **SERVICE:** USED CAR CLEAN**DESCRIPTION:** USED CAR CLEAN ~|~USED CAR CLEAN ~|~
~|~50038 0.5 TECH 12988 DONE**49982 MILES****DATE: 11/28/2005****REPAIR#** 0274603**REPORTED BY:** Sewell Lexus of Ft. Worth**SERVICE:** LOAD TESTED BATTERY AND ALTER- NATOR.

CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRC

DESCRIPTION: LOAD TESTED BATTERY AND ALTER- NATOR.CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRC ~|~LOAD
TESTED BATTERY AND ALTER- NATOR. CHECKED ELECTRICAL
SYSTEM FOR OPEN IN CIRCUIT. BATTERY FAILED LOAD TEST
AND SYSTEM CHECKS OUT FINE AT THIS TIME.*****REPLACED BATTERY ~|~ ~|~49982 BATT 0.5 TEST
CHARGING AND STARTING, CHECK FOR SYSTEM DRAW,
REPLACE BATTERY

REPAIR# 0273494

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CHARGED BATTERY

DESCRIPTION: CHARGED BATTERY ~~-LOAD TESTED BATTERY AND ALTER- NATOR. CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRCUIT. BATTERY FAILED LOAD TEST AND SYSTEM CHECKS OUT FINE AT THIS TIME. *****REPLACED BATTERY ~~-49981 CHKED BATT DOWN ALT OUTPUT 1.0 CHGED BATT CKED FOR LOADS NO PROBLEMS FOUND MUST HAD LOAD FROM DOORS OR LIGHTS

49980 MILES

DATE: 10/11/2005

REPAIR# 0270211

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CERTIFIED PRE-OWNED PDI

DESCRIPTION: CERTIFIED PRE-OWNED PDI ~~-CERTIFIED PRE-OWNED PDI ~~-49980 CERTIFIED PDI 2.0 HR 13204 DONE

SERVICE: CHECK OUT CAR

DESCRIPTION: CHECK OUT CAR ~~-REPLACE REAR WIPER BLADE ~~-49980 N-C REPLACED THE REAR WIPER INSERT. CHECK OUT CAR ~~-REPLACE DRIVE BELT ~~-49980 1.0 REPLACED BOTH DRIVE BELT.

SERVICE: LOAD TESTED BATTERY AND ALTER- NATOR.

CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRC

DESCRIPTION: LOAD TESTED BATTERY AND ALTER- NATOR.

CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRC ~~-LOAD TESTED BATTERY AND ALTER- NATOR. CHECKED ELECTRICAL SYSTEM FOR OPEN IN CIRCUIT. BATTERY FAILED LOAD TEST AND SYSTEM CHECKS OUT FINE AT THIS TIME.

*****REPLACED BATTERY ~~-49980 0.5 REPLACED THE BATTERY.

SERVICE: REPLACE REAR BRAKE PADS, SHIM KITS, AND FIT

KITS. APPLY ANTI-SQUEAL AGENT TO PAD

DESCRIPTION: REPLACE REAR BRAKE PADS, SHIM KITS, AND

FIT KITS. APPLY ANTI-SQUEAL AGENT TO PAD ~~-REPLACE REAR BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PADS AND SHIMS. RESURFACE REAR ROTORS. ~~-49980 2.2 PERFORMED REAR BRAKE JOB

How is your visit? X

SERVICE: USED CAR DETAIL

DESCRIPTION: USED CAR DETAIL ~~-USED CAR DETAIL ~~-49980 4.0 TECH 12988 DONE

38695 MILES

DATE: 12/15/2004

REPAIR# 0244249

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CHANGE OIL AND OIL FILTER

DESCRIPTION: CHANGE OIL AND OIL FILTER ~~-CHANGE OIL AND OIL FILTER ~~-38695 MAINT 0.4 LOF .

SERVICE: RECONNECTED #2 INJECTOR

DESCRIPTION: RECONNECTED #2 INJECTOR ~~-CHECK ENGINE LIGHT ON ~~-CHECK ENGINE LIGHT ~~-38695 PO302 820991 1.1 CONNECTOR FOR #2 INJ NOT FULLY CONNECTED CKED PINS AND RECONNECTED

SERVICE: REPAIR REAR BUMPER, REPLACE LT LIFTGATE LIGHT

DESCRIPTION: REPAIR REAR BUMPER, REPLACE LT LIFTGATE LIGHT ~~-LT REAR BUMPER REPAIR,,REPLACE LT INNER LIFTGATE LIGHT.SPOKE TO GREG,,REPAIR COST OF \$465.00 ~~-38695 3.0 TECH 13477

SERVICE: REPLACE FRONT BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PA

DESCRIPTION: REPLACE FRONT BRAKE PADS, SHIM KITS, AND FIT KITS. APPLY ANTI-SQUEAL AGENT TO PA ~~-BRAKES ARE GRINDING ~~-38695 FRT BRKS WORN 2.2 REPLACE FRT PADS TURN ROTORS

SERVICE: RESET LIGHT

DESCRIPTION: RESET LIGHT ~TRAC LIGHT AND VSC LIGHT
ON ~ ~38695 ENGINE CODE SETTING THESE

24218 MILES

DATE: 12/05/2003

REPAIR# 0216995

REPORTED BY: Sewell Lexus of Ft. Worth

SERVICE: CHANGE OIL AND OIL FILTER

DESCRIPTION: CHANGE OIL AND OIL FILTER ~CHANGE OIL
AND OIL FILTER ~ ~24213 LOF CL 0.4 LOF COMPLETED.

SERVICE: CHECK BRAKES

DESCRIPTION: CHECK BRAKES ~BRAKES SEEM TO BE
GRABBING ~ ~24213 WAS UNABLE TO DUPLICATE ANY
BRAKE GRABBING AT THIS TIME. FRONT BRAKES AT 7 MM,
REAR AT 8MM

SERVICE: COMPLETE DETAIL EXCLUDING GX AND LX
MODELS

DESCRIPTION: COMPLETE DETAIL EXCLUDING GX AND LX
MODELS ~COMPLETE DETAIL EXCLUDING GX AND LX
MODELS ~ ~24218 COMPLETE DETAIL 5.0 DONE

SERVICE: LUBE LOWER BOOT

DESCRIPTION: LUBE LOWER BOOT ~STEERING WHEEL
SQUEEKS ~LUBRICATE STEERING BOOT ~24218 LUBRICATED
STEERING WHEEL BOOT.

SERVICE: REPLACE ANTENNAE MAST

DESCRIPTION: REPLACE ANTENNAE MAST ~ANTENNAE
MAST BROKEN -MAST IN HATCH AREA ~ ~24213 MAST
BROKEN CL 1.0 INTALLED NEW ANTENNA MAST.

SERVICE: REPLACE HATCH CLIPS

DESCRIPTION: REPLACE HATCH CLIPS ~INSIDE REAR
HATCH LOOSE ~REPLACE HATCH CLIPS ~24213 REAR HATCH
LOOSE 642991 0.5 REMOVED REAR HATCH TRIM AND
INSTALLED NEW CLIPS AND REATTACHED.

9 MILES

DATE: 04/17/2002

REPAIR# 0485503

REPORTED BY: Sewell Lexus

How is your visit?

SERVICE: REMOVED RAIL DUST

DESCRIPTION: RAIL DUST

SERVICE: TWO YEAR STATE INSPECTION .3

DESCRIPTION: TWO YEAR STATE INSPECTION

5 MILES

DATE: 02/12/2002

REPAIR# 0473097

REPORTED BY: Sewell Lexus

SERVICE: PRE-DELIVERY SERVICE FOR USA INS

DESCRIPTION: PDI

TERMS AND CONDITIONS

ABOUT LEXUS

FINANCE & LEASING

BRAND & LIFESTYLE